



Cisco MDS 9000 Software Upgrade and Downgrade Guide, Release 6.2(x)

Last Published: April 15, 2019

This document describes how to upgrade to Cisco NX-OS Release 6.2(x) from Release 5.2(x), and how to downgrade from Cisco NX-OS Release 6.2(x) to Release 5.2(x).

This guide includes the following sections:

- [About Software Images, page 2](#)
- [Components Supported, page 2](#)
- [Installing Cisco NX-OS Release 6.2\(x\) Software on a New Cisco MDS Switch, page 15](#)
- [Upgrading to Cisco NX-OS Release 6.2\(x\) on an Existing Cisco MDS Switch, page 23](#)
- [Moving From an NPE Image to a non-NPE Image and Vice Versa, page 55](#)
- [Downgrading from Cisco NX-OS Release 6.2\(x\), page 59](#)
- [Nondisruptive Upgrades on Fabric and Modular Switches, page 93](#)
- [Related Documentation, page 98](#)
- [Obtaining Documentation and Submitting a Service Request, page 101](#)



Note

All command-line interface (CLI) session examples provided in this document are only intended for reference. The actual switch output differs based on your switch model.

About Software Images

Each switch is shipped with the Cisco MDS NX-OS operating system for Cisco MDS 9000 Family switches. The Cisco MDS NX-OS software consists of two images: the kickstart image and the system image.

- To select the kickstart image, use the KICKSTART variable.
- To select the system image, use the SYSTEM variable.

The images and variables are important factors in any install procedure. You must specify the variable and the respective image to upgrade or downgrade your switch. Both images are not always required for each install.


Note

To download new Cisco MDS 9000 Family software including Cisco NX-OS and Cisco DCNM management software, refer to the Storage Networking Software download site at: <http://www.cisco.com/cisco/software/navigator.html>

For Storage Services Interface image compatibility information, refer to the [Cisco MDS NX-OS Release Compatibility Matrix for Storage Service Interface Images](#).

Dependent Factors for Software Installation

The software image install procedure is dependent on the following factors:

- Software images—The kickstart and system image files reside in directories or folders that can be accessed from the Cisco MDS 9000 Family switch prompt.
- Image version—Each image file has a version.
- Flash disks on the switch—The bootflash: resides on the supervisor module and the CompactFlash disk is inserted into the slot0: device.
- Supervisor modules—There are single or dual supervisor modules.


Note

On switches with dual supervisor modules, both supervisor modules must have Ethernet connections on the management interfaces (mgmt 0) to maintain connectivity when switchovers occur during upgrades and downgrades. Refer to the [Cisco MDS 9500 Series Hardware Installation Guide](#).

Components Supported

Table 1 lists the NX-OS software part numbers and hardware components supported by the Cisco MDS 9000 Series.

Table 1 Cisco MDS 9000 Series Supported Software and Hardware Components

Component	Part Number	Description	Applicable Product
Software	M97S3K9-6.2.33	MDS 9710, MDS 9706 ¹ , NX-OS software	MDS 9700 Series
	M95S2K9-6.2.33	MDS 9500, NX-OS software	MDS 9500 Series

Table 1 *Cisco MDS 9000 Series Supported Software and Hardware Components (continued)*

Component	Part Number	Description	Applicable Product
	M93S5K9-6.2.33	MDS 9396S ² , NX-OS software	MDS 9396S Switch
	M92S5K9-6.2.33	MDS 9250i ³ NX-OS software	MDS 9250i Switch
	M92S2K9-6.2.33	MDS 9222i, NX-OS software	MDS 9222i Switch
	M91S5K9-6.2.33	MDS 9148S ⁴ , NX-OS software	MDS 9148S Switch
	M91S3K9-6.2.33	MDS 9148, NX-OS software	MDS 9148 Switch

Table 1 Cisco MDS 9000 Series Supported Software and Hardware Components (continued)

Component	Part Number	Description	Applicable Product
Licenses	DCNM-SAN-M97-K9	Cisco Prime Data Center Network Manager	MDS 9700 Series
	M97ENTK9	Enterprise Package for one Cisco MDS 9700 Series Multilayer Director	MDS 9700 Series
	M97FIC1K9	Cisco MDS 9700 Mainframe Package license for one MDS 9700 Switches	MDS 9700 Series
	M9500SSE184K9z	Storage Services Enabler License for one MSM-18/4 module	MDS 9500 Series
	M9300ENT1K9	Cisco MDS 9300 Series Enterprise Package	MDS 9396S Switch
	DCNM-SAN-M93-K9	Cisco Prime Data Center Network Manager	MDS 9396S Switch
	M9200ENT1K9	Cisco MDS 9200 Series Enterprise Package	MDS 9200 Series
	DCNM-SAN-M92-K9	Cisco Prime Data Center Network Manager	MDS 9200 Series
	M9250IIOA	Cisco MDS 9250i I/O Accelerator Services package	MDS 9250i Switch
	M9250IDMMK9	Cisco MDS 9250i Data Mobility Manager package	MDS 9250i Switch
	M9250IDMMT6M	Cisco MDS 9250i DMM License - 6-month period	MDS 9250i Switch
	M9200FIC1K9	Cisco MDS 9200 Series Mainframe Package	MDS 9200 Series
	M9200XRC	Cisco MDS 9200 XRC Acceleration Package for IBM series z, spare	MDS 9200 Series
	M9222ISSE1K9	Storage Services Enabler License	MDS 9222i Switch
	M9200SSE184K9	Storage Services Enabler License for one MSM-18/4 module	MDS 9222i Switch
	M95DMM184K9	Data Mobility Manager License for one MSM-18/4 module	MDS 9500 Series
	M9222IDMMK9	Data Mobility Manager License for Cisco MDS 9222i	MDS 9222i Switch
	M92DMM184K9	Data Mobility Manager License for one MSM-18/4 module	MDS 9222i Switch
	M95DMM184TSK9	Data Mobility Manager for one MSM-18/4 module — Time limited to 180 days only	MDS 9500 Series
	M9222IDMMTSK9	Data Mobility Manager — Time limited to 180 days only	MDS 9222i Switch
	M92DMM184TSK9	Data Mobility Manager for one MSM-18/4 module — Time limited to 180 days only	MDS 9222i Switch
	M92SSESSNK9	Cisco Storage Services Enabler License for SSN-16 (1 engine)	MDS 9222i Switch
	M95SSESSNK9	Cisco Storage Services Enabler License for SSN-16 (1 engine)	MDS 9500 Series
M92SMESSNK9	Cisco Storage Media Encryption License for SSN-16 (1 engine)	MDS 9222i Switch	

Table 1 *Cisco MDS 9000 Series Supported Software and Hardware Components (continued)*

Component	Part Number	Description	Applicable Product
	M95SMESSNK9	Cisco Storage Media Encryption License for SSN-16 (1 engine)	MDS 9500 Series
	M92IOASSN	Cisco I/O Accelerator License for SSN-16 (1 engine)	MDS 9222i Switch
	M95IOASSN	Cisco I/O Accelerator License for SSN-16 (1 engine)	MDS 9500 Series
	M92IOA184	Cisco I/O Accelerator License for MSM-18/4	MDS 9222i Switch
	M95IOA184	Cisco I/O Accelerator License for MSM-18/4	MDS 9500 Series
	M9222IIOA	Cisco I/O Accelerator License for Cisco MDS 9222i base switch	MDS 9222i Switch
	M92EXTSSNK9	Cisco SAN Extension License for SSN-16 (1 engine)	MDS 9222i Switch
	M95EXTSSNK9	Cisco SAN Extension License for SSN-16 (1 engine)	MDS 9500 Series
	M9200XRC	Cisco XRC Acceleration	MDS 9200 Series
	M9500XRC	Cisco XRC Acceleration	MDS 9500 Series

Table 1 Cisco MDS 9000 Series Supported Software and Hardware Components (continued)

Component	Part Number	Description	Applicable Product
Chassis	DS-C9710	Cisco MDS 9710 Multilayer Director (10-slot multilayer director with 2 half-width slots for Supervisor modules, with 8 slots available for switching modules — SFPs sold separately)	MDS 9710 Switch
	DS-C9706	Cisco MDS 9706 Multilayer Director (6-slot multilayer director with 2 half-width slots for Supervisor modules, with 4 slots available for switching modules — SFPs sold separately)	MDS 9706 Switch
	DS-C9513	Cisco MDS 9513 Multilayer Director (13-slot multilayer director with 2 slots for Supervisor modules, with 11 slots available for switching modules — SFPs sold separately)	MDS 9513 Switch
	DS-C9509	Cisco MDS 9509 Multilayer Director (9-slot multilayer director with 2 slots for Supervisor modules, with 7 slots available for switching modules — SFPs sold separately)	MDS 9509 Switch
	DS-C9506	Cisco MDS 9506 Multilayer Director (6-slot multilayer director with 2 slots for Supervisor modules, with 4 slots available for switching modules — SFPs sold separately)	MDS 9506 Switch
	DS-C9396S-K9	Cisco MDS 9396S 96-Port Multilayer Fabric Switch (2RU fixed-configuration multilayer fabric switch with 96 16-Gbps Fibre Channel ports)	MDS 9396S Switch
	DS-C9250I-K9	The Cisco MDS 9250i offers up to forty 16-Gbps Fibre Channel ports, two 10 Gigabit Ethernet IP storage services ports, and eight 10 Gigabit Ethernet Fibre Channel over Ethernet (FCoE) ports in a fixed two-rack-unit (2RU) form factor.	MDS 9250i Switch
	DS-C9222i-K9	Cisco MDS 9222i Multilayer Fabric Switch (3-rack-unit (3RU) semimodular multilayer fabric switch with 18 4-Gbps Fibre Channel ports, 4 Gigabit Ethernet ports, and a modular expansion slot for Cisco MDS 9000 Series Switching and Services modules)	MDS 9222i Switch
	DS-C9148S-K9	Cisco MDS 9148S 48-Port Multilayer Fabric Switch (1RU fixed-configuration multilayer fabric switch with 48 16-Gbps Fibre Channel ports)	MDS 9148S Switch
	DS-C9148-K9	Cisco MDS 9148 48-Port Multilayer Fabric Switch (1RU fixed-configuration multilayer fabric switch with 48 8-Gbps Fibre Channel ports)	MDS 9148 Switch
Supervisor Modules	DS-X97-SF1-K9	Cisco MDS 9700 Series Supervisor-1 Module	MDS 9700 Series
	DS-X9530-SF2-K9	Cisco MDS 9500 Series Supervisor-2 Module	MDS 9500 Series
	DS-X9530-SF2A-K9	Cisco MDS 9500 Series Supervisor-2A Module	MDS 9500 Series
Switching Modules	DS-X9448-768K9	Cisco MDS 9000 48-port 16-Gbps Fibre Channel Switching Module with SFP LC connectors	MDS 9700 Series

Table 1 Cisco MDS 9000 Series Supported Software and Hardware Components (continued)

Component	Part Number	Description	Applicable Product
	DS-X9848-480K9	Cisco MDS 48-Port 10-Gigabit Fibre Channel over Ethernet (FCoE) Module with SFP LC connectors	MDS 9700 Series
	DS-X9112 ⁵	Cisco MDS 9000 12-port 4-Gbps Fibre Channel Switching Module with SFP LC connectors	MDS 9500 Series MDS 9200 Series
	DS-X9124 ⁶	Cisco MDS 9000 24-port 4-Gbps Fibre Channel Switching Module	
	DS-X9148 ⁷	Cisco MDS 9000 48-port 4-Gbps Fibre Channel Switching Module with SFP LC	MDS 9500 Series MDS 9200 Series
	DS-X9224-96K9 ⁸	Cisco MDS 9000 24-Port 8-Gbps Fibre Channel Switching Module with SFP and SFP+ LC connectors	MDS 9500 Series
	DS-X9248-96K9 ⁹	Cisco MDS 9000 48-Port 8-Gbps Fibre Channel Switching Module with SFP and SFP+ LC connectors	MDS 9500 Series
	DS-X9248-48K9 ¹⁰	Cisco MDS 9000 4/44-Port Host-Optimized 8-Gbps Fibre Channel Switching Module with SFP and SFP+ LC connectors	MDS 9500 Series MDS 9222i Switch
	DS-X9708-K9	Cisco MDS 9000 8-port 10-Gbps Fibre Channel over Ethernet (FCoE) Module	MDS 9500 Series
	DS-X9232-256K9	Cisco MDS 9000 32-port 8-Gbps Advanced Fibre Channel Switching Module	MDS 9500 Series
	DS-X9248-256K9	Cisco MDS 9000 48-port 8-Gbps Advanced Fibre Channel Switching Module	MDS 9500 Series
Services Modules	DS-X9316-SSNK9	Cisco MDS 9000 Series 16-Port Storage Services Node (SSN-16) — 16 fixed 1-Gbps Ethernet ports, plus 4 service engines that support 16-Gigabit Ethernet IP storage services ports.	MDS 9500 Series MDS 9222i Switch
	DS-X9304-18K9	Cisco MDS 9000 18/4-Port Multiservice Module (MSM-18/4) — 18-port, 4-Gbps Fibre Channel plus 4-port Gigabit Ethernet IP services and switching module with SFP LC connectors	MDS 9500 Series MDS 9200 Series
External crossbar module	DS-X9710-FAB1	Cisco MDS 9710 Crossbar Switching Fabric 1 Module	MDS 9710 Switch
	DS-X9706-FAB1	Cisco MDS 9706 Crossbar Switching Fabric 1 Module	MDS 9706 Switch
	DS-13SLT-FAB1 ¹¹	Cisco MDS 9513 Switching Fabric 1 Module	MDS 9513 Switch
	DS-13SLT-FAB2 ¹²	Cisco MDS 9513 Switching Fabric 2 Module	MDS 9513 Switch
	DS-13SLT-FAB3	Cisco MDS 9513 Switching Fabric 3 Module	MDS 9513 Switch

Table 1 Cisco MDS 9000 Series Supported Software and Hardware Components (continued)

Component	Part Number	Description	Applicable Product
Power Supplies	DS-CAC-300W	300W AC power supply	MDS 9148 Switch
	DS-C48-300AC	300W AC power supply	MDS 9148 Switch
	DS-C48S-300AC	300W AC power supply	MDS 9148S Switch
	DS-CAC-845W	845W AC power supply	MDS9200 Series
	DS-C50I-300AC	300W AC power supply	MDS 9250i Switch
	DS-CAC-1200W-E	1200W AC power supply	MDS 9396S Switch
	DS-CAC-1200W	1200W AC power supply	MDS 9396S Switch
	DS-CAC-3000W	3000W AC power supply	MDS 9509 Switch
	DS-CAC-2500W	2500W AC power supply	MDS 9509 Switch
	DS-CDC-2500W	2500W DC power supply	MDS 9509 Switch
	DS-CAC-6000W	6000W AC power supply	MDS 9513 Switch
	DS-CAC-1900W	1900W AC power supply	MDS 9506 Switch
	DS-CAC97-3KW	3000W AC power supply	MDS 9700 Series
	DS-CDC97-3KW	3000W DC power supply	MDS 9700 Series
DS-CHV-3.5KW ¹³	3500W High Voltage DC power supply	MDS 9700 Series	
CompactFlash	MEM-MDS-FLD512M	External 512-MB CompactFlash memory for supervisor module	MDS 9500 Series
Smart Card Reader	DS-SCR-K9	Storage Media Encryption (SME) Smart Card Reader	MDS 9000 Series
Smart Card	DS-SC-K9	SME Smart Card	MDS 9000 Series

1. This switch supports Cisco MDS NX-OS Release 6.2(9) and later.
2. This switch supports Cisco MDS NX-OS Release 6.2(13a) and later.
3. This switch supports Cisco MDS NX-OS Release 6.2(5) and later.
4. This switch supports Cisco MDS NX-OS Release 6.2(9) and later.
5. This product has reached End of Support as of February 28, 2015. For more information on the End of Support, see the [End-of-Sale and End-of-Life Announcement for the Cisco MDS 9000 Family 4-Gbps Fibre Channel Switching Module](#) statement.
6. This product has reached End of Support as of February 28, 2015. For more information on the End of Support, see the [End-of-Sale and End-of-Life Announcement for the Cisco MDS 9000 Family](#) statement.
7. This switch supports Cisco MDS NX-OS Release 6.2(9) and later.
8. This product has reached End of Support as of July 31, 2018. For more information on the End of Support, see the [End-of-Sale and End-of-Life Announcement for the Cisco MDS 9000 48-Port 8-Gbps Fibre Channel Switching Module](#) statement.
9. This product has reached End of Support as of July 31, 2018. For more information on the End of Support, see the [End-of-Sale and End-of-Life Announcement for the Cisco MDS 9000 48-Port 8-Gbps Fibre Channel Switching Module](#) statement.
10. This product has reached End of Support as of July 31, 2018. For more information on the End of Support, see the [End-of-Sale and End-of-Life Announcement for the Cisco MDS 9000 48-Port 8-Gbps Fibre Channel Switching Module](#) statement.
11. This product has reached End of Support as of July 7, 2014. For more information on the End of Support, see the [End-of-Sale and End-of-Life Announcement for the Cisco MDS 9513 Crossbar Switching Fabric Module](#) statement.
12. This product has reached End of Support as of April 30, 2018. For more information on the End of Support, see the [End-of-Sale and End-of-Life Announcement for the Cisco MDS 9513 Crossbar Switching Fabric Module 2](#) statement.
13. This product supports Cisco MDS NX-OS Release 6.2(19) and later.

Table 2 lists the part numbers and optical components supported by the Cisco MDS 9000 Series.

**Note**

For the latest information about supported transceivers (SFPs), see the [Cisco MDS 9000 Series Pluggable Transceivers](#) data sheet.

Table 2 Cisco MDS 9000 Series Supported Optics and Transceivers

Component	Part Number	Description	Applicable Product
Optics	SFP-10G-SR / DS-SFP-10GE-SR	10GBASE-SR SFP+ Module	MDS 9700 Series, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i, MDS 9396S
	SFP-10G-LR / DS-SFP-10GE-LR	10GBASE-LR SFP+ Module	MDS 9700 Series, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i, MDS 9396S
	SFP-10G-ER	10GBASE-ER SFP+ Module	MDS 9700 Series, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i, MDS 9396S
	SFP-H10GB-CU1M	10GBASE-CU SFP+ cable 1 meter	MDS 9700 Series, DS-X9848-480K9, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i
	SFP-H10GB-CU3M	10GBASE-CU SFP+ cable 3 meter	MDS 9700 Series, DS-X9848-480K9, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i
	SFP-H10GB-CU5M	10GBASE-CU SFP+ cable 5 meter	MDS 9700 Series, DS-X9848-480K9, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i
	SFP-H10GB-ACU7M	10GBASE-CU SFP+ active copper cable 7 meter	MDS 9700 Series, DS-X9848-480K9, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i
	SFP-H10GB-ACU10M	10GBASE-CU SFP+ active copper cable 10 meter	MDS 9700 Series, DS-X9848-480K9, MDS 9500 Series, 8-port 10-Gbps FCoE Module (DS-X9708-K9), MDS 9250i
	DS-16G-ER-Dxxx	Smart Optics DWDM 16G LWL SFP	MDS 9700 Series (DS-X9448-768K9), MDS 9148S, MDS 9250i, MDS 9396S
	DS-16G-ER	Smart Optics 16G LWL SFP	MDS 9700 Series (DS-X9448-768K9), MDS 9148S, MDS 9250i, MDS 9396S
	DS-16G-ER-Cxx	Smart Optics CWDM 16G LWL SFP	MDS 9700 Series (DS-X9448-768K9), MDS 9148S, MDS 9250i, MDS 9396S

Table 2 Cisco MDS 9000 Series Supported Optics and Transceivers (continued)

Component	Part Number	Description	Applicable Product
	DS-8G-ZR-Dxxx	Smart Optics DWDM 8G LWL SFP	MDS 9700 Series (DS-X9448-768K9), MDS 9148S, MDS 9250i, MDS 9396S
	DS-8G-ZR	Smart Optics 8G LWLSFP	MDS 9700 Series (DS-X9448-768K9), MDS 9148S, MDS 9250i, MDS 9396S
	DS-8G-ZR-Cxx	Smart Optics CWDM 8G LWL SFP	MDS 9700 Series (DS-X9448-768K9), MDS 9148S, MDS 9250i, MDS 9396S
LC-type fiber-optic SFP	DS-SFP-FC16G-SW	SFP+ optics (LC type) for 16-Gbps Fibre Channel for shortwave mode	MDS 9700 Series, 48-port 16-Gbps Fibre Channel Switching Module (DS-X9448-768K9), MDS 9250i, MDS 9148S, MDS 9396S
	DS-SFP-FC16G-LW	SFP+ optics (LC type) for 16-Gbps Fibre Channel for longwave mode (10km reach)	MDS 9700 Series, 48-port 16-Gbps Fibre Channel Switching Module (DS-X9448-768K9), MDS 9250i, MDS 9148S, MDS 9396S
	DS-SFP-FC16GELW=	SFP+ optics (LC type) for 16-Gbps Fibre channel for longwave mode; (25km reach).	48-port 16-Gbps Fibre Channel Switching Module (DS-X9448-768K9), MDS 9250i, MDS 9148S, MDS 9396S
	DS-SFP-FC10G-SW	SFP+ optics (LC type) for 10-Gbps Fibre Channel for shortwave mode	48-port 16-Gbps Fibre Channel Switching Module (DS-X9448-768K9), 32-port 8-Gbps Advanced Fibre Channel Module (DS-X9232-256K9), 48-port 8-Gbps Advanced Fibre Channel Module (DS-X9248-256-K9), MDS 9396S
	DS-SFP-FC10G-LW	SFP+ optics (LC type) for 10-Gbps Fibre Channel for longwave mode (10km reach)	48-port 16-Gbps Fibre Channel Switching Module (DS-X9448-768K9), 32-port 8-Gbps Advanced Fibre Channel Module (DS-X9232-256K9), 48-port 8-Gbps Advanced Fibre Channel Module (DS-X9248-256-K9), MDS 9396S
	DS-SFP-FC8G-ER	SFP+ optics (LC type) for 2-, 4-, or 8-Gbps Fibre Channel for extended reach (40 km reach)	MDS DS-X9200 Series switching modules, 48-port 16-Gbps Fibre Channel Switching Module (DS-X9448-768K9) MDS 9148 MDS 9250i, MDS 9148S, MDS 9396S
	DS-SFP-FC8G-SW	SFP+ optics (LC type) for 2-, 4-, or 8-Gbps Fibre Channel for shortwave mode	MDS 9700 Series, MDS 9500 Series, MDS DS-X9200 Series switching modules, MDS 9250i, MDS 9148, MDS 9148S, MDS 9396S
	DS-SFP-FC8G-LW	SFP+ optics (LC type) for 2-, 4-, or 8-Gbps Fibre Channel for longwave mode; supports distances up to 10 km	MDS 9700 Series, MDS 9500 Series, MDS DS-X9200 Series switching modules, MDS 9250i, MDS 9148, MDS 9148S, MDS 9396S

Table 2 Cisco MDS 9000 Series Supported Optics and Transceivers (continued)

Component	Part Number	Description	Applicable Product
	DS-SFP-FC4G-SW	SFP optics (LC type) for 1-, 2-, or 4-Gbps Fibre Channel for shortwave mode	MDS 9134, MDS 9148, MDS 9222i, DS-X9100, and DS-X9200 Series switching modules
	DS-SFP-FC4G-MR	SFP optics (LC type) for 1-, 2-, or 4-Gbps Fibre Channel for longwave mode; supports distances up to 4 km	MDS 9134, MDS 9222i, DS-X9100, and DS-X9200 Series switching modules
	DS-SFP-FC4G-LW	SFP optics (LC type) for 1-, 2-, or 4-Gbps Fibre Channel for longwave mode; supports distances up to 10 km	MDS 9134, MDS 9222i, DS-X9100, and DS-X9200 Series switching modules
	DS-SFP-FCGE-SW	SFP optics (LC type) for 1-Gbps Ethernet and 1- or 2-Gbps Fibre Channel for shortwave mode; not for use in 4-Gbps-capable ports	DS-X9316-SSNK9, DS-X9304-18K9, MDS 9222i, MDS 9250i
	DS-SFP-FCGE-LW	SFP optics (LC type) for 1-Gbps Ethernet and 1- or 2-Gbps Fibre Channel for longwave mode; not for use in 4-Gbps-capable ports	DS-X9316-SSNK9, DS-X9304-18K9, MDS 9222i, MDS 9250i
	DS-SFP-GE-T	SFP (RJ-45 connector) for Gigabit Ethernet over copper	DS-X9316-SSNK9, DS-X9304-18K9, MDS 9222i, MDS 9250i
Cisco Coarse Wavelength-Division Multiplexing (CWDM)	DS-CWDM-xxxx	CWDM Gigabit Ethernet and 1- or 2-Gbps Fibre Channel SFP LC type, where product number xxxx = 1470, 1490, 1510, 1530, 1550, 1570, 1590, or 1610 nm	MDS 9000 Series
	DS-CWDM4Gxxxx	CWDM 4-Gbps Fibre Channel SFP LC type, where product number xxxx = 1470, 1490, 1510, 1530, 1550, 1570, 1590, or 1610 nm	MDS 9000 Series
	CWDM8G1490	1490 nm CWDM 2/4/8-Gbps Fibre Channel SFP+	DS-X9200 Series switching modules, MDS 9700 Series, 48-port 16-Gbps Fibre Channel Switching Module (DS-X9448-768K9), MDS 9148, MDS 9250i, MDS 9148S, MDS 9396S

Table 2 Cisco MDS 9000 Series Supported Optics and Transceivers (continued)

Component	Part Number	Description	Applicable Product
Dense Wavelength-Division Multiplexing (DWDM)	DWDM-X2-xx.xx	DWDM X2 SC optics for 10-Gbps Fibre Channel connectivity to an existing Ethernet DWDM infrastructure, with 15xx.xx nm wavelength, where xx.xx = 60.61, 59.79, 58.98, 58.17, 56.55, 55.75, 54.94, 54.13, 52.52, 51.72, 50.92, 50.12, 48.51, 47.72, 46.92, 46.12, 44.53, 43.73, 42.94, 42.14, 40.56, 39.77, 38.98, 38.19, 36.61, 35.82, 35.04, 34.25, 32.68, 31.90, 31.12, or 30.33	MDS 9500 Series MDS 9200 Series
	DWDM-SFP-xxxx	DWDM Gigabit Ethernet and 1- or 2-Gbps Fibre Channel SFP LC type, where product number xxxx = 3033, 3112, 3190, 3268, 3425, 3504, 3582, 3661, 3819, 3898, 3977, 4056, 4214, 4294, 4373, 4453, 4612, 4692, 4772, 4851, 5012, 5092, 5172, 5252, 5413, 5494, 5575, 5655, 5817, 5898, 5979, or 6061nm	MDS 9000 Series
	DWDM-SFP10G-xx.xx	10GBASE-DWDM SFP+	DS-X9848-480K9, MDS 9250i ¹
Add/Drop Multiplexer (ADM)	DS-CWDMOADM4A	4-channel CWDM optical ADM (OADM) module (Cisco CWDM 1470, 1490, 1510, or 1530 NM Add/Drop Module)	MDS 9000 Series
	DS-CWDMOADM4B	4-channel CWDM OADM module (Cisco CWDM 1550, 1570, 1590, or 1610 NM Add/Drop Module)	MDS 9000 Series
	DS-CWDM-MUX8A	ADM for 8 CWDM wavelengths	MDS 9000 Series
CWDM Multiplexer Chassis	DS-CWDMCHASSIS	2-slot chassis for CWDM ADMs	MDS 9000 Series

1. Supported in both FCoE and FCIP ports.

Selecting the Correct Software Image for an MDS 9100 Series Switch

Table 1-3 lists the image filename for Cisco MDS 9100 Series switches.

Table 1-3 Software Images for MDS 9100 Series Switches

Cisco MDS 9100 Series Switch Type	Naming Convention
Cisco MDS 8-Gbps Fabric Switch for HP c-Class BladeSystem	Both of these switches have the same filename that begins with m9100-s3ek9
MDS 9148	
MDS 9148S	Both of these switches have the same filename that begins with m9100-s5ek9

Selecting the Correct Software Image for an MDS 9200 Switch

Table 1-4 lists the image filename for Cisco MDS 9200 switch.

Table 1-4 Software Image for MDS 9200 Switch

Cisco MDS 9200 Switch Type	Naming Convention
MDS 9222i	Filename begins with m9200-s2ek9

Selecting the Correct Software Image for an MDS 9250i Switch

Table 1-5 lists the image filename for a Cisco MDS 9250i switch.

Table 1-5 Software Image for the MDS 9250i Switch

Cisco MDS 9250i Switch Type	Naming Convention
MDS 9250i	Filename begins with m9250-s5ek9

Selecting the Correct Software Image for an MDS 9396S Switch

Table 1-6 lists the image filename for Cisco MDS 9396S switch.

Table 1-6 Software Image for MDS 9396S Switch

Cisco MDS 9396S Switch Type	Naming Convention
MDS 9396S	Filename begins with m9300-s1ek9

Selecting the Correct Software Image for an MDS 9500 Series Switch

Table 1-7 lists the image filename for Cisco MDS 9500 Series switches.

Table 1-7 Software Images for MDS 9500 Series Switches

Cisco MDS 9500 Series Switch Type	Supervisor Module Type	Naming Convention
MDS 9513, 9506, and 9509	Supervisor-2 module Supervisor-2A module	Filename begins with m9500-sf2ek9

Use the **show module** command to display the type of supervisor module in the switch. For a Supervisor-1 module, the output might look like this:

```
switch# show module
Mod  Ports  Module-Type                Model                Status
-----
...
...
5    0      Supervisor/Fabric-1        DS-X9530-SF1-K9     active*
6    0      Supervisor/Fabric-1        DS-X9530-SF1-K9     ha-standby
```

For a Supervisor-2 module, the output might look like this:

```
switch# show module
Mod  Ports  Module-Type                Model                Status
-----
...
...
7    0      Supervisor/Fabric-2        DS-X9530-SF2-K9     active *
8    0      Supervisor/Fabric-2        DS-X9530-SF2-K9     ha-standby
```

Selecting the Correct Software Image for an MDS 9700 Series Switch

Table 1-8 lists the image filename for a Cisco MDS 9700 Series switch.

Table 1-8 Software Images for the MDS 9710 Switch

Cisco MDS 9710 Switch Type	Supervisor Module Type	Naming Convention
MDS 9710	Supervisor-3 module	Filename begins with m9700-sf3ek9
MDS 9706	Supervisor-3 module	Filename begins with m9700-sf3ek9

Installing Cisco NX-OS Release 6.2(x) Software on a New Cisco MDS Switch



Note

If the management 10/100/1000 Ethernet port (mgmt0) interface of the Cisco MDS 9700 Series switches has a preconfigured "/0" IPv6 address that cannot be removed, use the **write erase boot** command to clear the complete configuration of the device and reload it. Perform this process before commissioning the device into production as this process is disruptive to user traffic if it is applied to the active supervisor of a system. Ensure an active console connection to the supervisor as this process will remove the IPv4 address of the mgmt0 interface.

To install the latest Cisco NX-OS Release 6.2(x) software images on a new Cisco MDS 9000 Family switch, follow these steps:

- Step 1** Log in to Cisco.com to access the links provided in this document. To log in to Cisco.com, go to the URL <http://www.cisco.com/> and click **Log In** at the top of the page. Enter your Cisco Systems username and password.



Note Unregistered Cisco.com users cannot access the links provided in this document.

- Step 2** Verify the following physical connections for the new Cisco MDS 9000 Family switch:
- The console port is physically connected to a computer terminal (or terminal server).
 - The management 10/100/1000 Ethernet port (mgmt0) is connected to an external hub, switch, or router.

Information on physical connections can be found in the [Cisco MDS 9000 Series Hardware Installation Guides](#).



Note On switches with dual supervisor modules, both supervisor modules must have Ethernet connections on the management interfaces (mgmt 0) to maintain connectivity when switchovers occur during upgrades and downgrades. Refer to the [Cisco MDS 9500 Series Hardware Installation Guide](#).



Tip Save the host ID information for future use (for example, to enable licensed features). The host ID information is provided in the Proof of Purchase document that accompanies the switch.

- Step 3** Verify that the default console port parameters are identical to the parameters of the computer terminal (or terminal server) attached to the switch console port:
- 9600 baud
 - 8 data bits
 - 1 stop bit
 - No parity

Refer to the “Configuring Terminal Settings and Sessions” chapter in the [Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide](#).

- Step 4** Power up the Cisco MDS 9000 Family switch. The switch boots automatically and the switch prompt appears in your terminal window.
- Step 5** Obtain the IP address, subnet mask, and default gateway information that is required for the Cisco MDS 9000 Family switch to communicate over the supervisor module Ethernet interface. This information is required to configure and manage the switch.

Refer to the “Using the Cisco NX-OS Setup Utility” chapter in the [Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide](#).



Tip You have the option to change the default password during the initial setup process. All Cisco MDS 9000 Family switches have the network administrator as a default user (admin) and a default password (admin). You cannot change the default user at any time.

- Step 6** Complete the System Admin Account Setup.

**Tip**

If you create a short, easy-to-decipher password, your password is rejected. Be sure to configure a strong password as shown in the sample configuration. Passwords are case sensitive. You must explicitly create a password that meets the requirements listed in the “Characteristics of Strong Passwords” section in the “Configuring Users and Common Roles” chapter in the *Cisco MDS 9000 Family NX-OS Security Configuration Guide*.

```
---- System Admin Account Setup ----
```

```
Do you want to enforce secure password standard (yes/no) [y]: y
```

```
Enter the password for "admin":
```

```
Confirm the password for "admin":
```

Step 7 Enter **yes** to enter the setup mode and assign the information obtained in Step 5.

Refer to the “Using the Cisco NX-OS Setup Utility” chapter in the *Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide*.

**Note**

Press **Ctrl-C** at any prompt to skip the remaining configuration options and proceed with what is configured until that point.

**Tip**

If you do not want to answer a previously configured question, or if you want to skip answers to any questions, press **Enter**. If a default answer is not available (for example, a switch name), the switch uses the previously configured settings and skips to the next question.

The CLI configuration steps (using factory defaults) are as follows:

```
---- Basic System Configuration Dialog ----
```

```
This setup utility will guide you through the basic configuration of
the system. Setup configures only enough connectivity for management
of the system.
```

```
Press Enter incase you want to skip any dialog. Use ctrl-c at anytime
to skip remaining dialogs.
```

```
Would you like to enter the basic configuration dialog (yes/no): yes
```

By default, two roles exist in all switches:

- Network operator (network-operator)—Has permission to view the configuration only. The operator cannot make any configuration changes.
- Network administrator (network-admin)—Has permission to execute all commands and make configuration changes. The administrator can also create and customize up to 64 additional roles. One (of these 64 additional roles) can be configured during the initial setup process.

```
Create another login account (yes/no) [n]: yes
```



Note While configuring your initial setup, you can create an additional user account (in the network-admin role) besides the administrator's account. The user name must contain non-numeric characters. Refer to the "Configuring User Accounts" section in the "Configuring Users and Common Roles" chapter in the *Cisco MDS 9000 Family NX-OS Security Configuration Guide*.

Enter the user login ID: *test*

Enter the password for "test":

Confirm the password for "test":

Enter the user role [network-operator]:



Tip If you use SNMPv3, then do not configure the SNMPv2 community string. Refer to the "Configuring SMNP" chapter in the *Cisco MDS 9000 Family NX-OS System Management Configuration Guide*.

Configure read-only SNMP community string (yes/no) [n]: **yes**

SNMP community string: *admin*



Note The switch name is limited to 32 alphanumeric characters.

Enter the switch name: *switch*

Continue with Out-of-band (mgmt0) management configuration? [yes/no]: **yes**

IP version 6 (IPv6) is supported in Cisco MDS NX-OS Release 4.1(x) and later. However, the setup script only supports IP version 4 (IPv4) for the management interface. For information on configuring IPv6 on the management interface, refer the *Cisco MDS 9000 Family NX-OS IP Services Configuration Guide*, or the *IP Services Configuration Guide, Cisco DCNM for SAN*.

Mgmt0 IPv4 address: *ip_address*

Mgmt0 IPv4 netmask: *subnet_mask*

Configure the default gateway? (yes/no) [y]: **yes**

IPv4 address of the default gateway : 209.165.200.225

Configure advanced IP options? (yes/no) [n]: **yes**

Continue with In-band (vsan1) management configuration? (yes/no) [n]: **n**

Enable IP routing? (yes/no) [n]: **yes**

Configure static route? (yes/no) [n]: **n**



Note Be sure to configure the IP route, the IP default network address, and the IP default gateway address to enable SNMP access. If IP routing is enabled, the switch uses the IP route and the default network IP address. If IP routing is disabled, the switch uses the default gateway IP address.

Configure the default-network: (yes/no) [y]: **yes**



Note The default network address is the **Destination prefix: dest_prefix** provided above in **Mgmt0 IPv4 netmask: subnet_mask**.

Default network IPv4 address: *dest_prefix*

Configure the DNS IPv4 address? (yes/no) [y]: **yes**

DNS IP address: *name_server_ip_address*

Configure the default domain name? (yes/no) [n]: **yes**

Default domain name: *domain_name*



Note Refer to the “Configuring Users and Common Roles” chapter in the *Cisco MDS 9000 Family NX-OS Security Configuration Guide*.

Enable the ssh service? (yes/no) [y]:

Type of ssh key you would like to generate (dsa/rsa) [rsa]:

Number of rsa key bits <768-2048> [1024]:

Enable the telnet service? (yes/no) [n]: **y**

Enable the http-server? (yes/no) [y]:

Configure clock? (yes/no) [n]: **yes**

Clock config format [HH:MM:SS Day Mon YYYY] :

Enter clock config :10:10:10 1 July 2013

Configure timezone? (yes/no) [n]: **y**

Enter timezone config :**pst**

Configure summertime? (yes/no) [n]: **yes**

summer-time config :PDT 2 sunday march 02:00 1 sunday november 02:00 59

Configure NTP server? (yes/no) [n]: **yes**

NTP server IP address: *ntp_server_IP_address*

Configure default switchport interface state (shut/noshut) [shut]: **shut**



Note The mgmt0 interface is not shutdown at this point. Only the Fibre Channel, iSCSI, FCIP, and Gigabit Ethernet interfaces are shut down.

Configure default switchport trunk mode (on/off/auto) [on]: **on**

Configure default switchport port mode F (yes/no) [n]: **yes**

Configure default zone policy (permit/deny) [deny]: **deny**

Enable full zoneset distribution (yes/no) [n]: **yes**

Configure default zone mode (basic/enhanced) [basic]: **basic**



Note Refer to the “Configuring and Managing Zones” chapter in the *Cisco MDS 9000 Family NX-OS Fabric Configuration Guide*.

The following configuration will be applied:

```
username admin password admin_pass role network-admin
username user_name password user_pass role network-admin
snmp-server community snmp_community ro
switchname switch
interface mgmt0
  ip address ip_address subnet_mask
  no shutdown
ip routing
ip route dest_prefix dest_mask dest_address
ip default-network dest_prefix
ip default-gateway default_gateway
ip name-server name_server
ip domain-name domain_name
telnet server disable
ssh key rsa 2048 force
ssh server enable
ntp server ipaddr ntp_server
system default switchport shutdown
system default switchport trunk mode on
system default switchport mode F
system default port-channel auto-create
zone default-zone permit vsan 1-4093
zoneset distribute full vsan 1-4093
system default zone mode enhanced
```

Would you like to edit the configuration? (yes/no) [n]: **no**

Would you like to edit the configuration? (yes/no) [n]: **no**

Use this configuration and save it? (yes/no) [y]: **yes**



Caution If you do not save the configuration at this point, your changes will not be updated the next time that the switch is rebooted. Type **yes** in order to save the new configuration. This process ensures that the kickstart and system boot images are also automatically configured.



Tip Up to this point, you can only configure the switch using the CLI. After this step, you can continue configuring the switch using the CLI or switch over to using the Cisco DCNM application. Refer to the *Cisco DCNM Fundamentals Configuration Guide*.

If you continue to use the CLI, the login prompt automatically appears in your terminal window.

Step 8 Log in to the switch using the new user name and password.

Step 9 Verify that the required licenses are installed in the switch using the **show license** command.

**Note**

The switch is initially shipped with the required licenses installed in the system; however, the initial license file will not cover unlicensed features that may be used during the grace period. Refer to the [Cisco MDS 9000 Family NX-OS Licensing Guide](#).

The example CLI output for a valid license follows:

```
switch# show license
license.lic:
SERVER this_host ANY
VENDOR cisco
INCREMENT ENTERPRISE_PKG cisco 1.0 permanent uncounted \
  VENDOR_STRING=MDS HOSTID=VDH=REG070201 \
  NOTICE="<LicFileID>ent_ips_main_fm.lic</LicFileID><LicLineID>0</LicLineI
D> \
  <PAK>dummyPak</PAK>" SIGN=FB454F0A0D40
INCREMENT MAINFRAME_PKG cisco 1.0 permanent uncounted \
  VENDOR_STRING=MDS HOSTID=VDH=REG070201 \
  NOTICE="<LicFileID>ent_ips_main_fm.lic</LicFileID><LicLineID>1</LicLineI
D> \
  <PAK>dummyPak</PAK>" SIGN=0DAE1B086D9E
INCREMENT SAN_EXTN_OVER_IP cisco 1.0 permanent 7 VENDOR_STRING=MDS \
  HOSTID=VDH=REG070201 \
  NOTICE="<LicFileID>ent_ips_main_fm.lic</LicFileID><LicLineID>2</LicLineI
D> \
  <PAK>dummyPak</PAK>" SIGN=D336330C76A6
INCREMENT FM_SERVER_PKG cisco 1.0 permanent uncounted \
  VENDOR_STRING=MDS HOSTID=VDH=REG070201 \
  NOTICE="<LicFileID>ent_ips_main_fm.lic</LicFileID><LicLineID>3</LicLineI
D> \
  <PAK>dummyPak</PAK>" SIGN=AEAEA04629E8
```

- Step 10** Verify that the switch is running the latest Cisco NX-OS 6.2(x) software, depending on which you installed, by issuing the **show version** command.

```
switch# show version
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents: http://www.cisco.com/en/US/products/ps9372/tsd_products_support_serie
s_home.html
Copyright (c) 2002-2013, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software are covered under the GNU Public
License. A copy of the license is available at
http://www.gnu.org/licenses/gpl.html.

Software
  BIOS:      version 1.0.10
  loader:    version N/A
  kickstart: version 6.2(5)
  system:    version 6.2(5)
  BIOS compile time:      01/08/09
  kickstart image file is: bootflash:///m9500-sf2ek9-kickstart-mz.6.2.5.bin
  kickstart compile time: 11/25/2013 9:00:00 [01/30/2014 05:33:20]
  system image file is:   bootflash:///m9500-sf2ek9-mz.6.2.5.bin
  system compile time:    11/25/2013 9:00:00 [01/30/2014 07:10:42]

Hardware
  cisco MDS 9509 (9 Slot) Chassis ("Supervisor/Fabric-2a")
  Motorola, 7447A, altivec with 2071288 kB of memory.
```

```

Processor Board ID JAF1625BAES

Device name: switch
bootflash:      1000944 kB
slot0:          0 kB (expansion flash)

Kernel uptime is 20 day(s), 12 hour(s), 6 minute(s), 27 second(s)

---
switch#

```

If the latest Cisco NX-OS 6.2(x) software version is displayed, you can continue configuring the switch using one of the following options:

- Refer to the [Cisco MDS 9000 NX-OS and SAN-OS Configuration Guides](#) for information on configuring further Cisco NX-OS features using the CLI.
- Refer to the [Cisco DCNM for SAN Configuration Guides](#) for more information on using Cisco DCNM-SAN to configure your switch.

If the latest Cisco NX-OS 6.2(x) software is not displayed, continue with upgrading or downgrading the switch as required to install the correct version. Refer to the appropriate section in this guide for upgrading or downgrading to specific versions.

Step 11 Verify the status of the modules on the switch using the **show module** command.

```

switch# show module
Mod  Ports  Module-Type                Model                Status
---  ---
1    48     1/2/4/8 Gbps 48-Port FC Module DS-X9248-96K9       ok
2    24     1/2/4/8 Gbps 24-Port FC Module DS-X9224-96K9       ok
3    48     1/2/4/8 Gbps 48-Port FC Module DS-X9248-96         ok
4    48     1/2/4/8 Gbps 4/44-Port FC Module DS-X9248-48K9       ok
5    48     1/2/4 Gbps FC Module         DS-X9148             ok
7    0      Supervisor/Fabric-2         DS-X9530-SF2-K9     active *
8    0      Supervisor/Fabric-2         DS-X9530-SF2-K9     ha-standby
11   4      10 Gbps FC Module           DS-X9704             ok
12   22     4x1GE IPS, 18x1/2/4Gbps FC Modul DS-X9304-18K9       ok

Mod  Sw          Hw          World-Wide-Name(s) (WWN)
---  ---
1    6.2(x)      1.0         20:01:00:0d:ec:24:e8:40 to 20:30:00:0d:ec:24:e8:40
2    6.2(x)      0.6         20:41:00:0d:ec:24:e8:40 to 20:58:00:0d:ec:24:e8:40
3    6.2(x)      0.55        20:81:00:0d:ec:24:e8:40 to 20:b0:00:0d:ec:24:e8:40
4    6.2(x)      0.65        20:c1:00:0d:ec:24:e8:40 to 20:f0:00:0d:ec:24:e8:40
5    6.2(x)      1.5         21:01:00:0d:ec:24:e8:40 to 21:30:00:0d:ec:24:e8:40
7    6.2(x)      0.3         --
8    6.2(x)      1.6         --
11   6.2(x)      0.522       22:81:00:0d:ec:24:e8:40 to 22:84:00:0d:ec:24:e8:40
12   6.2(x)      1.1         22:c1:00:0d:ec:24:e8:40 to 22:d2:00:0d:ec:24:e8:40

Mod  MAC-Address(es)                Serial-Num
---  ---
1    00-0d-ec-75-3c-d8 to 00-0d-ec-75-3c-dc XXXXXXXXXXXX
2    00-0d-ec-75-3c-d0 to 00-0d-ec-75-3c-d4 XXXXXXXXXXXX
3    00-50-30-02-19-7e to 00-50-30-02-19-82 XXXXXXXXXXXX
4    00-0d-ec-75-33-dc to 00-0d-ec-75-33-e0 XXXXXXXXXXXX
5    00-19-56-3e-76-5c to 00-19-56-3e-76-60 XXXXXXXXXXXX
7    00-05-30-01-d5-e2 to 00-05-30-01-d5-e6 XXXXXXXXXXXX
8    00-23-5e-99-9f-e8 to 00-23-5e-99-9f-ec XXXXXXXXXXXX
11   00-13-1a-e5-f5-66 to 00-13-1a-e5-f5-6a XXXXXXXXXXXX
12   00-1b-54-02-e5-08 to 00-1b-54-02-e5-10 XXXXXXXXXXXX

```

```

Xbar Ports  Module-Type                Model                Status
-----
1    0      Fabric Module 2                DS-13SLT-FAB2       ok
2    0      Fabric Module 2                DS-13SLT-FAB2       ok

Xbar Sw      Hw      World-Wide-Name(s) (WWN)
-----
1    NA      2.0      --
2    NA      2.0      --

Xbar MAC-Address(es)                Serial-Num
-----
1    NA                        XXXXXXXXXXXX
2    NA                        XXXXXXXXXXXX

* this terminal session
switch#

```

Upgrading to Cisco NX-OS Release 6.2(x) on an Existing Cisco MDS Switch

This section provides information on upgrading your Cisco NS-OS software to Cisco NX-OS Release 6.2(x). It includes the following sections:

- [Upgrading Guidelines, page 24](#)
- [Upgrade Process for an MDS 9700 Series Director, page 24](#)
- [Upgrade Process for the MDS 9513 Director Switch, page 25](#)
- [Upgrade Process for the MDS 9506 and MDS 9509 Director Switches, page 25](#)
- [Upgrading to Cisco NX-OS Release 6.2\(x\) on an MDS 9500 Series Switch, page 34](#)
- [Upgrading to Cisco NX-OS Release 6.2\(9\) on the MDS 9250i Switch, page 43](#)
- [Upgrading to Cisco NX-OS Release 6.2\(x\) on the MDS 9222i Switch, page 49](#)

If your switch is running software that is earlier than Cisco NX-OS Release 5.2(x), you must upgrade to Release 6.2(x). Follow this upgrade path:

- Release 5.0(x): upgrade to 5.2(x), and then upgrade to 6.2(x).
- Release 4.1(x) or release 4.2(x): upgrade to Release 5.0(x), upgrade to Release 5.2(x) and then upgrade to Release 6.2(x).
- Release 3.3(2), Release 3.3(3), Release 3.3(4x), and Release 3.3(5x), upgrade to release 4.1(x) or Release 4.2(x), then upgrade to Release 5.0(x), and then upgrade to Release 5.2(x), and then upgrade to 6.2(x).
- Release 3.3(1c), all Release 3.2(x), all Release 3.1(x), and all Release 3.0(x), upgrade to release 3.3(5b), then upgrade to release 4.1(x) or release 4.2(x), then upgrade to Release 5.0(x), and then upgrade to Release 5.2(x), and then upgrade to 6.2(x).



Note

For a nondisruptive upgrade, the switch must be running Cisco SAN-OS Release 3.3(5b) or later. A disruptive upgrade requires a switch reload.

Upgrading Guidelines

Observe these guidelines when upgrading software on a Cisco MDS 9500 Series Director switch:

- Follow the upgrade path to Cisco NX-OS Release 6.2(x) specified in the Cisco MDS 9000 Series Release Notes for the particular release you intend to install.
- When you replace a linecard with a different type of linecard, the ports revert to VSAN 1 and all the port configurations are lost.

Observe these guidelines when upgrading software on Cisco MDS 9148s, 9250i, 9396s, and 9700 Series Director switches:

- Inserting smartoptics on Cisco MDS 9148s, 9250i, 9396s, and 9700 Series Director switches running an unsupported Cisco MDS NX-OS Release results in the port moving to error-disabled state.
- Upgrading from Cisco MDS NX-OS Release 6.2(19) to any other unsupported release (higher or lower) with smartoptics links that are error disabled will keep the links in the error-disabled state, unless the links are physically removed and inserted to bring the links up.
- Upgrading from Cisco MDS NX-OS Release 6.2(19) to any other unsupported release (higher or lower) with smartoptics links up and trunking will keep the links in trunking state.
- If you copy firmware using the SFTP or SCP clients after enabling the **feature scp-server** or **feature sftp-server** command on your switch, ensure that you close the SFTP or SCP connection before performing ISSU. Otherwise, ISSU will be disruptive. This issue is not seen when you transfer files from the switch using the **copy** command or when using the DCNM client.



Note

Parallel In-Service Software Upgrade (ISSU) is not recommended on MDS 9148S, MDS 9250i and MDS 9396S fabric switches when these category of fabric switches are peers to each other.

Upgrade Process for an MDS 9700 Series Director

On the MDS 9710 Director, the high-level process to upgrade to Cisco NX-OS Release 6.2(x) and is as follows:

-
- Step 1** Upgrade to Cisco MDS NX-OS Release 6.2(x) as described in [“Upgrading to Cisco NX-OS Release 6.2\(x\) on an MDS 9700 Series Switch”](#).
 - Step 2** Install Cisco MDS 48-Port 16-Gbps Fibre Channel Switching Module in the MDS 9710 chassis. For additional information, see the [Cisco MDS 9700 Series Hardware Installation Guide](#).
 - Step 3** Install Cisco MDS 48-Port 10-Gigabit Ethernet module modules in the MDS 9710 chassis. For additional information, see the [Cisco MDS 9700 Series Hardware Installation Guide](#).
 - Step 4** If needed, reload the switch.
-

Upgrade Process for the MDS 9513 Director Switch

On the MDS 9513 switch, the high-level process to upgrade to Cisco NX-OS Release 6.2(x) and enable the increased bandwidth capabilities of the Generation 4 modules is as follows:

-
- Step 1** Upgrade to Cisco MDS NX-OS Release 6.2(x) as described in “[Upgrading to Cisco NX-OS Release 6.2\(x\) on an MDS 9500 Series Switch](#)”.
 - Step 2** Install Cisco MDS 9513 Fabric 3 modules in the MDS 9513 chassis. For additional information, see the “Migrating to Generation 4 8-Gbps Advanced Fibre Channel Switching Modules” section in the [Cisco MDS 9500 Series Switch Hardware Installation Guide](#).
 - Step 3** If needed, reload the switch to enable increased bandwidth capabilities.
 - Step 4** Install Generation 4 8-Gbps Advanced Fibre Channel switching modules.
-

Upgrade Process for the MDS 9506 and MDS 9509 Director Switches

On the MDS 9506 and 9509 Director switches, the high-level process to upgrade to Cisco NX-OS Release 6.2(x) is as follows:

-
- Step 1** Upgrade to a Supervisor-2 or Supervisor-2A module.
 - Step 2** Upgrade to Cisco MDS NX-OS Release 6.2(x) as described in “[Upgrading to Cisco NX-OS Release 6.2\(x\) on an MDS 9500 Series Switch](#)”.
 - Step 3** Install a 8-Gbps Advanced Fibre Channel module.

Upgrading to Cisco NX-OS Release 6.2(x) on an MDS 9700 Series Switch



Note

Use the console connection for firmware upgrades. Be aware that if you are upgrading through the management interface, you must have a working connection to both supervisors, as this process causes a switchover and the current standby supervisor will be active after the upgrade

To upgrade your switch to use the latest Cisco MDS NX-OS software on your Cisco MDS 9700 Series switch, follow these steps:

-
- Step 1** Log in to Cisco.com to access the links provided in this document. To log in to Cisco.com, go to the URL <http://www.cisco.com/> and click **Log In** at the top of the page. Enter your Cisco Systems user name and password.



Note

Unregistered Cisco.com users cannot access the links provided in this document.

-
- Step 2** Verify the following physical connections for the new Cisco MDS 9700 Series :
 - The console port is physically connected to a computer terminal (or terminal server).

- The management 10/100/1000 Ethernet port (mgmt0) is connected to an external hub, switch, or router.

These procedures are specified in the hardware installation guide for the required product. For more information, see the *Cisco MDS 9710 Director Hardware Installation Guide*.

Step 3 Log in to the switch.

Step 4 Issue the **copy running-config startup-config** command to store your current running configuration. You can also create a backup of your existing configuration to a file by issuing the **copy running-config bootflash:backup_config.txt** command. Refer to the “Using the Cisco NX-OS Setup Utility” chapter in the *Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide*.

Step 5 Verify that the requested license files installed in the switch are displayed in response to the **show license usage** command.



Note The switch is initially shipped with the required licenses installed in the system; however, the initial license file will not cover unlicensed features that may be used during the grace period. Refer to the *Cisco MDS 9000 Family NX-OS Licensing Guide*. If no license is displayed at this point, perform **Step 6** and **Step 7** to install the required licenses. If the required licenses are displayed at this point, skip **Step 6** and **Step 7** and move to **Step 8**.

The example CLI output for a valid license follows:

```
switch# show license usage
Feature                               Ins  Lic  Status Expiry Date Comments
                                      Count
-----
FM_SERVER_PKG                         No   -   Unused          -
MAINFRAME_PKG                         No   -   Unused          -
ENTERPRISE_PKG                        Yes  -   Unused never    -
-----
```

Step 6 Install licenses (if necessary) to ensure that the required features are available on the switch. Perform the following steps:

- Use the **show license host-id** command to obtain the serial number for your switch. The host ID is also referred to as the switch serial number.

```
switch# show license host-id
License hostid: VDH=JAF1721AEQG
```



Tip Use the entire ID that appears after the colon (:) sign. In this example, the host ID is VDH=JAF1721AEQG

- Obtain your Claim Certificate or the Proof of Purchase document. This document accompanies every Cisco MDS switch.
- Locate the Product Authorization Key (PAK) from the Claim Certificate or Proof of Purchase document.
- Locate the website URL from the Claim Certificate or Proof of Purchase document.
- Access the specified URL that applies to your switch and enter the switch serial number and the PAK. The license key file is sent to you by e-mail. The license key file is digitally signed to only authorize use on the switch for which it was requested. The requested features are also enabled once the NX-OS software on the specified switch accesses the license key file.



Caution Install the license file in the specified Cisco MDS 9000 Family switch without making any modifications.

Refer to the *Cisco MDS 9000 Family NX-OS Licensing Guide*.

Step 7 Install the license key file when you receive it by e-mail. Perform the following steps:

- a. Copy the license file to bootflash using TFTP or SCP.
- b. Perform the installation by issuing the **install license** command on the active supervisor module from the switch console.

```
switch# install license bootflash:license_file.lic
Installing license ..done
```



Note If you provide a target name for the license key file, the file is installed with the specified name. Otherwise, the file name specified in the license key file is used to install the license.

- c. Exit the switch console.

Refer to the *Cisco MDS 9000 Family NX-OS Licensing Guide*.

Step 8 Ensure that the required space is available in the bootflash: directory for the image file(s) to be copied using the **dir bootflash:** command. Use the **delete bootflash:filename** command to remove unnecessary files.



Note Before downloading and installing Cisco NX-OS software, verify that the release is supported by your Cisco System MDS reseller. If you purchased support through a Cisco Systems reseller, contact them directly for more information. Otherwise, contact Cisco Technical support at this URL: http://www.cisco.com/en/US/support/tsd_cisco_worldwide_contacts.html.

```
switch# dir bootflash:
241410048   May 19 14:11:03 2014 0x501_eth-qos_core.4690
 239902720   May 19 14:21:14 2014 0x501_eth-qos_core.6054
 236326912   Jun 02 13:11:51 2014 0x501_eth-qos_core.6469
   44946     Jun 02 13:12:08 2014 0x501_eth-qos_log.6469
196659318   Apr 03 17:15:00 2014 IMG_629_suh.gbin
 37012992   Apr 03 17:12:51 2014 KS_629_suh.gbin
 36800512   May 15 14:43:21 2014 KS_SA.bin
 36800512   May 15 15:44:28 2014 KS_SA.gbin
196849390   May 15 18:48:29 2014 SUH.bin
 36426752   May 15 18:50:28 2014 SUH_KS.bin
196852387   May 15 19:11:22 2014 SUH_NW.bin
   212670   Feb 26 14:48:19 2014 ac_log
 5047806   Dec 17 11:43:00 2013 cfs
    92     Dec 18 17:51:39 2013 cfs_test.txt
 3400551   May 30 14:08:06 2014 debug
 3378033   Dec 17 11:40:16 2013 dp627
 3366221   Jan 07 14:32:34 2014 dps
   86850   Jun 02 13:09:38 2014 ethpm_act_logs.log
 491521   Jun 02 13:11:39 2014 ethpm_im_tech.log
   608    Jun 02 13:10:38 2014 ethpm_mts_details.log
   73     Jun 02 13:10:38 2014 ethpm_syslogs.log
 205691   Jun 02 13:11:38 2014 ethpm_tech.log
   4096   Oct 29 17:02:38 2013 fcoe_vdcl/
 819200   Jun 02 13:15:17 2014 hap_reset_show_tech.gz
12465596   Jun 30 13:29:36 2014 ipqosmgr
12335635   May 06 18:12:50 2014 ipqosmgr1
```

```

36426752 Jun 05 12:20:14 2014 kick_628_14.bin
36226560 Jun 09 16:17:07 2014 kick_629_s4.bin
12763786 May 13 17:54:24 2014 lc2dce_mds.bin
4096 May 14 13:29:55 2014 lost+found/
6442141 Oct 09 14:25:48 2013 m9700-s3-epld.6.2.7.BF.0.9.gimg
37011968 Apr 30 16:10:28 2014 m9700-sf3ek9-kickstart-mzg.6.2.7.bin
36423680 Apr 16 16:17:50 2014 m9700-sf3ek9-kickstart-mzg.6.2.9.FM.0.48.bin
36427264 May 22 11:27:11 2014 m9700-sf3ek9-kickstart-mzg.6.2.9.FM.0.68.bin
195875124 Apr 30 12:55:14 2014 m9700-sf3ek9-mzg.6.2.7.bin
2675 Jun 02 16:30:33 2014 pc_pfc.cfg
3356 Jun 02 16:03:48 2014 pc_pfc_ld.cfg
3287 Jun 02 12:23:36 2014 pfc_ld.cfg
197137263 Jun 20 13:44:00 2014 sys_629_s4_v3.bin
197134994 Jun 20 15:41:53 2014 sys_629_s4_v4.bin
46425962 May 26 13:18:17 2014 tech_support_xbow
46710118 May 26 13:57:44 2014 tech_support_xbow1
10087076 Jan 07 13:59:41 2014 techsupport_621
7647107 Jan 07 10:47:13 2014 techsupport_January
10609173 Jan 07 14:52:30 2014 temp_1
1051 Mar 05 12:54:24 2014 vimrc-cpy

```

```

Usage for bootflash://sup-local
2468593664 bytes used
1272250368 bytes free
3740844032 bytes total

```

- Step 9** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```

switch# del m9700-sf3ek9-kickstart-mzg.6.2.7.bin
switch# del m9700-sf3ek9-mzg.6.2.7.bin

```

- Step 10** Verify that there is space available on the standby supervisor module bootflash on a Cisco MDS 9700 Series switch.

```

switch# attach mod x (where x is the module number of the standby supervisor)
switch(standby)# dir bootflash:
12288 Aug 26 19:06:14 2011 lost+found/
16206848 Jul 01 10:54:49 2011 m9500-sf2ek9-kickstart-mz.6.2.5.bin
16604160 Jul 01 10:20:07 2011 m9500-sf2ek9-kickstart-mz.6.2.5c.bin
78337129 Jul 01 10:33:52 2011 m9500-sf2ek9-mz.6.2.1.bin
78718938 Jul 01 10:18:09 2011 m9500-sf2ek9-mz.6.2.1c.bin

```

```

Usage for bootflash://sup-local
122811392 bytes used
61748224 bytes free
184559616 bytes total

```

```

switch(standby)# exit (to return to the active supervisor)

```

- Step 11** If you need more space on the standby supervisor module bootflash on a Cisco MDS 9500 Series switch, delete unnecessary files to make space available.

```

switch(standby)# del bootflash: m9700-sf2ek9-kickstart-mz.6.2.5.bin.S68
switch(standby)# del m9700-sf3ek9-mz.6.2.5.bin.S68

```

- Step 12** Access the Software Download Center using this URL:

<http://www.cisco.com/cisco/software/navigator.html>

If prompted to log in, use your Cisco system user ID and password.

- Step 13** Select the required Cisco MDS NX-OS Release 6.2(x) image file, depending on which you are installing. You see the Technical Support Encryption Software Export Distribution Authorization form.

- Step 14** Complete the required forms to obtain authorization.
- Step 15** Download the files to an FTP or TFTP server.
- Step 16** Copy the Cisco MDS NX-OS kickstart and system images to the active supervisor module bootflash using FTP or TFTP.



Note When you download an image file, change to your FTP environment IP address or DNS name and the path where the files are located.

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9700-sf3ek9-kickstart-mzg.6.2.9.FM.0.48.bin
bootflash:m9700-sf3ek9-kickstart-mzg.6.2.9.FM.0.48.bin
switch# copy tftp://tftpserver.cisco.com/MDS/m9700-sf3ek9-mzg.6.2.9.FM.0.48.bin
bootflash:m9700-sf3ek9-mzg.6.2.9.FM.0.48.bin
```

- Step 17** Verify that the switch is running the required software version by issuing the **show version** command.

```
switch# show version
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents:
http://www.cisco.com/en/US/products/ps9372/tsd_products_support_series_home.html
Copyright (c) 2002-2014, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained in this software are
owned by other third parties and used and distributed under
license. Certain components of this software are licensed under
the GNU General Public License (GPL) version 2.0 or the GNU
Lesser General Public License (LGPL) Version 2.1. A copy of each
such license is available at
http://www.opensource.org/licenses/gpl-2.0.php and
http://www.opensource.org/licenses/lgpl-2.1.php
```

```
Software
  BIOS:          version 3.1.0
  kickstart:    version 6.2(7)
  system:       version 6.2(7)
  BIOS compile time:      02/27/2013
  kickstart image file is: bootflash:///m9700-sf3ek9-kickstart-mz.6.2.7.bin
  kickstart compile time: 3/12/2014 18:00:00 [03/30/2014 08:33:12]
  system image file is:   bootflash:///m9700-sf3ek9-mz.6.2.7.bin
  system compile time:    3/12/2014 18:00:00 [03/30/2014 10:17:03]
```

```
Hardware
  cisco MDS 9710 (10 Slot) Chassis ("Supervisor Module-3")
  Intel(R) Xeon(R) CPU          with 8120776 kB of memory.
  Processor Board ID JAE1717064T
```

```
Device name: switch
bootflash:   3915776 kB
slot0:      0 kB (expansion flash)
```

Kernel uptime is 0 day(s), 19 hour(s), 43 minute(s), 39 second(s)

Last reset at 254895 usecs after Sun Mar 30 12:49:01 2014

```
Reason: Reset triggered due to Switchover Request by User
System version: 6.2(7)
Service: SAP(93): Swover due to install
```

```
plugin
  Core Plugin, Ethernet Plugin
```

Step 18 Verify that your switch is running compatible hardware. Refer to the specific version of the [Cisco MDS 9000 Family Release Notes](#).

Step 19 Perform the upgrade by issuing the **install all** command.

The following example displays the result of the **install all** command if the system and kickstart files are specified locally. The example shows the command issued on an MDS 9700 Series switch.

```
switch# install all kickstart bootflash:m9700-sf3ek9-kickstart-mz.6.2.9.bin system
bootflash:m9700-sf3ek9-mz.6.2.9.bin
```

Installer will perform compatibility check first. Please wait.

```
Verifying image bootflash:/m9700-sf3ek9-kickstart-mz.6.2.9.bin for boot variable
"kickstart".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/m9700-sf3ek9-mz.6.2.9.bin for boot variable "system".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image type.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "slc4xb" version from image bootflash:/m9700-sf3ek9-mz.6.2.9.bin.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "bios" version from image bootflash:/m9700-sf3ek9-mz.6.2.9.bin.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "system" version from image bootflash:/m9700-sf3ek9-mz.6.2.9.bin.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "kickstart" version from image bootflash:/m9700-sf3ek9-kickstart-mz.6.2.9.bin.
```

```
[#####] 100% -- SUCCESS
```

Performing module support checks.

```
Modules <          > are not supported in target image.
Please, power down the modules before proceeding.
```

```
.
```

```
Modules <          > are not supported in target image.
Please, power down the modules before proceeding.
```

```
Modules <> are not supported in target image.
Please, power down the modules before proceeding.
```

```
.
```

```
[#####] 100% -- SUCCESS
```

Notifying services about system upgrade.

```
[#####] 100% -- SUCCESS
```

Compatibility check is done:

Module	bootable	Impact	Install-type	Reason
1	yes	non-disruptive	rolling	
5	yes	non-disruptive	reset	
6	yes	non-disruptive	reset	
9	yes	non-disruptive	rolling	

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version
Upg-Required			

1	slc4xb	6.2(1)	6.2(9)
yes			
1	bios	v1.10.21(11/26/12): v1.10.21(11/26/12)	v1.10.21(11/26/12)
no			
5	system	6.2(1)	6.2(9)
yes			
5	kickstart	6.2(1)	6.2(9)
yes			
5	bios	v3.1.0(02/27/2013):v3.1.0(02/27/2013)	v3.1.0(02/27/2013)
no			
6	system	6.2(1)	6.2(9)
yes			
6	kickstart	6.2(1)	6.2(9)
yes			
6	bios	v3.1.0(02/27/2013):v3.1.0(02/27/2013)	v3.1.0(02/27/2013)
no			
9	slc4xb	6.2(1)	6.2(9)
yes			
9	bios	v1.10.21(11/26/12): v1.10.21(11/26/12)	v1.10.21(11/26/12)
no			

Additional info for this installation:

 Modules < > are not supported in target image.
 Please, power down the modules before proceeding.

Modules <> are not supported in target image.
 Please, power down the modules before proceeding.

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.
 [#####] 100% -- SUCCESS

Syncing image bootflash:/m9700-sf3ek9-kickstart-mz.6.2.9.bin to standby.
 [#####] 100% -- SUCCESS

Syncing image bootflash:/m9700-sf3ek9-mz.6.2.9.bin to standby.
 [#####] 100% -- SUCCESS

Setting boot variables.
 [#####] 100% -- SUCCESS

Performing configuration copy.
 [#####] 100% -- SUCCESS

Module 1: Refreshing compact flash and upgrading bios/loader/bootrom.
 Warning: please do not remove or power off the module at this time.
 [#####] 100% -- SUCCESS

Module 5: Refreshing compact flash and upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.
 [#####] 100% -- SUCCESS

Module 6: Refreshing compact flash and upgrading bios/loader/bootrom.
 Warning: please do not remove or power off the module at this time.
 [#####] 100% -- SUCCESS

Module 9: Refreshing compact flash and upgrading bios/loader/bootrom.
 Warning: please do not remove or power off the module at this time.
 [#####] 100% -- SUCCESS
 2014 Jun 30 11:55:50 switch %\$ VDC-1 %\$ %PLATFORM-2-MOD_REMOVE: Module 6 removed (Serial number JAE171008AY)
 2014 Jun 30 11:58:01 switch %\$ VDC-1 %\$ %USBHSD-STANDBY-2-MOUNT: logflash: online

Module 6: Waiting for module online.
 -- SUCCESS

Notifying services about the switchover.
 [#####] 100% -- SUCCESS

"Switching over onto standby".
 [1811.402498] writing reset reason 7, SAP(93): Swover due to install



Note At this point, the standby supervisor reboots.

```

NX7k SUP BIOS version ( 3.01 ) : Build - 02/26/2013 14:16:20
PM FPGA Version : 0x00000013
Power sequence microcode revision - 0x00000001 : card type - f10156EEA0
Booting Spi Flash : Primary
  CPU Signature - 0x000106e4: Version - 0x000106e0
  CPU - 1 : Cores - 4 : HTEn - 1 : HT - 2 : Features - 0xbfebfbff
  FSB Clk - 532 Mhz : Freq - 2150 Mhz - 2128 Mhz
  MicroCode Version : 0x00000002
  Memory - 8192 MB : Frequency - 1067 MHZ
  Loading Bootloader: Done
  IO FPGA Version : 0x10001
  PLX Version : 861910b5
Bios digital signature verification - Passed

Reset Reason Registers: 0x0 0x8
  Filesystem type is ext2fs, partition type 0x83
    
```

GNU GRUB version 0.97

```

Autobooting bootflash:/m9700-sf3ek9-kickstart-mz.6.2.9.bin bootflash:/m9700-sf3
ek9-mz.6.2.9.bin...
  Filesystem type is ext2fs, partition type 0x83
Booting kickstart image: bootflash:/m9700-sf3ek9-kickstart-mz.6.2.7.bin...
.....
Kickstart digital signature verification Successful
Image verification OK
    
```

```

INIT: version 2
boot device node /dev/sda
obfl flash device node /dev/sdb
log flash device node /dev/sdc
Checking obfl filesystem.r
Checking all filesystems..r.r.r.. done.
Mounting Log Dir /logflash
    
```



```

mounting Log 0
rrLoading system software
/bootflash//m9700-sf3ek9-mz.6.2.9.bin read done
System image digital signature verification successful.
Uncompressing system image: bootflash://m9700-sf3ek9-mz.6.2.9.bin Sun Jun 30 11:57:36 UTC
2014
blogger: nothing to do.
C
..done Sun Jun 30 11:57:39 UTC 2014
Load plugins that defined in image conf: /isan/plugin_img/img.conf
Loading plugin 0: core_plugin...
num srgs 1
0: swid-core-sup3dc3mds, swid-core-sup3dc3mds
num srgs 1
0: swid-sup3dc3mds-ks, swid-sup3dc3mds-ks
INIT: Entering runlevel: 3

2014 Mar 30 11:58:01 switch %USBHSD-2-MOUNT: logflash: online

Continuing with installation, please wait

Module 6: Waiting for module online.
-- SUCCESS
2014 Jun 30 11:59:38 switch Jun 30 11:59:37 %KERN-2-SYSTEM_MSG: [ 196.786053] Switchover
started by redundancy driver - kernel
2014 Jun 30 11:59:38 switch %SYSMGR-2-HASWITCHOVER_PRE_START: This supervisor is becoming
active (pre-start phase).
2014 Jun 30 11:59:38 switch %SYSMGR-2-HASWITCHOVER_START: Supervisor 6 is becoming active.
2014 Jun 30 11:59:39 switch %SYSMGR-2-SWITCHOVER_OVER: Switchover completed.
2014 Jun 30 12:01:53 switch %USBHSD-STANDBY-2-MOUNT: logflash: online

Module 1: Non-disruptive upgrading.
[#####] 100% -- SUCCESS

Module 9: Non-disruptive upgrading.
[#####] 100% -- SUCCESS

Install has been successful.

User Access Verification
switch login:

```

If the configuration meets all guidelines when the **install all** command is issued, all modules (supervisor and switching) are upgraded.

Open a new terminal session to view the upgraded supervisor module using the **show module** command. Refer to the “Managing Modules” chapter in the *Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide*.

```

switch# show module
Mod  Ports  Module-Type                Model                Status
---  ---
1    48     10 Gbps FCoE Module        DS-X9848-480K9      ok
3    48     2/4/8/10/16 Gbps Advanced FC Module DS-X9448-768K9      ok
5    0      Supervisor Module-3        DS-X97-SF1-K9       active *
6    0      Supervisor Module-3        DS-X97-SF1-K9       ha-standby

Mod  Sw          Hw
---  ---
1    6.2(9)     0.110
3    6.2(9)     1.1
5    6.2(9)     1.0
6    6.2(9)     1.0

```

```

Mod  MAC-Address(es)                               Serial-Num
---  -
1    84-78-ac-1b-7f-90 to 84-78-ac-1b-7f-c3      JAF1718AAAP
3    0c-68-03-28-0d-b4 to 0c-68-03-28-0d-b7      JAE172009W3
5    1c-df-0f-78-d5-98 to 1c-df-0f-78-d5-aa      JAE1714009H
6    0c-68-03-28-6e-b1 to 0c-68-03-28-6e-c3      JAE17240CP3

Mod  Online Diag Status
---  -
1    Pass
3    Pass
5    Pass
6    Pass

Xbar  Ports  Module-Type                Model                Status
---  -
1    0      Fabric Module 1            DS-X9710-FAB1       ok
2    0      Fabric Module 1            DS-X9710-FAB1       ok
3    0      Fabric Module 1            DS-X9710-FAB1       ok

Xbar  Sw          Hw
---  -
1    NA          1.1
2    NA          1.1
3    NA          1.1

switch#

```

You have now upgraded the Cisco MDS NX-OS software in your existing switch.

Upgrading to Cisco NX-OS Release 6.2(x) on an MDS 9500 Series Switch



Note

Use the console connection for firmware upgrades. Be aware that if you are upgrading through the management interface, you must have a working connection to both supervisors, as this process causes a switchover and the current standby supervisor will be active after the upgrade

To upgrade your switch to use the latest Cisco MDS NX-OS software on your Cisco MDS 9500 Series switch, follow these steps:

Step 1

Log in to Cisco.com to access the links provided in this document. To log in to Cisco.com, go to the URL <http://www.cisco.com/> and click **Log In** at the top of the page. Enter your Cisco Systems user name and password.



Note

Unregistered Cisco.com users cannot access the links provided in this document.

Step 2

Verify the following physical connections for the new Cisco MDS 9500 Family switch:

- The console port is physically connected to a computer terminal (or terminal server).
- The management 10/100/1000 Ethernet port (mgmt0) is connected to an external hub, switch, or router.

These procedures are specified in the hardware installation guide for the required product. Refer to the *Cisco MDS 9000 Family Hardware Installation Guides* to obtain more information.

- Step 3** Log in to the switch.
- Step 4** Issue the **copy running-config startup-config** command to store your current running configuration. You can also create a backup of your existing configuration to a file by issuing the **copy running-config bootflash:backup_config.txt** command. Refer to the “Using the Cisco NX-OS Setup Utility” chapter in the *Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide*.
- Step 5** Verify that the requested license files installed in the switch are displayed in response to the **show license usage** command.



Note The switch is initially shipped with the required licenses installed in the system; however, the initial license file will not cover unlicensed features that may be used during the grace period. Refer to the *Cisco MDS 9000 Family NX-OS Licensing Guide*. If no license is displayed at this point, perform **Step 6** and **Step 7** to install the required licenses. If the required licenses are displayed at this point, skip **Step 6** and **Step 7** and move to **Step 8**.

The example CLI output for a valid license follows:

```
switch# show license usage
Feature                Insta License Status Expiry Date Comments
                    lled Count
-----
FM_SERVER_PKG          Yes      -   Unused never      -
MAINFRAME_PKG          Yes      -   Unused never      -
ENTERPRISE_PKG         Yes      -   In use never       -
SAN_EXTN_OVER_IP       Yes      1   Unused never       -
-----
```

The example CLI output for licenses with expiring grace periods follows:

```
switch# show license usage
Feature                Insta License Status Expiry Date Comments
                    lled Count
-----
FM_SERVER_PKG          No       -   In use              Grace Period 78days 5hrs
MAINFRAME_PKG          No       -   Unused              -
ENTERPRISE_PKG         No       -   In use              Grace Period 88days 5hrs
SAN_EXTN_OVER_IP       No       0   Unused              -
-----
```

- Step 6** Install licenses (if necessary) to ensure that the required features are available on the switch. Perform the following steps:

- a. Use the **show license host-id** command to obtain the serial number for your switch. The host ID is also referred to as the switch serial number.

```
switch# show license host-id
License hostid: VDH=FOX064317SQ
```



Tip Use the entire ID that appears after the colon (:) sign. In this example, the host ID is VDH=FOX064317SQ

- b. Obtain your Claim Certificate or the Proof of Purchase document. This document accompanies every Cisco MDS switch.

- c. Locate the Product Authorization Key (PAK) from the Claim Certificate or Proof of Purchase document.
- d. Locate the website URL from the Claim Certificate or Proof of Purchase document.
- e. Access the specified URL that applies to your switch and enter the switch serial number and the PAK. The license key file is sent to you by e-mail. The license key file is digitally signed to only authorize use on the switch for which it was requested. The requested features are also enabled once the NX-OS software on the specified switch accesses the license key file.



Caution Install the license file in the specified Cisco MDS 9000 Family switch without making any modifications.

Refer to the [Cisco MDS 9000 Family NX-OS Licensing Guide](#).

Step 7 Install the license key file when you receive it by e-mail. Perform the following steps:

- a. Copy the license file to bootflash using TFTP or SCP.
- b. Perform the installation by issuing the **install license** command on the active supervisor module from the switch console.

```
switch# install license bootflash:license_file.lic
Installing license ..done
```



Note If you provide a target name for the license key file, the file is installed with the specified name. Otherwise, the file name specified in the license key file is used to install the license.

- c. Exit the switch console.

Refer to the [Cisco MDS 9000 Family NX-OS Licensing Guide](#).

Step 8 Ensure that the required space is available in the bootflash: directory for the image file(s) to be copied using the **dir bootflash:** command. Use the **delete bootflash:filename** command to remove unnecessary files.



Note Before downloading and installing Cisco NX-OS software, verify that the release is supported by your Cisco System MDS reseller. If you purchased support through a Cisco Systems reseller, contact them directly for more information. Otherwise, contact Cisco Technical support at this URL: http://www.cisco.com/en/US/support/tsd_cisco_worldwide_contacts.html.

```
switch# dir bootflash:
290   Nov 12 03:16:15 2013  MDS20131111221034113.lic
11361  Feb 05 06:14:55 2014  ioa
      290   Nov 12 03:17:46 2013  ioa_18_4.lic
21049856 Dec 02 05:47:40 2013  kick_s46
      49152  Feb 03 06:50:00 2014  lost+found/
      1968553 Sep 23 09:30:04 2013  m9500-sf2ek9-dplug-mzg.5.2.6b.bin
      1912246 Sep 02 10:40:58 2013  m9500-sf2ek9-dplug-mzg.6.2.5.bin
      1912440 Nov 17 18:01:45 2013  m9500-sf2ek9-dplug-mzg.6.2.7.FM.0.18.bin.S
21049344 Feb 05 08:58:34 2014  m9500-sf2ek9-kickstart-mz-npe.6.2.5.bin
21049344 Jan 31 07:53:54 2014  m9500-sf2ek9-kickstart-mz.6.2.5.bin
20973056 Feb 03 05:13:24 2014  m9500-sf2ek9-kickstart-mz.6.2.6.27.bin
20972032 Feb 03 06:45:38 2014  m9500-sf2ek9-kickstart-mz.6.2.6.32.bin
171299932 Feb 05 09:01:31 2014  m9500-sf2ek9-mz-npe.6.2.5.bin
171301634 Jan 31 07:55:25 2014  m9500-sf2ek9-mz.6.2.5.bin
172971570 Feb 03 05:18:23 2014  m9500-sf2ek9-mz.6.2.6.27.bin
172989526 Feb 03 06:47:53 2014  m9500-sf2ek9-mz.6.2.6.32.bin
```

```

102339   Feb 05 09:11:08 2014   mts.log
28940    Nov 25 03:38:32 2013   new
8453     Nov 25 09:27:26 2013   span.log

```

```
Usage for bootflash://sup-local
```

```
Usage for bootflash://sup-local
122811392 bytes used
61748224 bytes free
184559616 bytes total
```

- Step 9** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# del m9500-sf2ek9-kickstart-mz.6.2.6.27.bin
switch# del m9500-sf2ek9-mz-npe.6.2.5.bin
```

- Step 10** Verify that there is space available on the standby supervisor module bootflash on a Cisco MDS 9500 Series switch.

```
switch# attach mod x ( where x is the module number of the standby supervisor )
switch(standby)# dir bootflash:
12288      Aug 26 19:06:14 2011 lost+found/
16206848   Jul 01 10:54:49 2011 m9500-sf2ek9-kickstart-mz.6.2.5.bin
16604160   Jul 01 10:20:07 2011 m9500-sf2ek9-kickstart-mz.6.2.5c.bin
78337129   Jul 01 10:33:52 2011 m9500-sf2ek9-mz.6.2.1.bin
78718938   Jul 01 10:18:09 2011 m9500-sf2ek9-mz.6.2.1c.bin
```

```
Usage for bootflash://sup-local
122811392 bytes used
61748224 bytes free
184559616 bytes total
```

```
switch(standby)# exit ( to return to the active supervisor )
```

- Step 11** If you need more space on the standby supervisor module bootflash on a Cisco MDS 9500 Series switch, delete unnecessary files to make space available.

```
switch(standby)# del bootflash: m9500-sf2ek9-kickstart-mz.6.2.5.bin
switch(standby)# del bootflash:m9500-sf2ek9-mz.6.2.5.bin
```

- Step 12** Access the Software Download Center using this URL:

<http://www.cisco.com/cisco/software/navigator.html>

If prompted to log in, use your Cisco system user ID and password.

- Step 13** Select the required Cisco MDS NX-OS Release 6.2(x) image file, depending on which you are installing. You see the Technical Support Encryption Software Export Distribution Authorization form.

- Step 14** Complete the required forms to obtain authorization.

- Step 15** Download the files to an FTP or TFTP server.

- Step 16** Copy the Cisco MDS NX-OS kickstart and system images to the active supervisor module bootflash using FTP or TFTP.



Note When you download an image file, change to your FTP environment IP address or DNS name and the path where the files are located.

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-kickstart-mz.6.2.x.bin
bootflash:m9500-sf2ek9-kickstart-mz.6.2.x.bin
```

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-mz.6.2.x.bin
bootflash:m9500-sf2ek9-mz.6.2.x.bin
```

Step 17 Verify that the switch is running the required software version by issuing the **show version** command.

```
switch# show version
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents: http://www.cisco.com/en/US/products/ps9372/tsd_products_support_series_home.html
Copyright (c) 2002-2013, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software are covered under the GNU Public
License. A copy of the license is available at
http://www.gnu.org/licenses/gpl.html.
```

```
Software
  BIOS:          version 1.0.10
  loader:        version N/A
  kickstart:     version 6.2(5)
  system:        version 6.2(5)
  BIOS compile time:    01/08/09
  kickstart image file is: bootflash:///m9500-sf2ek9-kickstart-mz.6.2.5.bin
  kickstart compile time: 11/25/2013 9:00:00 [01/30/2014 05:33:20]
  system image file is:   bootflash:///m9500-sf2ek9-mz.6.2.5.bin
  system compile time:    11/25/2013 9:00:00 [01/30/2014 07:10:42]
```

```
Hardware
  cisco MDS 9509 (9 Slot) Chassis ("Supervisor/Fabric-2a")
  Motorola, 7447A, altivec with 2071288 kB of memory.
  Processor Board ID JAF1625BAES
```

```
Device name: switch
bootflash:   1000944 kB
slot0:      0 kB (expansion flash)
.....
```

Step 18 Verify that your switch is running compatible hardware. Refer to the specific version of the [Cisco MDS 9000 Family Release Notes](#).

Step 19 Perform the upgrade by issuing the **install all** command.

The following example displays the result of the **install all** command if the system and kickstart files are specified locally. The example shows the command issued on an MDS 9500 Series switch.

```
switch# install all kickstart m9500-sf2ek9-kickstart-mz.6.2.9.bin system
m9500-sf2ek9-mz.6.2.9.bin ssi m9000-ek9-ssi-mz.6.2.9.bin
```

```
Copying image from bootflash:/m9000-ek9-ssi-mz.6.2.9.bin to
modflash://3-1/m9000-ek9-ssi-mz.6.2.9.bin.
[#####] 100% -- SUCCESS
```

```
Copying image from bootflash:/m9000-ek9-ssi-mz.6.2.9.bin to
modflash://4-1/m9000-ek9-ssi-mz.6.2.9.bin.
[#####] 100% -- SUCCESS
```

```
Verifying image modflash://3-1/m9000-ek9-ssi-mz.6.2.9.bin for boot variable "ssi".
[#####] 100% -- SUCCESS
```

```
Verifying image modflash://4-1/m9000-ek9-ssi-mz.6.2.9.bin for boot variable "ssi".
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/m9500-sf2ek9-kickstart-mz.6.2.9.bin for boot variable
"kickstart".
[#####] 100% -- SUCCESS

Verifying image bootflash:/m9500-sf2ek9-mz.6.2.9.bin for boot variable "system".
[#####] 100% -- SUCCESS

Verifying image type.
[#####] 100% -- SUCCESS

Extracting "slcdce-mds" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "bios" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "ips16" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "l8_4" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "system" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "kickstart" version from image bootflash:/m9500-sf2ek9-kickstart-mz.6.2.5.bin.
[#####] 100% -- SUCCESS

Extracting "slc4" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc4" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc4" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Extracting "slc4" version from image bootflash:/m9500-sf2ek9-mz.6.2.9.bin.
[#####] 100% -- SUCCESS

Performing Compact Flash and TCAM sanity test.
[#####] 100% -- SUCCESS

Performing module support checks.
[#####] 100% -- SUCCESS

Notifying services about system upgrade.
[#####] 100% -- SUCCESS
```

Compatibility check is done:

Module	bootable	Impact	Install-type	Reason
1	yes	non-disruptive	rolling	
2	yes	non-disruptive	rolling	
3	yes	disruptive	rolling	Hitless upgrade is not supported
4	yes	non-disruptive	rolling	
6	yes	non-disruptive	rolling	
7	yes	non-disruptive	reset	
8	yes	non-disruptive	reset	
9	yes	non-disruptive	rolling	
10	yes	non-disruptive	rolling	
11	yes	non-disruptive	rolling	
12	yes	non-disruptive	rolling	
13	yes	non-disruptive	rolling	

Other miscellaneous information for installation:

Module	info
3	Hitless upgrade is not supported
4	FC ports 1-18 are hitless, GigE 1-4 are hitful, and Intelligent Applications running are hitful

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version
1	slcdce-mds	5.2(8b)	6.2(9)
yes			
1	bios	v1.10.21(11/26/12) : v1.10.21(11/26/12)	v1.10.21(11/26/12)
no			
2	slc2	5.2(8b)	6.2(9)
yes			
2	bios	v1.0.19(02/01/10) : v1.0.19(02/01/10)	v1.0.19(02/01/10)
no			
3	slc2	5.2(8b)	6.2(9)
yes			
3	ips16	5.2(8b)	6.2(9)
yes			
3	ssi	5.2(8b)	6.2(9)
yes			
3	bios	v1.0.19(02/01/10) : v1.0.19(02/01/10)	v1.0.19(02/01/10)
no			
4	slc2	5.2(8b)	6.2(9)
yes			
4	18_4	5.2(8b)	6.2(9)
yes			
4	ssi	5.2(8b)	6.2(9)
yes			
4	bios	v1.0.19(02/01/10) : v1.0.19(02/01/10)	v1.0.19(02/01/10)
no			
6	slc2	5.2(8b)	6.2(9)
yes			
6	bios	v1.0.19(02/01/10) : v1.0.19(02/01/10)	v1.0.19(02/01/10)
no			
7	system	5.2(8b)	6.2(9)
yes			
7	kickstart	5.2(8b)	6.2(9)
yes			


```

7      bios      v1.0.10(01/08/09): v1.0.10(01/08/09)  v1.0.10(01/08/09)
no
8      system                    5.2(8b)                    6.2(9)
yes
8      kickstart                  5.2(8b)                    6.2(9)
yes
8      bios      v1.0.10(01/08/09): v1.0.10(01/08/09)  v1.0.10(01/08/09)
no
9      slc4                    5.2(8b)                    6.2(9)
yes
9      bios      v1.10.21(11/26/12): v1.10.21(11/26/12)  v1.10.21(11/26/12)
no
10     slc2                    5.2(8b)                    6.2(9)
yes
10     bios      v1.0.19(02/01/10): v1.0.19(02/01/10)  v1.0.19(02/01/10)
no
11     slc4                    5.2(8b)                    6.2(9)
yes
11     bios      v1.10.21(11/26/12): v1.10.21(11/26/12)  v1.10.21(11/26/12)
no
12     slc4                    5.2(8b)                    6.2(9)
yes
12     bios      v1.10.21(11/26/12): v1.10.21(11/26/12)  v1.10.21(11/26/12)
no
13     slc4                    5.2(8b)                    6.2(9)
yes
13     bios      v1.10.21(11/26/12): v1.10.21(11/26/12)  v1.10.21(11/26/12)
no

```

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.

[#####] 100% -- SUCCESS

Syncing image bootflash:/m9500-sf2ek9-kickstart-mz.6.2.9.bin to standby.

[#####] 100% -- SUCCESS

Syncing image bootflash:/m9500-sf2ek9-mz.6.2.9.bin to standby.

[#####] 100% -- SUCCESS

Setting boot variables.

[#####] 100% -- SUCCESS

Performing configuration copy.

[#####] 100% -- SUCCESS

Module 1: Refreshing compact flash and upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

Module 2: Refreshing compact flash and upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

Module 3: Refreshing compact flash and upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

Module 4: Refreshing compact flash and upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

```

Module 6: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 7: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 8: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 9: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 10: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 11: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 12: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 13: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
2014 Jun 30 10:02:24 sw-6x-9513 %PLATFORM-2-MOD_REMOVE: Module 7 removed (Serial number
JAF1626AKKQ)

Module 7: Waiting for module online.
-- SUCCESS

Notifying services about the switchover.
[#####] 100% -- SUCCESS

"Switching over onto standby".

```



Note At this point, the standby supervisor reboots.

```

Notifying services about the switchover.
[#####] 100% -- SUCCESS
Install has been successful.

```

If the configuration meets all guidelines when the **install all** command is issued, all modules (supervisor and switching) are upgraded.

Open a new terminal session to view the upgraded supervisor module using the **show module** command. Refer to the “Managing Modules” chapter in the [Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide](#).

```

switch# show module
Mod  Ports  Module-Type                               Model                               Status
---  ---
1    32      1/2/4/8/10 Gbps Advanced FC Module     DS-X9232-256K9                     ok

```

```

2 24 1/2/4/8 Gbps FC Module DS-X9224-96K9 ok
3 22 4x1GE IPS, 18x1/2/4Gbps FC Module DS-X9304-18K9 ok
5 0 Supervisor/Fabric-2a DS-X9530-SF2AK9 active *
6 0 Supervisor/Fabric-2a DS-X9530-SF2AK9 ha-standby
7 48 1/2/4/8 Gbps FC Module DS-X9248-96K9 ok
8 48 1/2/4/8 Gbps FC Module DS-X9248-48K9 ok
9 8 10 Gbps FCoE Module DS-X9708-K9 ok

Mod Sw Hw World-Wide-Name (s) (WWN)
---
1 6.2(9) 1.1 20:01:54:7f:ee:18:66:00 to 20:20:54:7f:ee:18:66:00
2 6.2(9) 1.6 20:41:54:7f:ee:18:66:00 to 20:58:54:7f:ee:18:66:00
3 6.2(9) 1.7 20:81:54:7f:ee:18:66:00 to 20:92:54:7f:ee:18:66:00
5 6.2(9) 1.4 --
6 6.2(9) 1.4 --
7 6.2(9) 1.6 21:81:54:7f:ee:18:66:00 to 21:b0:54:7f:ee:18:66:00
8 6.2(9) 1.6 21:c1:54:7f:ee:18:66:00 to 21:f0:54:7f:ee:18:66:00
9 6.2(9) 0.109 --

Mod MAC-Address (es) Serial-Num
---
1 50-3d-e5-9e-f2-f8 to 50-3d-e5-9e-f2-fb JAF1539CEQS
2 c8-4c-75-b1-64-04 to c8-4c-75-b1-64-07 JAF1550CCHS
3 00-0d-ec-77-54-dc to 00-0d-ec-77-54-e3 JAF1625BDKN
5 c8-9c-1d-41-a1-ec to c8-9c-1d-41-a1-ef JAF1625BAES
6 d0-d0-fd-1d-e0-58 to d0-d0-fd-1d-e0-5b JAF1625BAET
7 00-0d-ec-77-4c-d8 to 00-0d-ec-77-4c-db JAF1624ASAS
8 c8-4c-75-b1-3d-98 to c8-4c-75-b1-3d-9b JAF1549BMSF
9 68-ef-bd-a8-39-0c to 68-ef-bd-a8-39-1f JAF1444AGNQ

```

You have now upgraded the Cisco MDS NX-OS software in your existing switch.

Upgrading to Cisco NX-OS Release 6.2(9) on the MDS 9250i Switch

To upgrade to Cisco NX-OS Release 6.2(7) on an Cisco MDS 9250i switch, follow these steps:

- Step 1** Verify that the system image files for the upgrade are present on the active supervisor module bootflash:.

```

switch# dir bootflash:
 4096 Jan 12 09:05:55 2001 .partner/
   692 Feb 06 18:22:33 2001 abc.lic
2155240 Apr 17 10:18:30 2001 d
2155240 Mar 21 15:33:26 2014 d1
2155240 Mar 18 10:15:41 2014 dplug627
20090368 Apr 06 05:25:31 2001 m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
20044800 Mar 30 15:42:05 2014 m9250-s5ek9-kickstart-mz.6.2.5.bin
107197681 Apr 06 05:26:53 2001 m9250-s5ek9-mz.6.2.5.bin.S68
107587249 Mar 30 15:42:52 2014 m9250-s5ek9-mz.6.2.5.bin
   29714 Mar 30 16:20:21 2014 mts.log
2855303 Mar 30 14:14:36 2014 runn-fc
2855147 Mar 26 15:05:30 2014 runn-mar26
2777996 Mar 27 07:07:46 2014 runn-mar27
2855147 Mar 27 04:51:08 2014 runn-mar27-preRel
2777996 Mar 27 06:22:29 2014 runn-mar27-preRel-wozone

Usage for bootflash://sup-local
236338292 bytes used

```

```
142984076 bytes free
379322368 bytes total
```

- Step 2** If the software image file is not present, download it from an FTP or TFTP server to the active supervisor module bootflash: . You can obtain the software image file from the Cisco.com software download center at the following URL: <http://www.cisco.com/cisco/software/navigator.html>



Note If you need more space on the active supervisor module bootflash:, use the **delete** command to remove unnecessary files and follow [Step 3](#) and [Step 4](#).

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9250-s5ek9-kickstart-mz.6.2.9.bin
bootflash:m9250-s5ek9-kickstart-mz.6.2.9.bin
switch# copy tftp://tftpserver.cisco.com/MDS/m9250-s5ek9-mz.6.2.9.bin
bootflash:m9250-s5ek9-mz.6.2.9.bin
```

- Step 3** Ensure that the required space is available on the active supervisor.

```
switch# dir bootflash:
096 Jan 12 09:05:55 2001 .partner/
692 Feb 06 18:22:33 2001 abc.lic
2155240 Apr 17 10:18:30 2001 d
2155240 Mar 21 15:33:26 2014 d1
2155240 Mar 18 10:15:41 2014 dplug627
20090368 Apr 06 05:25:31 2001 m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
20044800 Mar 30 15:42:05 2014 m9250-s5ek9-kickstart-mz.6.2.7.bin
107197681 Apr 06 05:26:53 2001 m9250-s5ek9-mz.6.2.5.bin.S68
107587249 Mar 30 15:42:52 2014 m9250-s5ek9-mz.6.2.7.bin
29714 Mar 30 16:20:21 2014 mts.log

Usage for bootflash://sup-local
120695976 bytes used
63863640 bytes free
184559616 bytes total
```

- Step 4** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# del bootflash:m9250-s5ek9-kickstart-mz.6.2.5.bin.S60
switch# del bootflash:m9250-s5ek9-kickstart-mz.6.2.5.bin.S16
```

- Step 5** Save the configuration using the **copy running-config startup-config** command.

```
switch# copy running-config startup-config
```

You can also create a backup of your existing configuration to a file by issuing the **copy running-config bootflash:backup_config.txt** command. You might want to add a date reference to the .txt file name to identify the file at a later date.

- Step 6** Perform the upgrade by issuing the **install all** command.

```
switch# install all kickstart bootflash:m9250-s5ek9-kickstart-mz.6.2.9.bin system
bootflash:m9250-s5ek9-mz.6.2.9.bin
Installer will perform compatibility check first. Please wait.

Verifying image bootflash:/m9250-s5ek9-kickstart-mz.6.2.9.bin for boot variable
"kickstart".
[#####] 100% -- SUCCESS

Verifying image bootflash:/m9250-s5ek9-mz.6.2.9.bin for boot variable "system".
[#####] 100% -- SUCCESS

Verifying image type.
```

```

##### 100% -- SUCCESS

Extracting "system" version from image bootflash:/m9250-s5ek9-mz.6.2.9.bin.
##### 100% -- SUCCESS

Extracting "kickstart" version from image
bootflash:/m9250-s5ek9-kickstart-mz.6.2.9.bin.
##### 100% -- SUCCESS

Extracting "bios" version from image bootflash:/m9250-s5ek9-mz.6.2.9.bin.
##### 100% -- SUCCESS

Performing Compact Flash and TCAM sanity test.
##### 100% -- SUCCESS

Performing module support checks.
##### 100% -- SUCCESS

Notifying services about system upgrade.
##### 100% -- SUCCESS

```

```

Compatibility check is done:
Module  bootable          Impact  Install-type  Reason
-----  -
1       yes  non-disruptive          reset

```

```

Other miscellaneous information for installation:
Module  info
-----  -

```

```

1 FC ports 1-40 and FCoE ports 1-8 are hitless, IPS 1-2 are hitful, and
Intelligent Applications running are hitful

```

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version
Upg-Required			
1	system	6.2(5)	6.2(7)
yes			
1	kickstart	6.2(5)	6.2(7)
yes			
1	bios	v2.1.16(10/24/13):v2.1.16(10/24/13)	v2.1.16(10/24/13)
no			

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

```

Performing runtime checks.
##### 100% -- SUCCESS

```

```

Notifying services about the upgrade.
##### 100% -- SUCCESS

```

```

Setting boot variables.
##### 100% -- SUCCESS

```

```

Performing configuration copy.
##### 100% -- SUCCESS

```

Module 1: Refreshing compact flash and Upgrading bios/loader/bootrom.
 Warning: please do not remove or power off the module at this time.
 [#####] 100% -- SUCCESS

Upgrade can no longer be aborted, any failure will result in a disruptive upgrade.

Freeing memory in the file system.
 [#####] 100% -- SUCCESS

Loading images into memory.
 [#####] 100% -- SUCCESS

Saving linecard runtime state.
 [#####] 100% -- SUCCESS

Saving supervisor runtime state.
 [#####] 100% -- SUCCESS

Saving mts state.
 [#####] 100% -- SUCCESS

Rebooting the switch to proceed with the upgrade.
 All telnet and ssh connections will now be temporarily terminated.

>> NX7--LC-loader-02.01.16 (Oct 24 2013 - 16:00:49), Build: 02.01.16

CPU0: 8572E, Version: 2.1, (0x80e80021)
 Core: E500, Version: 3.0, (0x80210030)
 Clock Configuration:
 CPU:1066.672 MHz, CCB:533.336 MHz,
 DDR:266.668 MHz (533.336 MT/s data rate), LBC:33.334 MHz
 L1: D-cache 32 kB enabled
 I-cache 32 kB enabled
 Board: 9044, IOFPGA: 0x0000001A, SPROM: 0xAB
 Boot flash : Primary
 I2C: ready
 DRAM: Initializing
 DDR: dimm type 10, registered 1
 DDR: dimm type 10, registered 1
 DDR: 4 GB
 L2: 1024 KB enabled
 Using default environment

In: serial
 Out: serial
 Err: serial
 Net: INFO: Net boot mode = 1
 INFO: Net boot mode = 1
 INFO: Board will come up MGMT interface
 INFO: MAC address is: cc:fe:48:4a:5d:f0
 eTSEC2 board phy 3
 INFO: Net boot mode = 1
 eTSEC2
 IDE: Bus 0: OK
 Device 0: Model: SILICONSYSTEMS UDMA 4GB-4676 Firm: 3.38 Ser#:
 CC395293055000066K08
 Type: Hard Disk
 Capacity: 3919.7 MB = 3.8 GB (8027712 x 512)

Booting image bootflash://m9250-s5ek9-kickstart-mz.6.2.9.bin
 20044800 bytes read
 NBI at 08000000 size 134217728

```

Booting image at addr 0x00800000 ...
Memory <- <0x0 0x0 0x1 0x0> (4096MB)
ethernet0: local-mac-address <- cc:fe:48:4a:5d:f0
ethernet1: local-mac-address <- 00:e0:0c:00:01:fd
ethernet2: local-mac-address <- 00:e0:0c:00:02:fd
CPU clock-frequency <- 0x3f941f80 (1067MHz)
CPU timebase-frequency <- 0x3f941f8 (67MHz)
CPU bus-frequency <- 0x1fca0fc0 (533MHz)

zImage starting: loaded at 0x00800000 (sp: 0x7fedc4d0)
Allocating 0x4d9464 bytes for kernel ...
gunzipping (0x00000000 <- 0x0080f000:0x00ca3b94)...done 0x47a774 bytes
Using loader supplied ramdisk at 0x2700000-0x381de00
initrd head: 0x1f8b0808

Linux/PowerPC load: rw root=/dev/ram0 rdbase=0x7000000 card_index=9044 maxcpus=2
ip=off ramdisk_size=262144 noquiet obfl_type_ide=1 kgdboc=ttyS0,9600,B
softlockup_panic=1 isanimg_loc=0x6000000 isanimg_size=0x400 console=ttyS0,9600n8nn
loader_ver="02.01.16" card_index=9044 quiet bootdev=ide0 server_ip=171.69.21.28
ksimg=/m9250-s5ek9-kickstart-mz.6.2.9.bin isanimg=/m9250-s5ek9-mz.6.2.9.bin
Finalizing device tree... flat tree at 0x80be70
Jumping to kernel at 0
setup_arch: bootmem
mpc85xx_ds_setup_arch()
arch: exit

[ 1.523129] Host controller irq 26
[ 1.564310] pci 0000:00:00.0: ignoring class b20 (doesn't match header type 01)
[ 1.682586] Assign root port irq 26 for 0000:00:00.0
[ 2.013349] Enabling all PCI devices
INIT: Checking all filesystems..... done.
Setting kernel variables done.
Setting the System Clock using the Hardware Clock as reference...System Clock set.
Local time: Sun Mar 30 16:19:10 UTC 2014
Loading system software
Uncompressing system image: bootflash:///m9250-s5ek9-mz.6.2.9.bin
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
Load plugins that defined in image conf: /isan/plugin_img/img.conf
Loading plugin 0: core_plugin...
num srgs 1
0: swid-core-s5ek9, swid-core-s5ek9
num srgs 1
0: swid-sup-ali-ks, swid-sup-ali-ks
INIT: Entering runlevel: 3

[ 82.969865] clpk_hw_init_1:Post ISSU instance 0 status 0x00000736 GOOD
[ 83.048376] clpk_hw_init_1:Post ISSU instance 1 status 0x00000536 GOOD
2014 Mar 30 16:20:14 switch Mar 30 16:20:14 %KERN-0-SYSTEM_MSG: [ 2.013349]
Enabling all PCI devices - kernel
2014 Mar 30 16:20:14 switch Mar 30 16:20:14 %KERN-0-SYSTEM_MSG: [ 82.969865]
clpk_hw_init_1:Post ISSU instance 0 status 0x00000736 GOOD - kernel
2014 Mar 30 16:20:14 switch Mar 30 16:20:14 %KERN-0-SYSTEM_MSG: [ 83.048376]
clpk_hw_init_1:Post ISSU instance 1 status 0x00000536 GOOD - kernel
Sysmgr failed to send GET_TIME_OF_DAY Call_cnt= 1 errno= 32
2014 Mar 30 16:20:36 switch %CARDCLIENT-2-REG: OK
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...

Continuing with installation process, please wait.

```

The login will be disabled until the installation is completed.

```
Status for linecard upgrade.
2014 Mar 30 16:21:57 switch %PLATFORM-2-PS_OK: Power supply 1 ok (Serial number
QCS1549K0HU)
2014 Mar 30 16:21:57 switch %PLATFORM-2-PS_FANOK: Fan in Power supply 1 ok
2014 Mar 30 16:21:57 switch %PLATFORM-2-PS_OK: Power supply 2 ok (Serial number
QCS1549K087)
[#####] 100% -- SUCCESS

Performing supervisor state verification.
2014 Mar 30 16:21:57 switch %PLATFORM-2-PS_FANOK: Fan in Power supply 2 ok
2014 Mar 30 16:21:57 switch %PLATFORM-2-PS_OK: Power supply 3 ok (Serial number
QCS1549K0T5)
2014 Mar 30 16:21:57 switch %PLATFORM-2-PS_FANOK: Fan in Power supply 3 ok
2014 Mar 30 16:21:57 switch %PLATFORM-2-FAN_OK_: Fan 1 ok
2014 Mar 30 16:21:57 switch %PLATFORM-2-FAN_OK_: Fan 2 ok
[#####] 100% -- SUCCESS

Install has been successful.

User Access Verification
switch#
```

Step 7 Log in to the switch.

```
MDS Switch
209.165.200.226 login: admin
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Copyright (c) 2002-2014, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained in this software are
owned by other third parties and used and distributed under
license. Certain components of this software are licensed under
the GNU General Public License (GPL) version 2.0 or the GNU
Lesser General Public License (LGPL) Version 2.1. A copy of each
such license is available at
http://www.opensource.org/licenses/gpl-2.0.php and
http://www.opensource.org/licenses/lgpl-2.1.php
```

Step 8 Issue the **show version** command.

```
switch# show version
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents:
http://www.cisco.com/en/US/products/ps9372/tsd_products_support_series_home.html
Copyright (c) 2002-2014, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software are covered under the GNU Public
License. A copy of the license is available at
http://www.gnu.org/licenses/gpl.html.

Software
  BIOS:          version 2.1.16
  loader:        version N/A
  kickstart:     version 6.2(7)
  system:        version 6.2(7)
  BIOS compile time: 10/24/13
  kickstart image file is: bootflash:///m9250-s5ek9-kickstart-mz.6.2.9.bin
  kickstart compile time: 3/12/2014 18:00:00 [03/30/2014 08:26:48]
  system image file is: bootflash:///m9250-s5ek9-mz.6.2.9.bin
  system compile time: 3/12/2014 18:00:00 [03/30/2014 10:17:45]
```



```

Hardware
  cisco MDS 9250i 40 FC 2 IPS 8 FCoE (1 Slot) Chassis ("40FC+8FCoE+2IPS Supervisor")
  Motorola, e500v2, core 0 with 4155776 kB of memory.
  Processor Board ID JAF1605AMHH

  Device name: switch
  bootflash: 4013856 kB
  Kernel uptime is 0 day(s), 16 hour(s), 25 minute(s), 53 second(s)

  Last reset at 675523 usecs after Sun Mar 30 16:18:25 2014

  Reason: Reset due to upgrade
  System version: 6.2(5)
  Service:

  plugin
  Core Plugin

switch#

```

Step 9 Verify the status of the modules on the switch using the **show module** command.

```

switch# show module
Mod  Ports  Module-Type                      Model                      Status
---  ---
 1   50     40FC+8FCoE+2IPS Supervisor    DS-C9250I-K9-SUP         active *

Mod  Sw          Hw      World-Wide-Name(s) (WWN)
---  ---
 1   6.2(7)     0.0     20:01:54:7f:ee:1b:10:20 to 20:28:54:7f:ee:1b:10:20

Mod  MAC-Address(es)                      Serial-Num
---  ---
 1   cc-fe-48-4a-5d-f0 to cc-fe-48-4a-5d-ff  JAF1605AMHH

* this terminal session
switch#

```

Upgrading to Cisco NX-OS Release 6.2(x) on the MDS 9222i Switch

To upgrade to Cisco NX-OS Release 6.2(x) on a Cisco MDS 9222i switch, follow these steps:

Step 1 Verify that the system image files for the upgrade are present on the active supervisor module bootflash:.

```

switch# dir bootflash:
 12288 Aug 26 19:06:14 2013 lost+found/
18939904 Jul 01 10:54:49 2013 m9200-sf2ek9-kickstart-mz.6.2.1.bin
16858624 Jul 01 10:20:07 2013 m9200-sf2ek9-kickstart-mz.6.2.1a.bin
101756072 Jul 01 10:33:52 2013 m9200-sf2ek9-mz.6.2.1.bin
95771404 Jul 01 10:18:09 2011 m9200-sf2ek9-mz.5.0.1a.bin

```

Usage for bootflash://sup-local

236338292 bytes used

142984076 bytes free

379322368 bytes total

- Step 2** If the software image file is not present, download it from an FTP or TFTP server to the active supervisor module bootflash:. You can obtain the software image file from the Cisco.com software download center at the following URL:

<http://www.cisco.com/cisco/software/navigator.html>



Note If you need more space on the active supervisor module bootflash:, use the **delete** command to remove unnecessary files and follow [Step 3](#) and [Step 4](#).

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9200-sf2ek9-kickstart-mz.6.2.5.bin
bootflash:m9200-sf2ek9-kickstart-mz.6.2.5.bin
switch# copy tftp://tftpserver.cisco.com/MDS/m9200-sf2ek9-mz.6.2.5.bin
bootflash:m9200-sf2ek9-mz.6.2.5.bin
```

- Step 3** Ensure that the required space is available on the active supervisor.

```
switch# dir bootflash:
12288      Aug 26 19:06:14 2011 lost+found/
18939904   Jul 01 10:54:49 2011 m9200-sf2ek9-kickstart-mz.5.2.1.bin
101756072  Jul 01 10:33:52 2011 m9200-sf2ek9-mz.5.2.1a.bin
```

Usage for bootflash://sup-local

120695976 bytes used

63863640 bytes free

184559616 bytes total

- Step 4** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# del bootflash:m9200-sf2ek9-kickstart-mz.5.2.1a.bin
switch# del bootflash:m9200-sf2ek9-mz.5.2.1a.bin
```

- Step 5** Save the configuration using the **copy running-config startup-config** command.

```
switch# copy running-config startup-config
```

You can also create a backup of your existing configuration to a file by issuing the **copy running-config bootflash:backup_config.txt** command. You might want to add a date reference to the .txt file name to identify the file at a later date.

- Step 6** Perform the upgrade by issuing the **install all** command.

```
switch# install all system bootflash:m9200-s2ek9-mz.6.2.x.bin.S74 kickstart
bootflash:m9200-s2ek9-kickstart-mz.6.2.x.bin.S74
```

```
Verifying image bootflash:/m9200-s2ek9-kickstart-mz.6.2.x.bin.S74 for boot variable
"kickstart".
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/m9200-s2ek9-mz.6.2.x.bin.S74 for boot variable "system".
[#####] 100% -- SUCCESS
```

```

Verifying image type.
#####] 100% -- SUCCESS

Extracting "system" version from image bootflash:/m9200-s2ek9-mz.6.2.x.bin.S74.
#####] 100% -- SUCCESS

Extracting "kickstart" version from image
bootflash:/m9200-s2ek9-kickstart-mz.6.2.x.bin.S74.
#####] 100% -- SUCCESS

Extracting "bios" version from image bootflash:/m9200-s2ek9-mz.6.2.x.bin.S74.
#####] 100% -- SUCCESS

Extracting "slc2" version from image bootflash:/m9200-s2ek9-mz.6.2.x.bin.S74.
#####] 100% -- SUCCESS

Performing Compact Flash and TCAM sanity test.
#####] 100% -- SUCCESS

Performing module support checks.
#####] 100% -- SUCCESS

Notifying services about system upgrade.
#####] 100% -- SUCCESS
    
```

```

Compatibility check is done:
Module  bootable          Impact  Install-type  Reason
-----  -----  -
1         yes  non-disruptive      reset
2         yes  non-disruptive      rolling
    
```

Other miscellaneous information for installation:

```

Module  info
-----  -----
1       FC ports 1-18 are hitless, GigE 1-4 are hitful, and Intelligent Applications
running are hitful
    
```

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version	Upg-Required
1	system		5.2(1) 6.2.x	yes
1	kickstart		5.2(1) 6.2.x	yes
1	bios	v1.0.19(02/01/10):	v1.0.19(02/01/10)	no
2	slc2		5.2(1) 6.2.x	yes
2	bios	v1.0.19(02/01/10):	v1.0.19(02/01/10)	no

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

```

Performing runtime checks.
#####] 100% -- SUCCESS
    
```

```

Notifying services about the upgrade.
#####] 100% -- SUCCESS
    
```

```

Setting boot variables.
#####] 100% -- SUCCESS
    
```

```

Performing configuration copy.
[#####] 100% -- SUCCESS

Module 1: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Module 2: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Upgrade can no longer be aborted, any failure will result in a disruptive upgrade.

Freeing memory in the file system.
[#####] 100% -- SUCCESS

Loading images into memory.
[#####] 100% -- SUCCESS

Saving external linecard runtime state.
2011 Aug 1 17:16:56 sw4-qa05 %IMAGE_DNLD-SLOT2-2-IMG_DNLD_STARTED: Module image download
process. Please wait until completion...
2011 Aug 1 17:17:16 sw4-qa05 %IMAGE_DNLD-SLOT2-2-IMG_DNLD_COMPLETE: Module image
download process. Download successful.
[#####] 100% -- SUCCESS

Saving linecard runtime state.
[#####] 100% -- SUCCESS

Saving supervisor runtime state.
[#####] 100% -- SUCCESS

Saving mts state.
[#####] 100% -- SUCCESS

Rebooting the switch to proceed with the upgrade.
All telnet and ssh connections will now be temporarily terminated.
Starting new kernel
Starting kernel...
  Entered kgdb_console_init:1975
INIT: version 2.85 booting
Checking all filesystems.... done.
/etc/rc.d/rcS.d/S30procps: line 34: log_action_begin_msg: command not found
/etc/rc.d/rcS.d/S30procps: line 36: log_action_end_msg: command not found
Setting the System Clock using the Hardware Clock as reference...System Clock set. Local
time: Mon Aug 1 17:17:56 PDT 2011
Loading system software
Uncompressing system image: bootflash:///m9200-s2ek9-mz.6.2.x.bin.S74
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
Uncompressing linecard components
INIT: Entering runlevel: 3
Starting NFS servers: nfsd mountd.

2011 Aug 1 17:18:22 sw4-qa05 Aug 1 17:18:22 %KERN-2-SYSTEM_MSG: Starting kernel... -
kernel
2011 Aug 1 17:18:22 sw4-qa05 Aug 1 17:18:22 %KERN-1-SYSTEM_MSG: Entered
kgdb_console_init:1975 - kernel

Continuing with installation process, please wait.
The login will be disabled until the installation is completed.
2011 Aug 1 17:19:22 sw4-qa05 %PROC_MGR-2-MESG: Entity : (dnld_image) has exited
successfully

```

```

2011 Aug 1 17:19:29 sw4-qa05 %PLATFORM-2-PS_FAIL: Power supply 1 failed or shut down
(Serial number )
2011 Aug 1 17:19:29 sw4-qa05 %PLATFORM-2-PS_OK: Power supply 2 ok (Serial number
QCS104811U3)
2011 Aug 1 17:19:29 sw4-qa05 %PLATFORM-2-PS_FANOK: Fan in Power supply 2 ok
2011 Aug 1 17:19:29 sw4-qa05 %PLATFORM-2-FAN_OK: Fan module ok
2011 Aug 1 17:19:29 sw4-qa05 %PLATFORM-2-CHASSIS_CLKMODOK: Chassis clock module A ok
2011 Aug 1 17:19:29 sw4-qa05 %PLATFORM-2-CHASSIS_CLKMODOK: Chassis clock module B ok
2011 Aug 1 17:19:29 sw4-qa05 %PLATFORM-2-CHASSIS_CLKSRC: Current chassis clock source is
clock-A

```

```

Status for linecard upgrade.
[#####] 100% -- SUCCESS

```

```

Status for external linecard upgrade.
[#####] 100% -- SUCCESS

```

```

Performing supervisor state verification.
[#####] 100% -- SUCCESS

```

Install has been successful.

Step 7 Log in to the switch.

```

MDS Switch
209.165.200.226 login: admin
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Copyright (c) 2002-2013, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained in this software are
owned by other third parties and used and distributed under
license. Certain components of this software are licensed under
the GNU General Public License (GPL) version 2.0 or the GNU
Lesser General Public License (LGPL) Version 2.1. A copy of each
such license is available at
http://www.opensource.org/licenses/gpl-2.0.php and
http://www.opensource.org/licenses/lgpl-2.1.php
switch# sh ver
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents: http://www.cisco.com/en/US/products/ps9372/tsd\_products\_support\_series\_home.html
Copyright (c) 2002-2013, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software are covered under the GNU Public
License. A copy of the license is available at
http://www.gnu.org/licenses/gpl.html.

```

Step 8 Issue the show version command.

```

switch# show version
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents: http://www.cisco.com/en/US/products/ps9372/tsd\_products\_support\_series\_home.html
Copyright (c) 2002-2014, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software are covered under the GNU Public
License. A copy of the license is available at
http://www.gnu.org/licenses/gpl.html.

Software

```

```

BIOS:      version 1.0.19
loader:    version N/A
kickstart: version 6.2(9)
system:    version 6.2(9)
BIOS compile time:      02/07/14
kickstart image file is: bootflash:///m9250-s2ek9-kickstart-mz.6.2.9.bin.S0
kickstart compile time: 2/3/2014 21:00:00 [02/04/2014 07:07:32]
system image file is:   bootflash:///m9250-s2ek9-mz.6.2.9.bin.S0
system compile time:   7/3/2014 21:00:00 [07/04/2014 08:51:15]
    
```

Hardware

```

cisco MDS 9222i ("4x1GE IPS, 18x1/2/4Gbps FC/Sup2")
Motorola, e500v2 with 1036300 kB of memory.
Processor Board ID JAF1643AQJF
    
```

```

Device name: switch
bootflash:    1000944 kB
Kernel uptime is 0 day(s), 1 hour(s), 23 minute(s), 46 second(s)
    
```

Last reset at 780927 usecs after Thu Feb 6 08:47:48 2014

```

Reason: Reset Requested by CLI command reload
System version: 6.2(5)
Service:
    
```

switch#

Step 9 Verify the status of the modules on the switch using the **show module** command.

```

switch# show module
Mod  Ports  Module-Type                Model                Status
---  ---
1    22     4x1GE IPS, 18x1/2/4Gbps FC/Sup2  DS-C9222I-K9        active *
2    48     1/2/4 Gbps FC Module           DS-X9148             ok

Mod  Sw          Hw      World-Wide-Name(s) (WWN)
---  ---
1    6.2(x)      1.0     20:01:00:0d:ec:34:82:00 to 20:12:00:0d:ec:34:82:00
2    6.2(x)      0.322   20:41:00:0d:ec:34:82:00 to 20:70:00:0d:ec:34:82:00

Mod  MAC-Address(es)                Serial-Num
---  ---
1    00-17-94-ee-1b-54 to 00-17-94-ee-1b-5c  JAE11430NJM
2    00-14-a9-74-e0-e8 to 00-14-a9-74-e0-ec  JAB093902HZ
    
```

* this terminal session

Moving From an NPE Image to a non-NPE Image and Vice Versa

The following section describes how to upgrade from a no payload encryption (NPE) image to a non-NPE image and vice versa.



Note

- If the image file name includes *npe* text, the image is an NPE image. If the image file name does not include *npe* text, the image is a non-NPE image.
- If you are moving from using an NPE image to a non-NPE image, we recommend that you use the corresponding non-NPE Cisco MDS NX-OS release image and vice versa.
If you are upgrading from one release of Cisco MDS NX-OS to a newer release, and as part of this activity, you are moving from using an NPE image to a non-NPE image, we recommended that you first upgrade the existing NPE Cisco MDS NX-OS release image and then upgrade to the respective non-NPE Cisco MDS NX-OS release image and vice versa.
- Use the console connection for firmware upgrades. Be aware that if you are upgrading through the management interface, you must have a working connection to both supervisors, as this process causes a switchover and the current standby supervisor will be active after the upgrade.

Step 1 Log in to Cisco.com to access the links provided in this document. To log in to Cisco.com, go to the URL <http://www.cisco.com/> and click **Log In** at the top of the page. Enter your Cisco Systems user name and password.



Note

Unregistered Cisco.com users cannot access the links provided in this document.

Step 2 Verify the following physical connections for the switch:

- The console port is physically connected to a computer terminal (or terminal server).
- The management 10/100/1000 Ethernet port (mgmt0) is connected to an external hub, switch, or router.
- On switches with dual supervisor modules, both supervisor modules must have the management 10/100/1000 Ethernet ports (mgmt0) connected to an external hub, switch, or router.

These procedures are specified in the hardware installation guide for the required product.

Step 3 Log in to the switch.

Step 4 Issue the **copy running-config startup-config** command to store your current running configuration. You can also create a backup of your existing configuration to a file by issuing the **copy running-config bootflash:backup_config.txt** command.

Step 5 Verify that the requested license files installed in the switch are displayed in response to the **show license usage** command.



Note

The switch is initially shipped with the required licenses installed in the system; however, the initial license file will not cover unlicensed features that may be used during the grace period. If no license is displayed at this point, perform [Step 6](#) and [Step 7](#) to install the required licenses. If the required licenses are displayed at this point, skip [Step 6](#) and [Step 7](#) and move to [Step 8](#).

The example CLI output for a valid license follows:

```
switch# show license usage
Feature                               Ins Lic  Status Expiry Date Comments
                                      Count
-----
FM_SERVER_PKG                         No  -   Unused          -
MAINFRAME_PKG                         No  -   Unused          -
ENTERPRISE_PKG                        Yes  -   Unused never    -
-----
```

Step 6 Install licenses (if necessary) to ensure that the required features are available on the switch. Perform the following steps:

- a. Use the **show license host-id** command to obtain the serial number for your switch. The host ID is also referred to as the switch serial number.

```
switch# show license host-id
License hostid: VDH=JAF1721AEQG
```



Tip Use the entire ID that appears after the colon (:). In this example, the host ID is VDH=JAF1721AEQG.

- b. Obtain your Claim Certificate or the Proof of Purchase document. This document accompanies every Cisco MDS switch.
- c. Locate the Product Authorization Key (PAK) from the Claim Certificate or Proof of Purchase document.
- d. Locate the website URL from the Claim Certificate or Proof of Purchase document.
- e. Access the specified URL that applies to your switch and enter the switch serial number and the PAK. The license key file is sent to you by email. The license key file is digitally signed to authorize its use only on the switch for which it was requested. The requested features are also enabled once the NX-OS software on the specified switch accesses the license key file.



Caution Install the license file in the specified Cisco MDS 9000 Family switch without making any modifications.

Step 7 Install the license key file when you receive it by email. Perform the following steps:

- a. Copy the license file to bootflash using TFTP or SCP.
- b. Perform the installation by issuing the **install license** command on the active supervisor module from the switch console.

```
switch# install license bootflash:license_file.lic
Installing license ..done
```



Note If you provide a target name for the license key file, the file is installed with the specified name. Otherwise, the file name specified in the license key file is used to install the license.

- c. Exit the switch console.

Step 8 Ensure that the required space is available in the bootflash: directory for the image file(s) to be copied using the **dir bootflash:** command. Use the **delete bootflash:filename** command to remove unnecessary files.



Note Before downloading and installing Cisco NX-OS software, verify that the release is supported by your Cisco System MDS reseller. If you purchased support through a Cisco Systems reseller, contact them directly for more information. Otherwise, contact Cisco Technical support at this URL: http://www.cisco.com/en/US/support/tsd_cisco_worldwide_contacts.html.

```
switch# dir bootflash:
37011968   Apr 30 16:10:28 2014  m9500-sf3ek9-kickstart-mz-npe.6.2.1.bin
195875124  Apr 30 12:55:14 2014  m9500-sf3ek9-mz-npe.6.2.1.bin
Usage for bootflash://sup-local
  819736576 bytes used
  75313152 bytes free
  895049728 bytes total
```

Step 9 If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# delete m9500-sf3ek9-kickstart-mz-npe.6.2.1.bin
switch# delete m9500-sf3ek9-mz-npe.6.2.1.bin
```

Step 10 For switches with dual supervisor modules, verify that there is space available on the standby supervisor module bootflash on a switch.

```
switch# attach module x (where x is the module number of the standby supervisor)
switch(standby)# dir bootflash:
  12288      Aug 26 19:06:14 2011 lost+found/

16206848    Jul 01 10:54:49 2011 m9500-sf2ek9-kickstart-mz-npe.6.2.1.bin
 78337129   Jul 01 10:33:52 2011 m9500-sf2ek9-mz-npe.6.2.1.bin

Usage for bootflash://sup-local
 122811392 bytes used
  61748224 bytes free
 184559616 bytes total

switch(standby)# exit (to return to the active supervisor)
```

Step 11 For switches with dual supervisor modules, if you need more space on the standby supervisor module bootflash on a switch, delete unnecessary files to make space available.

```
switch(standby)# delete bootflash:m9500-sf2ek9-kickstart-mz-npe.6.2.1.bin
switch(standby)# delete m9500-sf2ek9-mz-npe.6.2.1.bin
```

Step 12 Access the Software Download Center using this URL:

<http://www.cisco.com/cisco/software/navigator.html>

If prompted to log in, use your Cisco system user ID and password.

Step 13 Select the same version of the NPE image file or non-NPE image file that the switch is currently running. You see the Technical Support Encryption Software Export Distribution Authorization form.

Step 14 Complete the required forms to obtain authorization.

Step 15 Download the files to an FTP or TFTP server.

Step 16 Copy the Cisco MDS NX-OS kickstart and system images to the active supervisor module bootflash using FTP or TFTP.



Note When you download an image file, change to your FTP environment IP address or DNS name and the path where the files are located.

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-kickstart-mz.6.2.1.bin
bootflash:m9500-sf2ek9-kickstart-mz.6.2.1.bin
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-mz.6.2.1.bin
bootflash:m9500-sf2ek9-mz.6.2.1.bin
```

- Step 17** Issue the **boot kickstart bootflash:filename** and **boot system bootflash:filename** commands to change the boot variables to point to the new image.

```
sw-6x-9509# configure terminal
sw-6x-9509(config)# boot kickstart bootflash:m9500-sf2ek9-kickstart-mz.6.2.1.bin
Performing image verification and compatibility check, please wait...
sw-6x-9509(config)# boot system bootflash:m9500-sf2ek9-mz.6.2.1.bin
Performing image verification and compatibility check, please wait...
```

- Step 18** Issue the **show incompatibility-all system filename** command to verify any incompatible hardware.

```
sw-6x-9509(config-if)# show incompatibility-all system m9500-sf2ek9-mz.6.2.1.bin
Checking incompatible configuration(s)
No incompatible configurations

Checking dynamic incompatibilities:
-----
No incompatible configurations
sw-6x-9509(config-if)#
```

- Step 19** Save the current running configuration to the startup configuration by issuing the **copy running-config startup-config** command.

```
sw-6x-9509(config)# copy running-config startup-config
[#####] 100%
Copy complete.
```

- Step 20** Issue the **show boot** command to check the current boot variable.

```
sw-6x-9509(config)# show boot

Current Boot Variables:

sup-1
kickstart variable = bootflash:/ m9500-sf2ek9-kickstart-mz.6.2.1.bin
system variable = bootflash:/ m9500-sf2ek9-mz.6.2.1.bin
sup-2
kickstart variable = bootflash:/ m9500-sf2ek9-kickstart-mz.6.2.1.bin
system variable = bootflash:/ m9500-sf2ek9-mz.6.2.1.bin
No module boot variable set

Boot Variables on next reload:

sup-1
kickstart variable = bootflash:/ m9500-sf2ek9-kickstart-mz.6.2.1.bin
system variable = bootflash:/ m9500-sf2ek9-mz.6.2.1.bin
sup-2
kickstart variable = bootflash:/ m9500-sf2ek9-kickstart-mz.6.2.1.bin
system variable = bootflash:/ m9500-sf2ek9-mz.6.2.1.bin
No module boot variable set
sw-6x-9509(config)#
```

- Step 21** Reload the switch by issuing the **reload** command.

```
sw-6x-9509(config)# reload
This command will reboot the system. (y/n)? [n]
```

You have now upgraded the Cisco MDS NX-OS software in your existing switch.

Downgrading from Cisco NX-OS Release 6.2(x)

Observe these guidelines when downgrading software on Cisco MDS 9148s, 9250i, 9396s, and 9700 Series Director Switches:

- Inserting smartoptics on Cisco MDS 9148s, 9250i, 9396s, and 9700 Series Director Switches running an unsupported Cisco MDS NX-OS Release results in the port moving to error-disabled state.
- Downgrading from Cisco MDS NX-OS Release 6.2(19) to any other unsupported release (higher or lower) on Cisco MDS 9148s, 9250i, 9396s, and 9700 Series Director Switches with smartoptics links that are error disabled will keep the links in the error-disabled state, unless the links are physically removed and inserted to bring the links up.
- Downgrading from Cisco MDS NX-OS Release 6.2(19) to any other unsupported release (higher or lower) on Cisco MDS 9148s, 9250i, 9396s, and 9700 Series Director Switches with smartoptics links up and trunking will keep the links in trunking state.
- If you copy firmware using the SFTP or SCP clients after enabling the **feature scp-server** or **feature sftp-server** command on your switch, ensure that you close the SFTP or SCP connection before performing ISSD. Otherwise, ISSD will be disruptive. This issue is not seen when you transfer files from the switch using the **copy** command or when using the DCNM client.

The following section describes how to downgrade from NX-OS Release 6.2(9) to NX-OS Release 6.2(7), 6.2(5a), 6.2(5), 6.2(3)6.2(1), or 5.2(x).



Note

Parallel In-Service Software Downgrade (ISSD) is not recommended on MDS 9148S, MDS 9250i and MDS 9396S fabric switches when these category of fabric switches are peers to each other.

Downgrading from Cisco MDS NX-OS Release 6.2(7) to Cisco MDS NX-OS Release 6.2(5a), 6.2(5), 6.2(3), or 6.2(1)

You must follow these general guidelines before performing a software downgrade from MDS NX-OS Release 6.2(7) to MDS NX-OS Release 6.2(7), 6.2(5a), 6.2(5), 6.2(3), or 6.2(1).

MDS 9700 Series Director with the 48-Port 10-Gigabit Fibre Channel over Ethernet (FCoE) Module and VLAN Configurations



Note

You must not perform the Step 2 before Step 1. If you perform Step 2 before Step 1, unexpected events might occur in the switch.

To downgrade from NX-OS Release 6.2(9) from NX-OS Release to Cisco MDS NX-OS Release, 6.2(5a), 6.2(5), 6.2(3), or 6.2(1), follow these steps:

- Step 1** You must remove all 48-Port 10-Gigabit FCoE modules from the Cisco MDS 9710 chassis.
- Step 2** Use the **purge module running-config** command to remove any FCoE-related configuration from each 48-Port 10-Gigabit FCoE module that is removed.
- Step 3** You must remove all VLANs that you have created and verify that no VLAN or VSAN mapping exist on the switch by using the **show vlan** and **show vlan fcoe** command.
- Step 4** You must remove all Ethernet Port Channels and verify that no Ethernet Port Channel exists on the switch by using the **show interface brief** and **show ethernet-port-channel database** command.

- Step 5** You must remove all virtual Fibre Channels (vFCs) and verify that no vFC exists on the switch by using the **show interface brief** command.

Downgrading from NX-OS Release 6.2(9) to NX-OS Release 6.2(7), 6.2(5a), 6.2(5), 6.2(3), or 6.2(1) on an MDS 9700 Series Director

Use the **install all** command to downgrade the switch and handle configuration conversions. When downgrading any switch in the Cisco MDS 9000 Family, avoid using the **reload** command.

To downgrade from NX-OS Release 6.2(x) from NX-OS Release 6.2(9), follow these steps:

- Step 1** Verify that the system image files for the downgrade are present on the active supervisor module bootflash:

```
switch# dir bootflash:
16384   Mar 13 22:06:41 2014  .fc-pcm-log-5354.swp
 195379283   Mar 29 10:24:59 2014  46_pvt_image.bin
 191117954   Mar 30 11:25:06 2014  47_ps_negative.bin
 195257014   Mar 29 07:30:28 2014  S46_deepak_fib_crash.bin
    4096     Dec 13 07:19:44 2013  _vdc1/
  3383061   Mar 21 04:29:41 2014  d
  3383061   Mar 22 12:20:51 2014  d1
    4096     Feb 11 12:53:22 2014  epld_dir/
  3963713   Mar 22 02:14:25 2014  ethpm.core.gz
  4997021   Mar 21 23:44:53 2014  ethpm.ts
    4096     Dec 26 10:15:18 2013  fcoe_vdc1/
 11870971   Mar 21 23:46:21 2014  lacpa.ts
  284045   Mar 14 15:09:58 2014  libfsccli.so
    232     Sep 10 13:18:19 2013  license.lic
  1718723   Mar 25 19:08:02 2014  logfile.txt
    4096     Mar 30 12:50:24 2014  lost+found/
  3382868   Mar 28 20:56:38 2014  m9700-sf3ek9-dplug-mzg.6.2.9.bin
 36701184   Mar 22 07:14:26 2014  m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60
 36726272   Mar 31 08:16:08 2014  m9700-sf3ek9-kickstart-mz.6.2.3.bin.S16
 36729856   Mar 22 05:53:53 2014  m9700-sf3ek9-kickstart-mz.6.2.5.bin.S68
 36819968   Mar 30 10:24:55 2014  m9700-sf3ek9-kickstart-mz.6.2.9.bin
 36819968   Mar 30 07:26:27 2014  m9700-sf3ek9-kickstart-mz.6.2.9.bin.S47
 180230838   Mar 22 07:19:31 2014  m9700-sf3ek9-mz.6.2.1.bin.S60
 184361989   Mar 31 08:17:24 2014  m9700-sf3ek9-mz.6.2.3.bin.S16
 185116340   Mar 22 05:55:29 2014  m9700-sf3ek9-mz.6.2.5.bin.S68
 191473732   Mar 30 10:27:44 2014  m9700-sf3ek9-mz.6.2.9.bin
 191461839   Mar 30 07:28:01 2014  m9700-sf3ek9-mz.6.2.9.bin.S47
    636324   Mar 21 20:14:53 2014  msgs.log
 191430449   Mar 30 09:37:09 2014  ps_negative.bin
  2887394   Mar 27 20:00:02 2014  runn-fc
  2887386   Mar 29 10:33:51 2014  runn-fc1
  2888147   Mar 30 06:55:55 2014  runn-fc2
  3145515   Mar 24 08:24:36 2014  runn-mar24
  3161689   Mar 26 18:34:36 2014  runn-mar26
    880111   Mar 27 07:07:25 2014  runn-mar27
  3161725   Mar 26 19:47:41 2014  runn-mar27-preRel

Usage for bootflash://sup-local
2178080768 bytes used
1562763264 bytes free
3740844032 bytes total
```

- Step 2** If the software image file is not present, download it from an FTP or TFTP server to the active supervisor module bootflash:. You can obtain the software image file from the Cisco.com software download center at the following URL:

<http://www.cisco.com/cisco/software/navigator.html>



Note If you need more space on the active supervisor module bootflash:, use the **delete** command to remove unnecessary files and follow [Step 3](#) through [Step 6](#).

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9700-sf3ek9-mz.6.2.5.bin
bootflash:m9700-sf3ek9-kickstart-mz.6.2.7.bin
switch# copy tftp://tftpserver.cisco.com/MDS/m9700-sf3ek9-mz.6.2.5.bin
bootflash:m9700-sf3ek9-mz.6.2.5.bin
```

- Step 3** Ensure that the required space is available on the active supervisor.

```
switch# dir bootflash:
3382868   Mar 28 20:56:38 2014  m9700-sf3ek9-dplug-mzg.6.2.7.bin
36701184  Mar 22 07:14:26 2014  m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60
36726272  Mar 31 08:16:08 2014  m9700-sf3ek9-kickstart-mz.6.2.3.bin.S16
36729856  Mar 22 05:53:53 2014  m9700-sf3ek9-kickstart-mz.6.2.5.bin.S68
36819968  Mar 30 10:24:55 2014  m9700-sf3ek9-kickstart-mz.6.2.5.bin
36819968  Mar 30 07:26:27 2014  m9700-sf3ek9-kickstart-mz.6.2.7.bin.S47
180230838 Mar 22 07:19:31 2014  m9700-sf3ek9-mz.6.2.1.bin.S60
184361989 Mar 31 08:17:24 2014  m9700-sf3ek9-mz.6.2.3.bin.S16
185116340 Mar 22 05:55:29 2014  m9700-sf3ek9-mz.6.2.5.bin
```

```
Usage for bootflash://sup-local
2178080768 bytes used
1562763264 bytes free
3740844032 bytes total
```

- Step 4** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# del m9700-sf3ek9-mz.6.2.1.bin.S60
switch# del m9700-sf3ek9-mz.6.2.3.bin.S16
```

- Step 5** Verify that there is enough space available for the standby supervisor.

```
switch(standby)# dir bootflash
3382868   Mar 28 20:56:38 2014  m9700-sf3ek9-dplug-mzg.6.2.7.bin
36701184  Mar 22 07:14:26 2014  m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60
36726272  Mar 31 08:16:08 2014  m9700-sf3ek9-kickstart-mz.6.2.3.bin.S16
36729856  Mar 22 05:53:53 2014  m9700-sf3ek9-kickstart-mz.6.2.5.bin.S68
36819968  Mar 30 10:24:55 2014  m9700-sf3ek9-kickstart-mz.6.2.7.bin
36819968  Mar 30 07:26:27 2014  m9700-sf3ek9-kickstart-mz.6.2.7.bin.S47
```

```
Usage for bootflash://sup-local
116188794 bytes used
68370822 bytes free
184559616 bytes total
```

- Step 6** If you need more space on the standby supervisor module bootflash, delete unnecessary files to make space available.

```
switch(standby)# del m9700-sf3ek9-kickstart-mz.6.2.3.bin.S16
switch(standby)# del m9700-sf3ek9-kickstart-mz.6.2.3.bin.S60
```

- Step 7** Issue the **show incompatibility system image-filename** command to determine if you need to disable any features not supported by the earlier release.

```
switch# show incompatibility system bootflash:m9700-sf3ek9-dplug-mzg.6.2.7.bin
No incompatible configuration
switch#
```

Step 8 Save the configuration using the **copy running-config startup-config** command.

```
switch# copy running-config startup-config
```

Step 9 Issue the **install all** command to downgrade the software.

```
switch# install all kickstart bootflash:m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60 system
bootflash:m9700-sf3ek9-mz.6.2.1.bin.S60
Installer will perform compatibility check first. Please wait.
```

```
Verifying image bootflash:/m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60 for boot variable
"kickstart".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/m9700-sf3ek9-mz.6.2.1.bin.S60 for boot variable "system".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image type.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "slc4xb" version from image bootflash:/m9700-sf3ek9-mz.6.2.1.bin.S60.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "bios" version from image bootflash:/m9700-sf3ek9-mz.6.2.1.bin.S60.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "system" version from image bootflash:/m9700-sf3ek9-mz.6.2.1.bin.S60.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "kickstart" version from image
bootflash:/m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60.
```

```
[#####] 100% -- SUCCESS
```

```
Performing module support checks.
```

```
[#####] 100% -- SUCCESS
```

```
Notifying services about system upgrade.
```

```
[#####] 100% -- SUCCESS
```

```
Compatibility check is done:
```

Module	bootable	Impact	Install-type	Reason
1	yes	non-disruptive	rolling	
5	yes	non-disruptive	reset	
6	yes	non-disruptive	reset	
9	yes	non-disruptive	rolling	

```
Images will be upgraded according to following table:
```

Module	Image	Running-Version (pri:alt)	New-Version
Upg-Required			
1	slc4xb	6.2(7)	6.2(1)
yes			
1	bios	v1.10.21(11/26/12) :v1.10.21(11/26/12)	v1.10.21(11/26/12)
no			

```

5      system                6.2(7)                6.2(1)
yes
5      kickstart            6.2(7)                6.2(1)
yes
5      bios      v3.1.0(02/27/2013):v3.1.0(02/27/2013)  v3.1.0(02/27/2013)
no
6      system                6.2(7)                6.2(1)
yes
6      kickstart            6.2(7)                6.2(1)
yes
6      bios      v3.1.0(02/27/2013):v3.1.0(02/27/2013)  v3.1.0(02/27/2013)
no
9      slc4xb                6.2(7)                6.2(1)
yes
9      bios      v1.10.21(11/26/12):v1.10.21(11/26/12)  v1.10.21(11/26/12)
no

```

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.

[#####] 100% -- SUCCESS

Syncing image bootflash:/m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60 to standby.

[#####] 100% -- SUCCESS

Syncing image bootflash:/m9700-sf3ek9-mz.6.2.1.bin.S60 to standby.

[#####] 100% -- SUCCESS

Setting boot variables.

[#####] 100% -- SUCCESS

Performing configuration copy.

[#####] 100% -- SUCCESS

Module 1: Upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

Module 5: Upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

Module 6: Upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

Module 9: Upgrading bios/loader/bootrom.

Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS

2014 Mar 30 11:02:48 switch %PLATFORM-2-MOD_REMOVE: Module 5 removed (Serial number JAE1717064T)

Module 5: Waiting for module online.

-- SUCCESS

Notifying services about the switchover.

[#####] 100% -- SUCCESS

"Switching over onto standby".



Note At this point, the previously active supervisor module is rebooting after a nondisruptive switchover has taken place. Refer to the [Cisco MDS 9000 Family NX-OS High Availability and Redundancy Configuration Guide](#).



Note At this point, a switchover occurs to the new active supervisor module.

```
>>>
NX7k SUP BIOS version ( 3.01 ) : Build - 02/26/2013 14:16:20
PM FPGA Version : 0x00000013
Power sequence microcode revision - 0x00000001 : card type - f10156EEA0
Booting Spi Flash : Primary
  CPU Signature - 0x000106e4: Version - 0x000106e0
  CPU - 1 : Cores - 4 : HTEn - 1 : HT - 2 : Features - 0xbfebfbff
  FSB Clk - 532 Mhz : Freq - 2145 Mhz - 2128 Mhz
  MicroCode Version : 0x00000002
  Memory - 8192 MB : Frequency - 1067 MHZ
  Loading Bootloader: Done
  IO FPGA Version   : 0x10001
  PLX Version       : 861910b5
Bios digital signature verification - Passed

Reset Reason Registers: 0x0 0x8
  Filesystem type is ext2fs, partition type 0x83

          GNU GRUB  version 0.97

Autobooting bootflash:/m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60 bootflash:/m9700
-sf3ek9-mz.6.2.1.bin.S60...
  Filesystem type is ext2fs, partition type 0x83
Booting kickstart image: bootflash:/m9700-sf3ek9-kickstart-mz.6.2.1.bin.S60....
.....
Kickstart digital signature verification Successful
Image verification OK

INIT: version 2
boot device node /dev/sdb
obfl flash device node /dev/sda
log flash device node /dev/sdc
Checking obfl filesystem.
Checking all filesystems..r.r... done.
Mounting Log Dir /logflash
mounting Log 0
rrLoading system software
/bootflash//m9700-sf3ek9-mz.6.2.1.bin.S60 read done
System image digital signature verification successful.
Uncompressing system image: bootflash:/m9700-sf3ek9-mz.6.2.1.bin.S60 Sun Mar 30 11:04:34
UTC 2014
blogger: nothing to do.
C
..done Sun Mar 30 11:04:37 UTC 2014
Load plugins that defined in image conf: /isan/plugin_img/img.conf
Loading plugin 0: core_plugin...
num srgs 1
0: swid-core-sup3dc3mds, swid-core-sup3dc3mds
num srgs 1
0: swid-sup3dc3mds-ks, swid-sup3dc3mds-ks
```



```

INIT: Entering runlevel: 3

init: MAX_ALLOWED_VDCS= 1

Continuing with installation, please wait

Module 5: Waiting for module online.
-- SUCCESS
2014 Mar 30 11:06:32 switch %$ VDC-1 %$ Mar 30 11:06:32 %KERN-2-SYSTEM_MSG: [ 194.058357]
Switchover started by redundancy driver - kernel
2014 Mar 30 11:06:33 switch %$ VDC-1 %$ %SYSMGR-2-HASWITCHOVER_PRE_START: This supervisor
is becoming active (pre-start phase).
2014 Mar 30 11:06:33 switch %$ VDC-1 %$ %SYSMGR-2-HASWITCHOVER_START: Supervisor 5 is
becoming active.
2014 Mar 30 11:06:34 switch %$ VDC-1 %$ %SYSMGR-2-SWITCHOVER_OVER: Switchover completed.

Module 1: Non-disruptive upgrading.
[#####] 100% -- SUCCESS

Module 9: Non-disruptive upgrading.
[#####] 100% -- SUCCESS

Install has been successful.

User Access Verification
switch# login:

```

Step 10 Verify the status of the modules on the switch using the **show module** command.

```

switch# show module
Mod  Ports  Module-Type                               Model                               Status
---  ---
1    48     2/4/8/10/16 Gbps Advanced FC Module DS-X9448-768K9                       ok
4    48     10 Gbps FCoE Module                     DS-X9848-480K9                       ok
5    0      Supervisor Module-3                      DS-X97-SF1-K9                        active *
6    0      Supervisor Module-3                      DS-X97-SF1-K9                        ha-standby
9    48     2/4/8/10/16 Gbps Advanced FC Module DS-X9448-768K9                       ok
10   48     10 Gbps FCoE Module                     DS-X9848-480K9                       ok

Mod  Sw          Hw
---  ---
1    6.2(7)      1.1
4    6.2(7)      0.110
5    6.2(7)      1.0
6    6.2(7)      1.0
9    6.2(7)      1.1
10   6.2(7)      0.110

Mod  MAC-Address(es)                               Serial-Num
---  ---
1    1c-df-0f-79-18-f8 to 1c-df-0f-79-18-fb JAE17190321
4    84-78-ac-1a-ef-c0 to 84-78-ac-1a-ef-f3 JAF1718AACG
5    1c-df-0f-79-04-cc to 1c-df-0f-79-04-de JAE1717064T
6    1c-df-0f-78-c4-60 to 1c-df-0f-78-c4-72 JAE171008AY
9    0c-68-03-29-92-e8 to 0c-68-03-29-92-eb JAE173302WD
10   84-78-ac-1c-1c-2c to 84-78-ac-1c-1c-5f JAF1718AABT

Mod  Online Diag Status
---  ---
1    Pass
4    Pass
5    Pass
6    Pass

```

```

9    Pass
10   Pass

```

Xbar	Ports	Module-Type	Model	Status
1	0	Fabric Module 1	DS-X9710-FAB1	ok
2	0	Fabric Module 1	DS-X9710-FAB1	ok
4	0	Fabric Module 1	DS-X9710-FAB1	ok
5	0	Fabric Module 1	DS-X9710-FAB1	ok

Xbar	Sw	Hw
1	NA	1.1
2	NA	1.1
4	NA	1.1
5	NA	1.1

Xbar	MAC-Address(es)	Serial-Num
1	NA	JAE172008XA
2	NA	JAE173407BU
4	NA	JAE172008XZ
5	NA	JAE171504YJ

```

* this terminal session
switch#

```

Downgrading from NX-OS Release 6.2(x) to NX-OS Release 5.2(x)

Before performing ISSD from Cisco MDS NX-OS Release 6.2(x) to Cisco MDS NX-OS Release 5.2(x) on Cisco MDS 9500 Series Directors, ensure that the **purge fcdomain fcid vsan vsan-id** command is executed on the IOA VSAN.

The following sections describe how to perform downgrades on an MDS 9513 switch:

- [Downgrading from NX-OS Release 6.2\(x\) to NX-OS Release 5.2\(x\) on an MDS 9513 Multilayer Director, page 67.](#)

To determine whether high bandwidth capability is enabled, issue the **show hardware fabric-mode** command. The following example shows that the higher bandwidth capability has not been activated:

```

switch# show hardware fabric-mode
Fabric mode supports only one configuration of 8G FC modules - 4/44 Host-Optimized 8G FC
module.
switch#

```

The following example shows that the higher bandwidth capability has been activated:

```

switch# show hardware fabric-mode
fabric mode supports FCoE, Gen2 and above linecards
switch#

```

The following sections describe how to perform downgrades on an MDS 9509 and MDS 9506 switch:

- [Downgrading from NX-OS Release 6.2\(x\) to NX-OS Release 5.2\(x\) on an MDS 9509 or MDS 9506 Switch, page 72.](#)
- [..., page 78.](#)

The following section describes how to perform a downgrade on an MDS 9250i switch:

- [Downgrading from NX-OS Release 6.2\(x\) to NX-OS Release 5.2\(x\) on an MDS 9250i Switch, page 84.](#)

For information on supported chassis and modules, refer to “[Components Supported](#)” section on page 2. For information on the procedures for installing and upgrading software for Intelligent Storage Services on the Cisco MDS 9000 Family Storage Services Module (SSM), refer to the [Cisco MDS 9000 Family Storage Services Module Software Installation and Upgrade Guide](#).

Downgrading from NX-OS Release 6.2(x) to NX-OS Release 5.2(x) on an MDS 9513 Multilayer Director

Use the **install all** command to downgrade the switch and handle configuration conversions. When downgrading any switch in the Cisco MDS 9000 Family, avoid using the **reload** command.

To downgrade from NX-OS Release 6.2(x) from NX-OS Release 5.2(x), follow these steps:

- Step 1** Verify that the system image files for the downgrade are present on the active supervisor module bootflash:.

```
switch# dir bootflash:
 12288      Aug 26 19:06:14 2011  lost+found/
22001152    Jul  01 10:54:49 2011  m9500-sf2ek9-kickstart-mz.5.2.x.bin
16604160    Jul  01 10:20:07 2011  m9500-sf2ek9-kickstart-mz.5.0.1a.bin
94175354    Jul  01 10:33:52 2011  m9500-sf2ek9-mz.5.2.x.bin
78718938    Jul  01 10:18:09 2011  m9500-sf2ek9-mz.5.0.1a.bin
```

```
Usage for bootflash://sup-local
211411892 bytes used
167810476 bytes free
379322368 bytes total
```

- Step 2** If the software image file is not present, download it from an FTP or TFTP server to the active supervisor module bootflash:. You can obtain the software image file from the Cisco.com software download center at the following URL:

<http://www.cisco.com/cisco/software/navigator.html>



Note If you need more space on the active supervisor module bootflash:, use the **delete** command to remove unnecessary files and follow [Step 3](#) through [Step 6](#).

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-kickstart-mz.5.2.1.bin
bootflash:m9500-sf2ek9-kickstart-mz.5.2.1a.bin
```

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-mz.5.2.1.bin
bootflash:m9500-sf2ek9-mz.5.2.1.bin
```

- Step 3** Ensure that the required space is available on the active supervisor.

```
switch# dir bootflash:
 12288      Aug 26 19:06:14 2011  lost+found/
22001152    Jul  01 10:54:49 2011  m9500-sf2ek9-kickstart-mz.5.2.x.bin
94175354    Jul  01 10:33:52 2011  m9500-sf2ek9-mz.5.2.x.bin
```

```
Usage for bootflash://sup-local
116188794 bytes used
 68370822 bytes free
184559616 bytes total
```

- Step 4** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# del bootflash:m9500-sf2ek9-kickstart-mz.5.0.x.bin
switch# del bootflash:m9500-sf2ek9-mz.5.0.x.bin
```

- Step 5** Verify that there is enough space available for the standby supervisor.

```
switch(standby)# dir bootflash:
 12288      Aug 26 19:06:14 2011  lost+found/
22001152   Jul 01 10:54:49 2011  m9500-sf2ek9-kickstart-mz.5.2.1.bin
 94175354   Jul 01 10:33:52 2011  m9500-sf2ek9-mz.5.2.1.bin

Usage for bootflash://sup-local
116188794 bytes used
68370822 bytes free
184559616 bytes total
```

- Step 6** If you need more space on the standby supervisor module bootflash, delete unnecessary files to make space available.

```
switch(standby)# del bootflash:m9500-sf2ek9-kickstart-mz.5.2.x.bin
switch(standby)# del bootflash:m9500-sf2ek9-mz.5.2.x.bin
```

- Step 7** Issue the **show incompatibility system image-filename** command to determine if you need to disable any features not supported by the earlier release.

```
switch# show incompatibility system bootflash:m9500-sf2ek9-mz.5.2.1.bin
The following configurations on active are incompatible with the system image
1) Service : port-channel , Capability : CAP_FEATURE_AUTO_CREATED_41_PORT_CHANNEL
Description : auto create enabled ports or auto created port-channels are present
Capability requirement : STRICT
Disable command :
1.Disable autcreate on interfaces (no channel-group auto).
2.Convert autcreated port channels to be persistent (port-channel 1 persistent)
...
```

- Step 8** Disable any features that are incompatible with the downgrade system image.

```
switch# configure terminal
Enter configuration commands, one per line. End with CNTL/Z.
switch(config)# interface fcip 31
switch(config-if)# no channel-group auto
switch(config-if)# end
switch# port-channel 127 persistent
switch#
```

- Step 9** Save the configuration using the **copy running-config startup-config** command.

```
switch# copy running-config startup-config
```

- Step 10** Issue the **install all** command to downgrade the software.

```
switch# install all kickstart bootflash:m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74 system
bootflash:m9500-sf2ek9-mz.5.2.1.bin.S74
```

```
Verifying image bootflash:/m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74 for boot variable
"kickstart".
[#####] 100% -- SUCCESS
Verifying image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74 for boot variable "system".
[#####] 100% -- SUCCESS
Verifying image type.
[#####] 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
```

```

##### 100% -- SUCCESS
Extracting "bios" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "system" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "kickstart" version from image
bootflash:/m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Performing Compact Flash and TCAM sanity test.
##### 100% -- SUCCESS
Performing module support checks.
##### 100% -- SUCCESS
Notifying services about system upgrade.
##### 100% -- SUCCESS
Compatibility check is done:

```

Module	bootable	Impact	Install-type	Reason
3	yes	non-disruptive	rolling	
4	yes	non-disruptive	rolling	
5	yes	non-disruptive	rolling	
6	yes	non-disruptive	rolling	
7	yes	non-disruptive	reset	
8	yes	non-disruptive	reset	
9	yes	non-disruptive	rolling	
10	yes	non-disruptive	rolling	
11	yes	non-disruptive	rolling	
12	yes	non-disruptive	rolling	
13	yes	non-disruptive	rolling	

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version	Upg-Required
3	slc2		6.2(x) 5.2(1)	yes
3	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
4	slc2		6.2(x) 5.2(1)	yes
4	bios	v1.0.17(05/28/09) :	v1.0.17(05/28/09)	no
5	slc2		6.2(x) 5.2(1)	yes
5	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
6	slc2		6.2(x) 5.2(1)	yes
6	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
7	system		6.2(x) 5.2(1)	yes
7	kickstart		6.2(x) 5.2(1)	yes
7	bios	v1.0.10(01/08/09) :	v1.0.10(01/08/09)	no
8	system		6.2(x) 5.2(1)	yes
8	kickstart		6.2(x) 5.2(1)	yes
8	bios	v1.0.10(01/08/09) :	v1.0.10(01/08/09)	no
9	slc2		6.2(x) 5.2(1)	yes
9	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
10	slc2		6.2(x) 5.2(1)	yes

```

10      bios      v1.0.19(02/01/10):  v1.0.19(02/01/10)      no
11      slc2      6.2(x) 5.2(1)      yes
11      bios      v1.0.19(02/01/10):  v1.0.19(02/01/10)      no
12      slc2      6.2(x) 5.2(1)      yes
12      bios      v1.0.19(02/01/10):  v1.0.19(02/01/10)      no
13      slc2      6.2(x) 5.2(1)      yes
13      bios      v1.0.15(07/16/08):  v1.0.15(07/16/08)      no

```

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.

```

[#####] 100% -- SUCCESS
Syncing image bootflash:/m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74 to standby.
[#####] 100% -- SUCCESS
Syncing image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74 to standby.
[#####] 100% -- SUCCESS
Setting boot variables.
[#####] 100% -- SUCCESS
Performing configuration copy.
[#####] 100% -- SUCCESS
Module 3: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 4: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 5: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 6: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 7: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 8: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 9: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 10: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 11: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 12: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
Module 13: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS
2011 Aug 2 00:56:32 sw86 %PLATFORM-2-MOD_REMOVE: Module 8 removed (Serial number
JAF1421FKAS)
Module 8: Waiting for module online.
-- SUCCESS

```

**Note**

At this point, the previously active supervisor module is rebooting after a nondisruptive switchover has taken place. Refer to the [Cisco MDS 9000 Family NX-OS High Availability and Redundancy Configuration Guide](#).

<http://www.gnu.org/licenses/gpl.html> and
<http://www.gnu.org/licenses/lgpl.html>

Step 11 Verify the status of the modules on the switch using the **show module** command.

```
switch# show module
Mod  Ports  Module-Type                Model                Status
---  -
1    12     1/2/4 Gbps FC Module      DS-X9112             ok
3    16     1/2 Gbps FC Module        DS-X9016             ok
4    48     1/2/4 Gbps FC Module      DS-X9148             ok
7    0      Supervisor/Fabric-2       DS-X9530-SF2-K9     ha-standby
8    0      Supervisor/Fabric-2       DS-X9530-SF2-K9     active *
9    24     1/2/4 Gbps FC Module      DS-X9124             ok
10   16     1/2 Gbps FC Module        DS-X9016             ok
11   4      10 Gbps FC Module         DS-X9704             ok
...

```

Downgrading from NX-OS Release 6.2(x) to NX-OS Release 5.2(x) on an MDS 9509 or MDS 9506 Switch

To downgrade to Cisco NX-OS Release 5.2(x) from Cisco NX-OS Release 6.2(x), on an MDS 9509 or MDS 9506 switch, follow these steps:

Step 1 Verify that the system image files for the downgrade are present on the active supervisor module bootflash:

```
switch# dir bootflash:
 12288      Aug 26 19:06:14 2011  lost+found/
22001152   Jul  01 10:54:49 2011  m9500-sf2ek9-kickstart-mz.5.2.x.bin
16604160   Jul  01 10:20:07 2011  m9500-sf2ek9-kickstart-mz.5.0.1a.bin
94175354   Jul  01 10:33:52 2011  m9500-sf2ek9-mz.5.2.x.bin
78718938   Jul  01 10:18:09 2011  m9500-sf2ek9-mz.5.0.1a.bin

Usage for bootflash://sup-local
211411892 bytes used
167810476 bytes free
379322368 bytes total

```

Step 2 If the software image file is not present, download it from an FTP or TFTP server to the active supervisor module bootflash:. You can obtain the software image file from the Cisco.com software download center at the following URL:

<http://www.cisco.com/cisco/software/navigator.html>



Note If you need more space on the active supervisor module bootflash:, use the **delete** command to remove unnecessary files and follow [Step 3](#) through [Step 6](#).

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-kickstart-mz.5.2.x.bin
bootflash:m9500-sf2ek9-kickstart-mz.5.2.x.bin
switch# copy tftp://tftpserver.cisco.com/MDS/m9500-sf2ek9-mz.5.2.x.bin
bootflash:m9500-sf2ek9-mz.5.2.x.bin

```

Step 3 Ensure that the required space is available on the active supervisor.

```
switch# dir bootflash:
```



```

    12288      Aug 26 19:06:14 2011  lost+found/
22001152     Jul  01 10:54:49 2011  m9500-sf2ek9-kickstart-mz.5.2.x.bin
94175354     Jul  01 10:33:52 2011  m9500-sf2ek9-mz.5.2.x.bin

```

```

Usage for bootflash://sup-local
116188794 bytes used
68370822 bytes free
184559616 bytes total

```

- Step 4** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```

switch# del bootflash:m9500-sf2ek9-kickstart-mz.5.0.1a.bin
switch# del bootflash:m9500-sf2ek9-mz.5.0.1a.bin

```

- Step 5** Verify that there is enough space available for the standby supervisor.

```

switch(standby)# dir bootflash:
    12288      Aug 26 19:06:14 2011  lost+found/
22001152     Jul  01 10:54:49 2011  m9500-sf2ek9-kickstart-mz.5.2.x.bin
94175354     Jul  01 10:33:52 2011  m9500-sf2ek9-mz.5.2.x.bin

```

```

Usage for bootflash://sup-local
116188794 bytes used
68370822 bytes free
184559616 bytes total

```

- Step 6** If you need more space on the standby supervisor module bootflash, delete unnecessary files to make space available.

```

switch(standby)# del bootflash:m9500-sf2ek9-kickstart-mz.5.2.x.bin
switch(standby)# del bootflash:m9500-sf2ek9-mz.5.2.x.bin

```

- Step 7** Issue the **show incompatibility system image-filename** command to determine if you need to disable any features not supported by the earlier release.

```

switch# show incompatibility system bootflash:m9500-sf2ek9-mz.5.2.x.bin
The following configurations on active are incompatible with the system image
1) Service : port-channel , Capability : CAP_FEATURE_AUTO_CREATED_41_PORT_CHANNEL
Description : auto create enabled ports or auto created port-channels are present
Capability requirement : STRICT
Disable command :
1.Disable autcreate on interfaces (no channel-group auto).
2.Convert autcreated port channels to be persistent (port-channel 1 persistent)
...

```

- Step 8** Disable any features that are incompatible with the downgrade system image.

```

switch# configure terminal
Enter configuration commands, one per line. End with CNTL/Z.
switch(config)# interface fcip 31
switch(config-if)# no channel-group auto
switch(config-if)# end
switch# port-channel 127 persistent
switch#

```

- Step 9** Save the configuration using the **copy running-config startup-config** command.

```

switch# copy running-config startup-config

```

- Step 10** Verify the status of the modules on the switch using the **show module** command.

```

switch# show module
Mod  Ports  Module-Type                Model                Status
-----

```

```

2      4      10 Gbps FC Module                DS-X9704      ok
3      48     1/2/4 Gbps FC Module            DS-X9148      ok
5      0      Supervisor/Fabric-2             DS-X9530-SF2-K9  active *
6      0      Supervisor/Fabric-2             DS-X9530-SF2-K9  ha-standby
8      48     1/2/4/8 Gbps 48-Port FC Module  DS-X9248-96    ok
...

```

Step 11 Verify that the switch is running the required software version by issuing the **show version** command.

```

switch# show version
show version
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents: http://www.cisco.com/en/US/products/ps9372/tsd_products_support_serie
s_home.html
Copyright (c) 2002-2013, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software are covered under the GNU Public
License. A copy of the license is available at
http://www.gnu.org/licenses/gpl.html.
Software
BIOS: version 1.0.10
loader: version N/A
kickstart: version 6.2(5)
system: version 6.2(5)
BIOS compile time: 01/08/09
kickstart image file is: bootflash:///m9500-sf2ek9-kickstart-mz.6.2.5.bin
kickstart compile time: 11/25/2013 9:00:00 [01/30/2014 05:33:20]
system image file is: bootflash:///m9500-sf2ek9-mz.6.2.5.bin
system compile time: 11/25/2013 9:00:00 [01/30/2014 07:10:42]
Hardware
cisco MDS 9509 (9 Slot) Chassis ("Supervisor/Fabric-2a")
Motorola, 7447A, altivec with 2071288 kB of memory.
Processor Board ID JAF1625BAES
Device name: switch
bootflash: 1000944 kB
slot0: 0 kB (expansion flash)
Kernel
----More

```

Step 12 Issue the **install all** command to downgrade the software.

```

switch# install all kickstart bootflash:m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74 system
bootflash:m9500-sf2ek9-mz.5.2.1.bin.S74

Verifying image bootflash:/m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74 for boot variable
"kickstart".
[#####] 100% -- SUCCESS
Verifying image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74 for boot variable "system".
[#####] 100% -- SUCCESS
Verifying image type.
[#####] 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
[#####] 100% -- SUCCESS
Extracting "bios" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
[#####] 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
[#####] 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
[#####] 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
[#####] 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
[#####] 100% -- SUCCESS
Extracting "system" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.

```

```

##### 100% -- SUCCESS
Extracting "kickstart" version from image
bootflash:/m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Extracting "slc2" version from image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74.
##### 100% -- SUCCESS
Performing Compact Flash and TCAM sanity test.
##### 100% -- SUCCESS
Performing module support checks.
##### 100% -- SUCCESS
Notifying services about system upgrade.
##### 100% -- SUCCESS
Compatibility check is done:

```

Module	bootable	Impact	Install-type	Reason
3	yes	non-disruptive	rolling	
4	yes	non-disruptive	rolling	
5	yes	non-disruptive	rolling	
6	yes	non-disruptive	rolling	
7	yes	non-disruptive	reset	
8	yes	non-disruptive	reset	
9	yes	non-disruptive	rolling	
10	yes	non-disruptive	rolling	
11	yes	non-disruptive	rolling	
12	yes	non-disruptive	rolling	
13	yes	non-disruptive	rolling	

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version	Upg-Required
3	slc2		6.2(x) 5.2(1)	yes
3	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
4	slc2		6.2(x) 5.2(1)	yes
4	bios	v1.0.17(05/28/09) :	v1.0.17(05/28/09)	no
5	slc2		6.2(x) 5.2(1)	yes
5	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
6	slc2		6.2(x) 5.2(1)	yes
6	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
7	system		6.2(x) 5.2(1)	yes
7	kickstart		6.2(x) 5.2(1)	yes
7	bios	v1.0.10(01/08/09) :	v1.0.10(01/08/09)	no
8	system		6.2(x) 5.2(1)	yes
8	kickstart		6.2(x) 5.2(1)	yes
8	bios	v1.0.10(01/08/09) :	v1.0.10(01/08/09)	no
9	slc2		6.2(x) 5.2(1)	yes
9	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
10	slc2		6.2(x) 5.2(1)	yes
10	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
11	slc2		6.2(x) 5.2(1)	yes
11	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
12	slc2		6.2(x) 5.2(1)	yes
12	bios	v1.0.19(02/01/10) :	v1.0.19(02/01/10)	no
13	slc2		6.2(x) 5.2(1)	yes
13	bios	v1.0.15(07/16/08) :	v1.0.15(07/16/08)	no

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.

```

#####] 100% -- SUCCESS
Syncing image bootflash:/m9500-sf2ek9-kickstart-mz.5.2.1.bin.S74 to standby.
#####] 100% -- SUCCESS
Syncing image bootflash:/m9500-sf2ek9-mz.5.2.1.bin.S74 to standby.
#####] 100% -- SUCCESS
Setting boot variables.
#####] 100% -- SUCCESS
Performing configuration copy.
#####] 100% -- SUCCESS
Module 3: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 4: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 5: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 6: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 7: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 8: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 9: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 10: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 11: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 12: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
Module 13: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
#####] 100% -- SUCCESS
2011 Aug 2 00:56:32 sw86 %PLATFORM-2-MOD_REMOVE: Module 8 removed (Serial number
JAF1421FKAS)
Module 8: Waiting for module online.
-- SUCCESS

```



Note At this point, the previously active supervisor module is rebooting after a nondisruptive switchover has taken place. Refer to the [Cisco MDS 9000 Family NX-OS High Availability and Redundancy Configuration Guide](#).

```

>> MDS-Bootloader-01.00.06 (Jun 14 2011 - 15:04:07) (MPC7447A)

INFO: Booting off primary flash.
CPU:   MPC7447A v1.1 @ 1411 MHz
DRAM:  SPD Checksum ok!
SPD Checksum ok!
-- DIMM1 has 1 banks
-- DIMM2 has 1 banks
ECC Initialization of Bank 0: Done

```

```


ECC Initialization of Bank 1: Done
CAS Latency = 2.5 tRP = 3 tRAS = 7 tRCD=3
Total SDRAM memory is 1024 MB
40000000
INFO: SDRAM tests PASSED.
PCI 0 bus mode: Conventional PCI
PCI 1 bus mode: Conventional PCI
L2 Cache Initialization.

Internal SRAM ECC Initialization: Done
IDE:   Bus 0: OK Bus 1: OK
  Device 0: Model: TOSHIBA THNCF1G02DG Firm:  Ser#: TSBC1G0207627A79490A
            Type: Hard Disk
            Capacity: 976.9 MB = 0.9 GB (2000880 x 512)
  Device 3: Model: SanDisk SDCFB-64 Firm: Vdg 1.21 Ser#: 02220224946
            Type: Removable Hard Disk
            Capacity: 61.2 MB = 0.0 GB (125440 x 512)

Booting bootflash:/m9500-sf2ek9-kickstart-mz.5.0.1a.bin ...
.....
Automatic boot of image at addr 0x00000000 ...
Starting kernel...
INIT: version 2.78 booting
Checking all filesystems..r.r.r.r. done.

pwck: no changes
Loading system software
Uncompressing system image: bootflash:/m9500-sf2ek9-mz.5.0.1a.bin
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
CCCCCCCCCCCC
INIT: Entering runlevel: 3

```

 **Note** At this point, a switchover occurs to the new active supervisor module.

```

...
Install has been successful.

User Access Verification

209.165.200.226 login: admin
Password:
Cisco Storage Area Networking Operating System (SAN-OS) Software
TAC support: http://www.cisco.com/tac
Copyright (c) 2002-2011, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software may be covered under the GNU Public
License or the GNU Lesser General Public License. A copy of
each such license is available at
http://www.gnu.org/licenses/gpl.html and
http://www.gnu.org/licenses/lgpl.html

```

Step 13 Verify the status of the modules on the switch using the **show module** command.

```

switch# show module
Mod  Ports  Module-Type          Model                Status
---  ---  -
2    4      10 Gbps FC Module    DS-X9704             ok
3    48     1/2/4 Gbps FC Module DS-X9148             ok
5    0      Supervisor/Fabric-2  DS-X9530-SF2-K9     ha-standby

```

```

6      0      Supervisor/Fabric-2      DS-X9530-SF2-K9      active *

Mod  Sw              Hw      World-Wide-Name(s) (WWN)
---  -
2    5.2(1)           1.0     20:41:00:0b:fd:2c:90:c0 to 20:44:00:0b:fd:2c:90:c0
3    5.2(1)           0.302   20:81:00:0b:fd:2c:90:c0 to 20:b0:00:0b:fd:2c:90:c0
5    5.2(1)           1.4     --
6    5.2(1)           1.6     --
...

```

Downgrading from NX-OS Release 6.2(x) to NX-OS Release 5.2(x) on an MDS 9222i Switch

To downgrade from Cisco NX-OS Release 6.2(x) to Cisco NX-OS Release 5.2(x) on an MDS 9222i switch, follow these steps:

- Step 1** Verify that the system image files for the downgrade are present on the active supervisor module bootflash:.

```

switch# dir bootflash:
 12288      Aug 26 19:06:14 2011  lost+found/
18939904    Jul 01 10:54:49 2011  m9200-sf2ek9-kickstart-mz.5.2.x.bin
16858624    Jul 01 10:20:07 2011  m9200-sf2ek9-kickstart-mz.5.0.1a.bin
101756072   Jul 01 10:33:52 2011  m9200-sf2ek9-mz.5.2.x.bin
 95771404    Jul 01 10:18:09 2011  m9200-sf2ek9-mz.5.0.1a.bin

Usage for bootflash://sup-local
236338292 bytes used
142984076 bytes free
379322368 bytes total

```

- Step 2** If the software image file is not present, download it from an FTP or TFTP server to the active supervisor module bootflash:. You can obtain the software image file from the Cisco.com software download center at the following URL:

<http://www.cisco.com/cisco/software/navigator.html>



Note If you need more space on the active supervisor module bootflash:, use the **delete** command to remove unnecessary files and follow [Step 3](#) and [Step 4](#).

```

switch# copy tftp://tftpserver.cisco.com/MDS/m9200-sf2ek9-kickstart-mz.5.2.x.bin
bootflash:m9200-sf2ek9-kickstart-mz.5.2.x.bin
switch# copy tftp://tftpserver.cisco.com/MDS/m9200-sf2ek9-mz.5.2.x.bin
bootflash:m9200-sf2ek9-mz.5.2.x.bin

```

- Step 3** Ensure that the required space is available on the active supervisor.

```

switch# dir bootflash:
 12288      Aug 26 19:06:14 2011  lost+found/
18939904    Jul 01 10:54:49 2011  m9200-sf2ek9-kickstart-mz.5.2.x.bin
101756072   Jul 01 10:33:52 2011  m9200-sf2ek9-mz.5.2.x.bin

Usage for bootflash://sup-local
120695976 bytes used
 63863640 bytes free
184559616 bytes total

```

- Step 4** If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# del bootflash:m9200-sf2ek9-kickstart-mz.5.0.1a.bin
switch# del bootflash:m9200-sf2ek9-mz.5.0.1a.bin
```

- Step 5** Issue the **show incompatibility system *image-filename*** command to determine if you need to disable any features not supported by the earlier release.

```
switch# show incompatibility system bootflash:m9200-sf2ek9-mz.5.2.x.bin
The following configurations on active are incompatible with the system image
1) Service : port-channel , Capability : CAP_FEATURE_AUTO_CREATED_41_PORT_CHANNEL
Description : auto create enabled ports or auto created port-channels are present
Capability requirement : STRICT
Disable command :
1.Disable autcreate on interfaces (no channel-group auto).
2.Convert autcreated port channels to be persistent (port-channel 1 persistent)
...
```

- Step 6** Disable any features that are incompatible with the downgrade system image.

```
switch# configure terminal
Enter configuration commands, one per line. End with CNTL/Z.
switch(config)# interface fcip 31
switch(config-if)# no channel-group auto
switch(config-if)# end
switch# port-channel 127 persistent
switch#
```

- Step 7** Save the configuration using the **copy running-config startup-config** command.

```
switch# copy running-config startup-config
```

- Step 8** Issue the **install all** command to downgrade the software.

```
switch# install all kickstart bootflash:m9200-s2ek9-kickstart-mz.5.2.1.bin.S74 system
bootflash:m9200-s2ek9-mz.5.2.1.bin.S74
```

```
Verifying image bootflash:/m9200-s2ek9-kickstart-mz.5.2.1.bin.S74 for boot variable
"kickstart".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/m9200-s2ek9-mz.5.2.1.bin.S74 for boot variable "system".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image type.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "system" version from image bootflash:/m9200-s2ek9-mz.5.2.1.bin.S74.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "kickstart" version from image
bootflash:/m9200-s2ek9-kickstart-mz.5.2.1.bin.S74.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "bios" version from image bootflash:/m9200-s2ek9-mz.5.2.1.bin.S74.
```

```
[#####] 100% -- SUCCESS
```

Extracting "slc2" version from image bootflash:/m9200-s2ek9-mz.5.2.1.bin.S74.

[#####] 100% -- SUCCESS

Performing Compact Flash and TCAM sanity test.

[#####] 100% -- SUCCESS

Performing module support checks.

[#####] 100% -- SUCCESS

Notifying services about system upgrade.

[#####] 100% -- SUCCESS

Compatibility check is done:

Module	bootable	Impact	Install-type	Reason
1	yes	non-disruptive	reset	
2	yes	non-disruptive	rolling	

Other miscellaneous information for installation:

Module info

1 FC ports 1-18 are hitless, GigE 1-4 are hitful, and Intelligent Applications running are hitful

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version	Upg-Required
1	system	6.2(x)	5.2(1)	yes
1	kickstart	6.2(x)	5.2(1)	yes
1	bios	v1.0.19(02/01/10):	v1.0.19(02/01/10)	no
2	slc2	6.2(x)	5.2(1)	yes
2	bios	v1.0.19(02/01/10):	v1.0.19(02/01/10)	no

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.

[#####] 100% -- SUCCESS

Notifying services about the upgrade.

[#####] 100% -- SUCCESS

Setting boot variables.


```
[#####] 100% -- SUCCESS
Performing configuration copy.

[#####] 100% -- SUCCESS
Module 1: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS
Module 2: Refreshing compact flash and upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.

[#####] 100% -- SUCCESS
Upgrade can no longer be aborted, any failure will result in a disruptive upgrade.
Freeing memory in the file system.

[#####] 100% -- SUCCESS
Loading images into memory.

[#####] 100% -- SUCCESS
Saving external linecard runtime state.

2011 Aug 1 17:16:56 sw4-qa05 %IMAGE_DNLD-SLOT2-2-IMG_DNLD_STARTED: Module image download
process. Please wait until completion...

2011 Aug 1 17:17:16 sw4-qa05 %IMAGE_DNLD-SLOT2-2-IMG_DNLD_COMPLETE: Module image
download process. Download successful.

[#####] 100% -- SUCCESS
Saving linecard runtime state.

[#####] 100% -- SUCCESS
Saving supervisor runtime state.

[#####] 100% -- SUCCESS
Saving mts state.

[#####] 100% -- SUCCESS
Rebooting the switch to proceed with the upgrade.

All telnet and ssh connections will now be temporarily terminated.

Starting new kernel
Starting kernel...

Entered kgdb_console_init:1975
INIT: version 2.85 booting
Checking all filesystems..... done.
```

```

/etc/rc.d/rcS.d/S30procps: line 34: log_action_begin_msg: command not found

/etc/rc.d/rcS.d/S30procps: line 36: log_action_end_msg: command not found

Setting the System Clock using the Hardware Clock as reference...System Clock set. Local
time: Mon Aug  1 17:17:56 PDT 2011

Loading system software

Uncompressing system image: bootflash:///m9200-s2ek9-mz.5.2.1.bin.S74

CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC

Uncompressing linecard components

INIT: Entering runlevel: 3

Starting NFS servers: nfsd mountd.

2011 Aug  1 17:18:22 sw4-qa05 Aug  1 17:18:22 %KERN-2-SYSTEM_MSG: Starting kernel... -
kernel

2011 Aug  1 17:18:22 sw4-qa05 Aug  1 17:18:22 %KERN-1-SYSTEM_MSG: Entered
kgdb_console_init:1975 - kernel

Continuing with installation process, please wait.

The login will be disabled until the installation is completed.

2011 Aug  1 17:19:22 sw4-qa05 %PROC_MGR-2-MESG: Entity : (dnld_image) has exited
successfully

2011 Aug  1 17:19:29 sw4-qa05 %PLATFORM-2-PS_FAIL: Power supply 1 failed or shut down
(Serial number )

2011 Aug  1 17:19:29 sw4-qa05 %PLATFORM-2-PS_OK: Power supply 2 ok (Serial number
QCS104811U3)

2011 Aug  1 17:19:29 sw4-qa05 %PLATFORM-2-PS_FANOK: Fan in Power supply 2 ok

2011 Aug  1 17:19:29 sw4-qa05 %PLATFORM-2-FAN_OK: Fan module ok

2011 Aug  1 17:19:29 sw4-qa05 %PLATFORM-2-CHASSIS_CLKMODOK: Chassis clock module A ok

2011 Aug  1 17:19:29 sw4-qa05 %PLATFORM-2-CHASSIS_CLKMODOK: Chassis clock module B ok

2011 Aug  1 17:19:29 sw4-qa05 %PLATFORM-2-CHASSIS_CLKSRC: Current chassis clock source is
clock-A

Status for linecard upgrade.

[#####] 100% -- SUCCESS

Status for external linecard upgrade.
[#####] 100% -- SUCCESS
Performing supervisor state verification.

[#####] 100% -- SUCCESS
Install has been successful.

```

Step 9 Issue the **show version** command to verify the successful downgrade.

```
switch# show version
```

```
Cisco Nexus Operating System (NX-OS) Software
```

```
TAC support: http://www.cisco.com/tac
```

```
Copyright (c) 2002-2011, Cisco Systems, Inc. All rights reserved.
```

```
The copyrights to certain works contained herein are owned by  
other third parties and are used and distributed under license.
```

```
Some parts of this software are covered under the GNU Public  
License. A copy of the license is available at
```

```
http://www.gnu.org/licenses/gpl.html.
```

```
Software
```

```
BIOS:      version 1.0.15
```

```
loader:    version N/A
```

```
kickstart: version 5.2(1)
```

```
system:    version 5.2(1)
```

```
BIOS compile time:      07/16/11
```

```
kickstart image file is: bootflash:///m9200-s2ek9-kickstart-mz.5.2.x.bin
```

```
kickstart compile time: 8/22/2011 25:00:00 [08/25/2011 10:00:03]
```

```
system image file is:   bootflash:///m9200-s2ek9-mz.5.2.x.bin
```

```
system compile time:    8/22/2011 0:00:00 [08/25/2011 11:20:26]
```

```
Hardware
```

```
cisco MDS 9222i ("4x1GE IPS, 18x1/2/4Gbps FC/Sup2")
```

```
Motorola, e500v2 with 1036340 kB of memory.
```

```
Processor Board ID JAE11430NJM
```

```
Device name: 209.165.200.226
```

```
bootflash: 1000440 kB
```

```
Kernel uptime is 0 day(s), 0 hour(s), 4 minute(s), 15 second(s)
```

```
Last reset at 913177 usecs after Wed Aug 27 21:09:20 2011
```

```
Reason: Reset due to upgrade
```

```
System version: 5.2.x
```

```
Service:
```

Step 10 Verify the status of the modules on the switch using the **show module** command.

```
switch# show module
Mod  Ports  Module-Type                Model                Status
---  ---
1    22     4x1GE IPS, 18x1/2/4Gbps FC/Sup2  DS-C9222I-K9       active *
2    48     1/2/4 Gbps FC Module          DS-X9148            ok

Mod  Sw                Hw                World-Wide-Name(s) (WWN)
---  ---
1    5.0(1a)           0.610            20:01:00:05:30:00:00:00 to 20:12:00:05:30:00:00:00
2    5.0(1a)           0.302            20:41:00:05:30:00:00:00 to 20:70:00:05:30:00:00:00

Mod      Application Image Description          Application Image Version
-----
1        SSI linecard image (Packaged in SAN-OS) 5.0(1a)

Mod  MAC-Address(es)                Serial-Num
---  ---
1    00-17-5a-b5-72-80 to 00-17-5a-b5-72-88  JAE1123KANK
2    00-14-a9-74-db-30 to 00-14-a9-74-db-34  JAB093301JZ

* this terminal session
switch#
```

Downgrading from NX-OS Release 6.2(x) to NX-OS Release 5.2(x) on an MDS 9250i Switch

To downgrade from Cisco NX-OS Release 6.2(9) to Cisco NX-OS Release 5.2(x) or lower on an MDS 9250i switch, follow these steps:

Step 1 Verify that the system image files for the downgrade are present on the active supervisor module bootflash:.

```
switch# dir bootflash:
 4096   Jan 12 09:05:55 2001  .partner/
   692   Feb 06 18:22:33 2001  switch.lic
2155240 Apr 17 10:18:30 2001  d
2155240 Mar 21 15:33:26 2014  d1
2155240 Mar 18 10:15:41 2014  dplug627
20090368 Apr 06 05:25:31 2001  m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
20044800 Mar 30 15:42:05 2014  m9250-s5ek9-kickstart-mz.6.2.7.bin
107197681 Apr 06 05:26:53 2001  m9250-s5ek9-mz.6.2.5.bin.S68
107587249 Mar 30 15:42:52 2014  m9250-s5ek9-mz.6.2.7.bin
  29714  Mar 30 16:20:21 2014  mts.log
 2855303 Mar 30 14:14:36 2014  runn-fc
 2855147 Mar 26 15:05:30 2014  runn-mar26
 2777996 Mar 27 07:07:46 2014  runn-mar27
 2855147 Mar 27 04:51:08 2014  runn-mar27-preRel
 2777996 Mar 27 06:22:29 2014  runn-mar27-preRel-wozone
```

Step 2 If the software image file is not present, download it from an FTP or TFTP server to the active supervisor module bootflash:. You can obtain the software image file from the Cisco.com software download center at the following URL:

<http://www.cisco.com/cisco/software/navigator.html>



Note If you need more space on the active supervisor module bootflash:, use the **delete** command to remove unnecessary files and follow [Step 3](#) and [Step 4](#).

```
switch# copy tftp://tftpserver.cisco.com/MDS/m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
bootflash:m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
switch# copy tftp://tftpserver.cisco.com/MDS/m9250-s5ek9-mz.6.2.5.bin.S68
bootflash:m9250-s5ek9-mz.6.2.5.bin.S68
```

Step 3 Ensure that the required space is available on the active supervisor.

```
switch# dir bootflash:
12288      Aug 26 19:06:14 2011  lost+found/
18939904   Jul  01 10:54:49 2011  m9250-sf2ek9-kickstart-mz.6.2.5.bin
101756072  Jul  01 10:33:52 2011  m9250-sf2ek9-mz.6.2.5.bin
```

```
Usage for bootflash://sup-local
120695976 bytes used
63863640 bytes free
184559616 bytes total
```

Step 4 If you need more space on the active supervisor module bootflash, delete unnecessary files to make space available.

```
switch# del bootflash:m9250-sf2ek9-kickstart-mz.6.2.5.bin
switch# del bootflash:m9250-sf2ek9-kickstart-mz.6.2.5.bin
```

Step 5 Issue the **show incompatibility system image-filename** command to determine if you need to disable any features not supported by the earlier release.

```
switch# show incompatibility system bootflash:m9200-sf2ek9-mz.5.2.x.bin
no incompatible configuration
```

Step 6 Save the configuration using the **copy running-config startup-config** command.

```
switch# copy running-config startup-config
```

Step 7 Issue the **install all** command to downgrade the software.

```
switch# install all kickstart bootflash:m9250-s5ek9-kickstart-mz.6.2.5.bin.S68 system
bootflash:m9250-s5ek9-mz.6.2.5.bin.S68
Installer will perform compatibility check first. Please wait.
```

```
Verifying image bootflash:/m9250-s5ek9-kickstart-mz.6.2.5.bin.S68 for boot variable
"kickstart".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/m9250-s5ek9-mz.6.2.5.bin.S68 for boot variable "system".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image type.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "system" version from image bootflash:/m9250-s5ek9-mz.6.2.5.bin.S68.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "kickstart" version from image
```

```
bootflash:/m9250-s5ek9-kickstart-mz.6.2.5.bin.S68.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "bios" version from image bootflash:/m9250-s5ek9-mz.6.2.5.bin.S68.
```

```
[#####] 100% -- SUCCESS
```

Performing Compact Flash and TCAM sanity test.
 [#####] 100% -- SUCCESS

Performing module support checks.
 [#####] 100% -- SUCCESS

Notifying services about system upgrade.
 [#####] 100% -- SUCCESS

Compatibility check is done:

Module	bootable	Impact	Install-type	Reason
1	yes	non-disruptive	reset	

Other miscellaneous information for installation:

Module info

 1 FC ports 1-40 and FCoE ports 1-8 are hitless, IPS 1-2 are hitful, and Intelligent Applications running are hitful

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version
Upg-Required			
-----	-----	-----	-----
1	system	6.2(7)	6.2(5)
yes			
1	kickstart	6.2(7)	6.2(5)
yes			
1	bios	v2.1.16(10/24/13):v2.1.16(10/24/13)	v2.1.16(10/24/13)
no			

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.
 [#####] 100% -- SUCCESS

Notifying services about the upgrade.
 [#####] 100% -- SUCCESS

Setting boot variables.
 [#####] 100% -- SUCCESS

Performing configuration copy.
 [#####] 100% -- SUCCESS

Module 1: Refreshing compact flash and Upgrading bios/loader/bootrom.
 Warning: please do not remove or power off the module at this time.
 [#####] 100% -- SUCCESS

Converting startup config.
 [#####] 100% -- SUCCESS

Upgrade can no longer be aborted, any failure will result in a disruptive upgrade.

Freeing memory in the file system.
 [#####] 100% -- SUCCESS

```

Loading images into memory.
[#####] 100% -- SUCCESS

Saving linecard runtime state.
[#####] 100% -- SUCCESS

Saving supervisor runtime state.
[#####] 100% -- SUCCESS

Saving mts state.
[#####] 100% -- SUCCESS

Rebooting the switch to proceed with the upgrade.
All telnet and ssh connections will now be temporarily terminated.

>> NX7--LC-loader-02.01.16 (Oct 24 2013 - 16:00:49), Build: 02.01.16

CPU0: 8572E, Version: 2.1, (0x80e80021)
Core: E500, Version: 3.0, (0x80210030)
Clock Configuration:
      CPU:1066.672 MHz, CCB:533.336 MHz,
      DDR:266.668 MHz (533.336 MT/s data rate), LBC:33.334 MHz
L1:   D-cache 32 kB enabled
      I-cache 32 kB enabled
Board: 9044, IOFPGA: 0x0000001A, SPROM: 0xAB
Boot flash : Primary
I2C:   ready
DRAM:  Initializing
DDR:  dimm type 10, registered 1
DDR:  dimm type 10, registered 1
      DDR:   4 GB
L2:   1024 KB enabled
Using default environment

In:   serial
Out:  serial
Err:  serial
Net:  INFO: Net boot mode = 1
INFO: Net boot mode = 1
INFO: Board will come up MGMT interface
INFO: MAC address is: cc:fe:48:4a:5d:f0
      eTSEC2 board phy 3
INFO: Net boot mode = 1
eTSEC2
IDE:  Bus 0: OK
      Device 0: Model: SILICONSYSTEMS UDMA 4GB-4676 Firm: 3.38 Ser#: CC395293055000066K08
              Type: Hard Disk
              Capacity: 3919.7 MB = 3.8 GB (8027712 x 512)

Booting image bootflash://m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
20090368 bytes read
NBI at 08000000 size 134217728

Booting image at addr 0x00800000 ...
Memory <- <0x0 0x0 0x1 0x0> (4096MB)
ethernet0: local-mac-address <- cc:fe:48:4a:5d:f0
ethernet1: local-mac-address <- 00:e0:0c:00:01:fd
ethernet2: local-mac-address <- 00:e0:0c:00:02:fd
CPU clock-frequency <- 0x3f941f80 (1067MHz)
CPU timebase-frequency <- 0x3f941f8 (67MHz)
CPU bus-frequency <- 0x1fca0fc0 (533MHz)

```

```

zImage starting: loaded at 0x00800000 (sp: 0x7fedc4d0)
Allocating 0x4d7464 bytes for kernel ...
gunzipping (0x00000000 <- 0x0080f000:0x00calb94)...done 0x478774 bytes
Using loader supplied ramdisk at 0x2700000-0x3831a00
initrd head: 0x1f8b0808

```

```

Linux/PowerPC load: rw root=/dev/ram0 rdbase=0x7000000 card_index=9044 maxcpus=2 ip=off
ramdisk_size=262144 noquiet obfl_type_id=1 kgdboc=ttyS0,9600,B isanimg_loc=0x6000000
isanimg_size=0x400 console=ttyS0,9600n8nn loader_ver="02.01.16" card_index=9044 quiet
bootdev=ide0 server_ip=171.69.21.28 ksimg=/m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
isanimg=/m9250-s5ek9-mz.6.2.5.bin.S68
Finalizing device tree... flat tree at 0x80be70
Jumping to kernel at 0
setup_arch: bootmem
mpc85xx_ds_setup_arch()
arch: exit

```

```

[ 1.522927] Host controller irq 26
[ 1.564107] pci 0000:00:00.0: ignoring class b20 (doesn't match header type 01)
[ 1.682399] Assign root port irq 26 for 0000:00:00.0
[ 1.983375] Enabling all PCI devices
INIT: Checking all filesystems..... done.
Setting kernel variables done.
Setting the System Clock using the Hardware Clock as reference...System Clock set. Local
time: Thu Mar 27 10:19:08 UTC 2014
Loading system software
Uncompressing system image: bootflash:///m9250-s5ek9-mz.6.2.5.bin.S68
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
Load plugins that defined in image conf: /isan/plugin_img/img.conf
Loading plugin 0: core_plugin...
num srgs 1
0: swid-core-s5ek9, swid-core-s5ek9
num srgs 1
0: swid-sup-ali-ks, swid-sup-ali-ks
INIT: Entering runlevel: 3

[ 81.048355] clpk_hw_init_1:Post ISSU instance 0 status 0x00000736 GOOD
[ 81.126871] clpk_hw_init_1:Post ISSU instance 1 status 0x00000536 GOOD
2014 Mar 27 10:20:10 switch Mar 27 10:20:10 %KERN-0-SYSTEM_MSG: [ 1.983375] Enabling
all PCI devices - kernel
2014 Mar 27 10:20:10 switch Mar 27 10:20:10 %KERN-0-SYSTEM_MSG: [ 81.048355]
clpk_hw_init_1:Post ISSU instance 0 status 0x00000736 GOOD - kernel
2014 Mar 27 10:20:10 switch Mar 27 10:20:10 %KERN-0-SYSTEM_MSG: [ 81.126871]
clpk_hw_init_1:Post ISSU instance 1 status 0x00000536 GOOD - kernel
Sysmgr failed to send GET_TIME_OF_DAY Call_cnt= 1 errno= 32
2014 Mar 27 10:20:32 switch %CARDCLIENT-2-REG: OK
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...

```

```

Continuing with installation process, please wait.
The login will be disabled until the installation is completed.

```

```

Status for linecard upgrade.
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_FAIL: Power supply 1 failed or shut down
(Serial number QCS1549K0HU)
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_OK: Power supply 2 ok (Serial number
QCS1549K087)
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_FANOK: Fan in Power supply 2 ok
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_OK: Power supply 3 ok (Serial number
QCS1549K0T5)
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_FANOK: Fan in Power supply 3 ok

```



```
2014 Mar 27 10:21:49 switch %PLATFORM-2-ALISHAN_FAN_OK: Fan module 1 ok
2014 Mar 27 10:21:49 switch %PLATFORM-2-ALISHAN_FAN_OK: Fan module 2 ok
[#####] 100% -- SUCCESS
```

Performing supervisor state verification.

```
2014 Mar 27 10:21:50 switch %PLATFORM-2-PS_ALI_TWO_POWERSUPPLY: Only two Power supply are
functional, please connect third Power Supply for redundancy
[#####] 100% -- SUCCESS
```

Install has been successful.

User Access Verification
switch login:

Step 8 Issue the **show version** command to verify the successful downgrade.

```
switch# show version
```

```
install all kickstart bootflash:m9250-s5ek9-kickstart-mz.6.2.5.bin.S68 system
bootflash:m9250-s5ek9-mz.6.2.5.bin.S68
Installer will perform compatibility check first. Please wait.
```

```
Verifying image bootflash:/m9250-s5ek9-kickstart-mz.6.2.5.bin.S68 for boot variable
"kickstart".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/m9250-s5ek9-mz.6.2.5.bin.S68 for boot variable "system".
```

```
[#####] 100% -- SUCCESS
```

```
Verifying image type.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "system" version from image bootflash:/m9250-s5ek9-mz.6.2.5.bin.S68.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "kickstart" version from image
```

```
bootflash:/m9250-s5ek9-kickstart-mz.6.2.5.bin.S68.
```

```
[#####] 100% -- SUCCESS
```

```
Extracting "bios" version from image bootflash:/m9250-s5ek9-mz.6.2.5.bin.S68.
```

```
[#####] 100% -- SUCCESS
```

```
Performing Compact Flash and TCAM sanity test.
```

```
[#####] 100% -- SUCCESS
```

```
Performing module support checks.
```

```
[#####] 100% -- SUCCESS
```

```
Notifying services about system upgrade.
```

```
[#####] 100% -- SUCCESS
```

Compatibility check is done:

Module	bootable	Impact	Install-type	Reason
1	yes	non-disruptive	reset	

Other miscellaneous information for installation:

```
Module info
```

```
-----
```

```
1 FC ports 1-40 and FCoE ports 1-8 are hitless, IPS 1-2 are hitful, and Intelligent
Applications running are hitful
```

```

Images will be upgraded according to following table:
Module      Image      Running-Version(pri:alt)      New-Version
Upg-Required
-----
-----
      1      system      6.2(7)      6.2(5)
yes
      1      kickstart  6.2(7)      6.2(5)
yes
      1      bios      v2.1.16(10/24/13):v2.1.16(10/24/13)  v2.1.16(10/24/13)
no

```

Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Performing runtime checks.
[#####] 100% -- SUCCESS

Notifying services about the upgrade.
[#####] 100% -- SUCCESS

Setting boot variables.
[#####] 100% -- SUCCESS

Performing configuration copy.
[#####] 100% -- SUCCESS

Module 1: Refreshing compact flash and Upgrading bios/loader/bootrom.
Warning: please do not remove or power off the module at this time.
[#####] 100% -- SUCCESS

Converting startup config.
[#####] 100% -- SUCCESS

Upgrade can no longer be aborted, any failure will result in a disruptive upgrade.

Freeing memory in the file system.
[#####] 100% -- SUCCESS

Loading images into memory.
[#####] 100% -- SUCCESS

Saving linecard runtime state.
[#####] 100% -- SUCCESS

Saving supervisor runtime state.
[#####] 100% -- SUCCESS

Saving mts state.
[#####] 100% -- SUCCESS

Rebooting the switch to proceed with the upgrade.
All telnet and ssh connections will now be temporarily terminated.

>> NX7--LC-loader-02.01.16 (Oct 24 2013 - 16:00:49), Build: 02.01.16

```

CPU0: 8572E, Version: 2.1, (0x80e80021)
Core: E500, Version: 3.0, (0x80210030)
Clock Configuration:
      CPU:1066.672 MHz, CCB:533.336 MHz,

```

```

        DDR:266.668 MHz (533.336 MT/s data rate), LBC:33.334 MHz
L1:   D-cache 32 kB enabled
      I-cache 32 kB enabled
Board: 9044, IOFPGA: 0x0000001A, SPROM: 0xAB
Boot flash : Primary
I2C:   ready
DRAM:  Initializing
DDR: dimm type 10, registered 1
DDR: dimm type 10, registered 1
      DDR: 4 GB
L2:   1024 KB enabled
Using default environment

In:    serial
Out:   serial
Err:   serial
Net:   INFO: Net boot mode = 1
INFO:  Net boot mode = 1
INFO:  Board will come up MGMT interface
INFO:  MAC address is: cc:fe:48:4a:5d:f0
      eTSEC2 board phy 3
INFO:  Net boot mode = 1
eTSEC2
IDE:   Bus 0: OK
      Device 0: Model: SILICONSYSTEMS UDMA 4GB-4676 Firm: 3.38 Ser#: CC395293055000066K08
              Type: Hard Disk
              Capacity: 3919.7 MB = 3.8 GB (8027712 x 512)

Booting image bootflash://m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
20090368 bytes read
NBI at 08000000 size 134217728

Booting image at addr 0x00800000 ...
Memory <- <0x0 0x0 0x1 0x0> (4096MB)
ethernet0: local-mac-address <- cc:fe:48:4a:5d:f0
ethernet1: local-mac-address <- 00:e0:0c:00:01:fd
ethernet2: local-mac-address <- 00:e0:0c:00:02:fd
CPU clock-frequency <- 0x3f941f80 (1067MHz)
CPU timebase-frequency <- 0x3f941f8 (67MHz)
CPU bus-frequency <- 0x1fca0fc0 (533MHz)

zImage starting: loaded at 0x00800000 (sp: 0x7fedc4d0)
Allocating 0x4d7464 bytes for kernel ...
gunzipping (0x00000000 <- 0x0080f000:0x00ca1b94)...done 0x478774 bytes
Using loader supplied ramdisk at 0x27000000-0x3831a00
initrd head: 0x1f8b0808

Linux/PowerPC load: rw root=/dev/ram0 rdbase=0x70000000 card_index=9044 maxcpus=2 ip=off
ramdisk_size=262144 noquiet obfl_type_ide=1 kgdboc=ttyS0,9600,B isanimg_loc=0x6000000
isanimg_size=0x400 console=ttyS0,9600n8nn loader_ver="02.01.16" card_index=9044 quiet
bootdev=ide0 server_ip=171.69.21.28 ksimg=/m9250-s5ek9-kickstart-mz.6.2.5.bin.S68
isanimg=/m9250-s5ek9-mz.6.2.5.bin.S68
Finalizing device tree... flat tree at 0x80be70
Jumping to kernel at 0
setup_arch: bootmem
mpc85xx_ds_setup_arch()
arch: exit

[ 1.522927] Host controller irq 26
[ 1.564107] pci 0000:00:00.0: ignoring class b20 (doesn't match header type 01)
[ 1.682399] Assign root port irq 26 for 0000:00:00.0
[ 1.983375] Enabling all PCI devices
INIT: Checking all filesystems..... done.
Setting kernel variables done.

```

```

Setting the System Clock using the Hardware Clock as reference...System Clock set. Local
time: Thu Mar 27 10:19:08 UTC 2014
Loading system software
Uncompressing system image: bootflash:///m9250-s5ek9-mz.6.2.5.bin.S68
CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
Load plugins that defined in image conf: /isan/plugin_img/img.conf
Loading plugin 0: core_plugin...
num srgs 1
0: swid-core-s5ek9, swid-core-s5ek9
num srgs 1
0: swid-sup-ali-ks, swid-sup-ali-ks
INIT: Entering runlevel: 3

[ 81.048355] clpk_hw_init_1:Post ISSU instance 0 status 0x00000736 GOOD
[ 81.126871] clpk_hw_init_1:Post ISSU instance 1 status 0x00000536 GOOD
2014 Mar 27 10:20:10 switch Mar 27 10:20:10 %KERN-0-SYSTEM_MSG: [ 1.983375] Enabling
all PCI devices - kernel
2014 Mar 27 10:20:10 switch Mar 27 10:20:10 %KERN-0-SYSTEM_MSG: [ 81.048355]
clpk_hw_init_1:Post ISSU instance 0 status 0x00000736 GOOD - kernel
2014 Mar 27 10:20:10 switch Mar 27 10:20:10 %KERN-0-SYSTEM_MSG: [ 81.126871]
clpk_hw_init_1:Post ISSU instance 1 status 0x00000536 GOOD - kernel
Sysmgr failed to send GET_TIME_OF_DAY Call_cnt= 1 errno= 32
2014 Mar 27 10:20:32 switch %CARDCLIENT-2-REG: OK
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...
System is coming up ... Please wait ...

Continuing with installation process, please wait.
The login will be disabled until the installation is completed.

Status for linecard upgrade.
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_FAIL: Power supply 1 failed or shut down
(Serial number QCS1549K0HU)
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_OK: Power supply 2 ok (Serial number
QCS1549K087)
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_FANOK: Fan in Power supply 2 ok
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_OK: Power supply 3 ok (Serial number
QCS1549K0T5)
2014 Mar 27 10:21:49 switch %PLATFORM-2-PS_FANOK: Fan in Power supply 3 ok
2014 Mar 27 10:21:49 switch %PLATFORM-2-ALISHAN_FAN_OK: Fan module 1 ok
2014 Mar 27 10:21:49 switch %PLATFORM-2-ALISHAN_FAN_OK: Fan module 2 ok
[#####] 100% -- SUCCESS

Performing supervisor state verification.
2014 Mar 27 10:21:50 switch %PLATFORM-2-PS_ALI_TWO_POWERSUPPLY: Only two Power supply are
functional, please connect third Power Supply for redundancy
[#####] 100% -- SUCCESS

Install has been successful.

User Access Verification
switch login:

```

Step 9 Verify the status of the modules on the switch using the **show module** command.

```
switch# show module
```

Mod	Ports	Module-Type	Model	Status
1	50	40FC+8FCoE+2IPS Supervisor	DS-C9250I-K9-SUP	active *

```

Mod Sw                Hw      World-Wide-Name(s) (WWN)
--- -----
1   6.2(7)             0.0    20:01:54:7f:ee:1b:10:20 to 20:28:54:7f:ee:1b:10:20

Mod MAC-Address(es)          Serial-Num
--- -----
1   cc-fe-48-4a-5d-f0 to cc-fe-48-4a-5d-ff  JAF1605AMHH

* this terminal session

switch#

```

Nondisruptive Upgrades on Fabric and Modular Switches

This section describes how to perform nondisruptive upgrades on the following Cisco fabric switches:

- Cisco MDS 9148 Multilayer Fabric Switch
- Cisco MDS 9222i Multiservice Modular Switch
- Cisco MDS 9250i Multiservice Modular Switch
- Cisco MDS 9396S Multilayer Fabric Switch

This section includes the following topics:

- [Preparing for a Nondisruptive Upgrade on Fabric and Modular Switches, page 93](#)
- [Performing a Nondisruptive Upgrade on a Fabric Switch, page 96](#)
- [Displaying the Status of a Nondisruptive Upgrade on a Fabric Switch, page 97](#)
- [Troubleshooting a Nondisruptive Upgrade on a Fabric Switch, page 98](#)

Preparing for a Nondisruptive Upgrade on Fabric and Modular Switches

You can upgrade software on the following switches without any disruptions by using the **install all** command for the system software images:

- Cisco MDS 9148 Multilayer Fabric Switch
- Cisco MDS 9148S Multilayer Fabric Switch
- Cisco MDS 9222i Multiservice Modular Switch
- Cisco MDS 9250i Multiservice Modular Switch

When the installation is completed, the supervisor kickstart image, supervisor system image, line card image, and the system BIOS are all updated.

Nondisruptive upgrades on these fabric switches disrupts the control plane for not more than 80 seconds. The software upgrade might be disruptive if the upgrade progresses beyond when it can be stopped gracefully or if a failure occurs.

**Note**

During the upgrade the control plane is down, but the data plane remains up. New devices are not able to log in to the fabric through the control plane, but existing devices do not experience any disruption of traffic through the data plane.

Before attempting to upgrade any software images on the fabric switches, follow these guidelines:

- During the upgrade, the fabric must be stable. Do not perform these configuration activities during the upgrade:
 - Zoning changes
 - Telnet sessions
 - Schedule changes
 - Switch cabling
 - Addition or removal of physical devices
- Configure the FSPF timers to the default value of 20 seconds.
- If any CFS commits are pending in the fabric, the upgrade is aborted.
- If a zone server merge is in progress, the upgrade is aborted.
- If the upgrade is aborted due to a service not being ready for the upgrade, you are prompted to enter the **show install all failure-reason** command to identify the reason.
- If the system has insufficient space to load the new images, then you will be notified through the compatibility table. At this point, you need to either abort the upgrade or proceed with a disruptive upgrade.
- Check whether sufficient space is available in the system to load the new images by using the Software Install Wizard. Depending on the available space, you need to either abort the upgrade or proceed with a disruptive upgrade.
- Enter the **no logging level all** command before beginning the upgrade. If you do not enter this command, a failure might occur due to the debug system log messages being printed, which potentially can result in the control plane downtime to exceed 80 seconds.
- If VRRP is running on the mgmt0 interface, and the switch being upgraded is the master, then a new master is selected. This situation cannot be avoided because the mgmt0 interface goes down when the control plane goes down.
- On the Cisco MDS 18/4-port multiservice module, upgrades of the 4-Gigabit Ethernet ports for the hybrid Supervisor 18/4 line card will be disruptive.

To ensure that you can view the entire upgrade process, you should perform the upgrade by using the console port. By performing the upgrade this way, you can log your session to a file (in case you need it later for troubleshooting). Telnet sessions are lost when the switch is rebooted, so if you want to view the process in its entirety, be sure to use the console port.

The following section shows an example of the failed nondisruptive upgrade due to insufficient resources.

Example 1-1 Failed Nondisruptive Upgrade Due to Insufficient Resources

```
switch# install all kickstart bootflash:boot-fs9148 system bootflash:isan-164

Verifying image bootflash:/boot-fs9148 for boot variable "kickstart".
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/isan-164 for boot variable "system".
[#####] 100% -- SUCCESS
```

```
Extracting "system" version from image bootflash:/isan-164.
[#####] 100% -- SUCCESS
```

```
Extracting "kickstart" version from image bootflash:/boot-fs9148.
[#####] 100% -- SUCCESS
```

```
Extracting "bios" version from image bootflash:/isan-164.
[#####] 100% -- SUCCESS
```

Compatibility check is done:

Module	bootable	Impact	Install-type	Reason
1	yes	disruptive	reset	insufficient resources<----Reason for failure

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version	Upg-Required
1	system	5.2(x)	6.2(x)	yes
1	kickstart	5.2(x)	6.2(x)	yes
1	bios	v1.0.0(10/04/06):v1.0.0(10/04/06)	v1.0.0(10/04/06)	no

Do you want to continue with the installation (y/n)? [n]

Before performing an upgrade, you may wish to use the **show install all impact** command to view the effect of updating the system from the running image to another specified image.

```
switch# show install all impact kickstart bootflash:boot-fs9148 system bootflash:isan-164
```

```
Verifying image bootflash:/boot-fs9148 for boot variable "kickstart".
[#####] 100% -- SUCCESS
```

```
Verifying image bootflash:/isan-164 for boot variable "system".
[#####] 100% -- SUCCESS
```

```
Extracting "system" version from image bootflash:/isan-164.
[#####] 100% -- SUCCESS
```

```
Extracting "kickstart" version from image bootflash:/boot-fs9148.
[#####] 100% -- SUCCESS
```

```
Extracting "bios" version from image bootflash:/isan-164.
[#####] 100% -- SUCCESS
```

Compatibility check is done:

Module	bootable	Impact	Install-type	Reason
1	yes	non-disruptive	reset	

Images will be upgraded according to following table:

Module	Image	Running-Version(pri:alt)	New-Version	Upg-Required
1	system	5.2(x)	6.2(x)	yes
1	kickstart	5.2(x)	6.2(x)	yes
1	bios	v1.0.0(10/04/06):v1.0.0(10/04/06)	v1.0.0(10/04/06)	no

```
switch#
```

Performing a Nondisruptive Upgrade on a Fabric Switch

You can perform a nondisruptive software upgrade on any of the following switches by entering the **install all kickstart** command using the console port:

- Cisco MDS 9148 Multilayer Fabric Switch
- Cisco MDS 9148S Multilayer Fabric Switch
- Cisco MDS 9222i Multiservice Modular Switch
- Cisco MDS 9250i Multiservice Modular Switch
- Cisco MDS 9396S Multilayer Fabric Switch

The following is an example of the nondisruptive upgrade on a fabric switch:

```
switch# install all kickstart bootflash:boot-fs9148 system bootflash:isan-164u

Verifying image bootflash:/boot-fs9148 for boot variable "kickstart".
[#####] 100% -- SUCCESS

Verifying image bootflash:/isan-164u for boot variable "system".
[#####] 100% -- SUCCESS

Extracting "system" version from image bootflash:/isan-164u.
[#####] 100% -- SUCCESS

Extracting "kickstart" version from image bootflash:/boot-fs9148.
[#####] 100% -- SUCCESS

Extracting "bios" version from image bootflash:/isan-164u.
[#####] 100% -- SUCCESS

Compatibility check is done:
Module  bootable          Impact  Install-type  Reason
-----  -----
      1      yes  non-disruptive      reset

Images will be upgraded according to following table:
Module      Image  Running-Version(pri:alt)      New-Version      Upg-Required
-----  -----
      1      system  5.2(x)                        6.2(x)           yes
      1  kickstart  5.2(x)                        6.2(x)           yes
      1      bios  v1.0.0(10/04/06): v1.0.0(10/04/06)  v1.0.0(10/04/06)  no

Do you want to continue with the installation (y/n)? [n]

Install is in progress, please wait.

Notifying services about the upgrade.
[#####] 100% -- SUCCESS

Setting boot variables.
[#####] 100% -- SUCCESS

Performing configuration copy.
[#####] 100% -- SUCCESS

Converting startup config.
[#####] 100% -- SUCCESS

Upgrade can no longer be aborted, any failure will result in a disruptive upgrade.
<---Note that after this point you cannot abort the upgrade.
```



```

Freeing memory in the file system.
[#####] 100% -- SUCCESS

Loading images into memory.
[#####] 100% -- SUCCESS

Saving linecard runtime state.
[#####] 100% -- SUCCESS

Saving supervisor runtime state.
[#####] 100% -- SUCCESS

Saving mts state.
[#####] 100% -- SUCCESS

Rebooting the switch to proceed with the upgrade.

Continuing with installation process, please wait.
The login will be disabled until the installation is completed.

Status for linecard upgrade.
[#####] 100% -- SUCCESS

Performing supervisor state verification.
[#####] 100% -- SUCCESS

Install has been successful.

```

You can use the Software Install Wizard to perform nondisruptive upgrades on Cisco MDS 9148 Fabric Switches.



Caution

We recommend that you enable PortFast on the Ethernet interface of the Catalyst switch to which the management interface of the fabric switch is connected. This step action avoids spanning tree convergence time on the Catalyst switch, and immediately forwards packets from the fabric switch during the nondisruptive upgrade.



Note

ASM-SFN and SSI images are not supported for upgrades on the Cisco MDS 9148 Multilayer Fabric Switch.

Displaying the Status of a Nondisruptive Upgrade on a Fabric Switch

You can display the status of a nondisruptive upgrade by using the **show install all status** command. The output displays the status only after the switch has rebooted with the new image. All actions preceding the reboot are not captured in this output because when you enter the **install all** command using a Telnet session, the session is disconnected when the switch reboots. When you can reconnect to the switch through a Telnet session, the upgrade might already be complete, in which case, the output will display the status of the upgrade.

```

switch# show install all status
This is the log of last installation.

```

```

Continuing with installation process, please wait.
The login will be disabled until the installation is completed.

```

```
Status for linecard upgrade.
-- SUCCESS

Performing supervisor state verification.
-- SUCCESS

Install has been successful.
```

Troubleshooting a Nondisruptive Upgrade on a Fabric Switch

When a nondisruptive upgrade begins, the system notifies all services that an upgrade is about to start, and finds out whether or not the upgrade can proceed. If a service cannot allow the upgrade to proceed at this time (for example, FSPF timers are not configured to the default value, or a CFS operation is in progress), then the service aborts the upgrade. If this situation occurs, you are prompted to enter the **show install all failure-reason** command to determine the reason why the upgrade cannot proceed.

```
...
Do you want to continue with the installation (y/n)? [n] y

Install is in progress, please wait.

Notifying services about the upgrade.
[#           ] 0% -- FAIL. Return code 0x401E0066 (request timed out).

Please issue "show install all failure-reason" to find the cause of the failure.<---system
prompt to enter the show all failure-reason command.

Install has failed. Return code 0x401E0066 (request timed out).
Please identify the cause of the failure, and try 'install all' again.

switch# show install all failure-reason
Service: "cfs" failed to respond within the given time period.
switch#
```

Once the upgrade is already in progress if any failures occur for whatever reason (for example, a save runtime state failure or line card upgrade failure), then the switch is rebooted disruptively because the changes cannot be rolled back. In this case, the upgrade fails, but you are not prompted to enter the **show install all failure-reason** command; entering it will not yield any useful information.

If you need additional information to determine why an upgrade is unsuccessful, you can obtain the details from the **show tech-support** command output and from the console output from the installation, if available.

Related Documentation

The documentation set for the Cisco MDS 9000 Family includes the following documents. To find a document online, use the Cisco MDS NX-OS Documentation Locator at:

http://www.cisco.com/en/US/docs/storage/san_switches/mds9000/roadmaps/doclocator.htm

Release Notes

- *Cisco MDS 9000 Family Release Notes for Cisco MDS NX-OS Releases*
- *Cisco MDS 9000 Family Release Notes for MDS SAN-OS Releases*
- *Cisco MDS 9000 Family Release Notes for Cisco MDS 9000 EPLD Images*
- *Cisco DCNM Release Notes*

Regulatory Compliance and Safety Information

- *Regulatory Compliance and Safety Information for the Cisco MDS 9000 Family*

Compatibility Information

- *Cisco Data Center Interoperability Support Matrix*
- *Cisco MDS 9000 NX-OS Hardware and Software Compatibility Information and Feature Lists*
- *Cisco MDS 9000 Family Switch-to-Switch Interoperability Configuration Guide*

Hardware Installation

- *Cisco MDS 9700 Series Hardware Installation Guide*
- *Cisco MDS 9500 Series Hardware Installation Guide*
- *Cisco MDS 9250i Series Hardware Installation Guide*
- *Cisco MDS 9200 Series Hardware Installation Guide*
- *Cisco MDS 9100 Series Hardware Installation Guide*
- *Cisco MDS 9148S Series Hardware Installation Guide*
- *Cisco MDS 9148S Multilayer Switch Quick Start Guide*
- *Cisco MDS 9396 Series Hardware Installation Guide*

Software Installation and Upgrade

- *Cisco MDS 9000 NX-OS Software Upgrade and Downgrade Guide*
- *Cisco MDS 9000 Family Storage Services Interface Image Install and Upgrade Guide*
- *Cisco MDS 9000 Family Storage Services Module Software Installation and Upgrade Guide*

Cisco NX-OS

- *Cisco MDS 9000 Family NX-OS Licensing Guide*
- *Cisco MDS 9000 Family NX-OS Fundamentals Configuration Guide*
- *Cisco MDS 9000 Family NX-OS System Management Configuration Guide*

- *Cisco MDS 9000 Family NX-OS Interfaces Configuration Guide*
- *Cisco MDS 9000 Family NX-OS Fabric Configuration Guide*
- *Cisco MDS 9000 Family NX-OS Quality of Service Configuration Guide*
- *Cisco MDS 9000 Family NX-OS Security Configuration Guide*
- *Cisco MDS 9000 Family NX-OS IP Services Configuration Guide*
- *Cisco MDS 9000 Family NX-OS Intelligent Storage Services Configuration Guide*
- *Cisco MDS 9000 Family NX-OS High Availability and Redundancy Configuration Guide*
- *Cisco MDS 9000 Family NX-OS Inter-VSAN Routing Configuration Guide*
- *Cisco MDS 9000 Family Cookbook for Cisco MDS SAN-OS*

Cisco DCNM-SAN

- *Cisco DCNM Fundamentals Guide*
- *System Management Configuration Guide, Cisco DCNM for SAN*
- *Interfaces Configuration Guide, Cisco DCNM for SAN*
- *Fabric Configuration Guide, Cisco DCNM for SAN*
- *Quality of Service Configuration Guide, Cisco DCNM for SAN*
- *Security Configuration Guide, Cisco DCNM for SAN*
- *IP Services Configuration Guide, Cisco DCNM for SAN*
- *Intelligent Storage Services Configuration Guide, Cisco DCNM for SAN*
- *High Availability and Redundancy Configuration Guide, Cisco DCNM for SAN*
- *Inter-VSAN Routing Configuration Guide, Cisco DCNM for SAN*
- *SMI-S and Web Services Programming Guide, Cisco DCNM for SAN*

Command-Line Interface

- *Cisco MDS 9000 Family Command Reference*

Intelligent Storage Networking Services Configuration Guides

- *Cisco MDS 9000 I/O Acceleration Configuration Guide*
- *Cisco MDS 9000 Family SANTap Deployment Guide*
- *Cisco MDS 9000 Family Data Mobility Manager Configuration Guide*
- *Cisco MDS 9000 Family Storage Media Encryption Configuration Guide*
- *Cisco MDS 9000 Family Secure Erase Configuration Guide*

Troubleshooting and Reference

- *Cisco MDS 9000 Family and Nexus 7000 Series System Messages Reference*

- *Cisco MDS 9000 Family NX-OS Troubleshooting Guide*
- *Cisco MDS 9000 Family NX-OS MIB Quick Reference*
- *Cisco DCNM for SAN Database Schema Reference*

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS version 2.0.

This document is to be used in conjunction with the documents listed in the “[Related Documentation](#)” section.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2012-2014 Cisco Systems, Inc. All rights reserved.

