



## SNMP: Frequently Asked Questions About IOS Software

TAC Notice: What's Changing on TAC Web

Document ID: 26010	Help us help you.		
	Please rate this document.		
	© Excellent		
Questions	Good		
	Average		
<u>Introduction</u>	Fair		
The IP-SNMP CPU process on my router spikes to 90 percent (or more). Is this a bug?	C Poor		
<b>Does Cisco IOS Software support subinterfaces in the if Table?</b>	This document solved my problem.		
How can I reload a router with use of SNMP?	© Yes		
NetPro Discussion Forums - Featured Conversations	No     No		
Related Information	Just browsing		
	Suggestions for improvement:		
Introduction			
This document provides answers to commonly asked questions and guides users to find helpful resources on Simple Network Management Protocol. (SNMP) and SNMP issues as the issues relate to Cisco equipment.	(256 character limit)		

# Q. The IP-SNMP CPU process on my router spikes to 90 percent (or more). Is this a bug?

**A.** No, this is not a bug. IP-SNMP can take up 90 percent of the CPU on the router when the router is lightly loaded with other tasks; this situation is not unusual. IP-SNMP runs at a low priority. A CPU usage of 90 percent or higher means that the router has the bandwidth to spend more time on SNMP.

However, under heavy use, the CPU usage can approach 100 percent and starve low-priority processes. An example of heavy use is the retrieval of large tables (such as autodiscovery retrieval of the ipRouteTable and ipNetToMediaTable) by a network management application.

Under certain circumstances, the IP-SNMP process can consume almost all the CPU resources. The process can starve other processes and cause erratic behavior in the device. The most obvious symptom is the loss of TCP connections to the device. The most likely

cause of the problem is the send of a flurry of SNMP requests to the device in a short period of time, which causes the retrieval of large amounts of data. This behavior is usually associated with network auto discovery mechanisms that retrieve the entire Address Resolution Protocol (ARP) cache of the device and IP routing table on a periodic basis.

Some network management applications can exacerbate the problem. Some of these applications, by default, perform auto discovery as often as every 5 minutes.

A partial workaround is to identify the devices that perform auto discovery and modify the default behavior.

Another workaround is to force the router to prematurely end the queries for the IP route table and ARP cache from the network management system server. Configure the router to respond with a **complete** message as soon as the router receives the start of a request for the IP route table or ARP cache. Refer to the document IP Simple Network Management Protocol (SNMP) Causes High CPU Utilization for an example of how to do this configuration on a Cisco router.

#### Q. Does Cisco IOS Software support subinterfaces in the if Table?

A. RFC 1573 IF-MIB implements support for subinterfaces. (RFC 2233 and RFC 2863 obsolete RFC 1573 ).) It allows the use of VLANs, Frame Relay data-link connection identifiers (DLCIs), and X.25 virtual circuits (VCs) as subinterfaces to appear in the ifTable. RFC 1213 introduced the ifTable, and RFC 1573 enhanced the ifTable. One of the enhancements is to allow nonphysical interfaces to exist in the ifTable.

Generic support for sublayers in the ifTable has been present since Cisco IOS Software Release 11.1(1). The groups that support any given media type must determine (with direction from the Internet Engineering Task Force [IETF]) whether sublayers are appropriate for that media type. The groups must also determine how to support those sublayers.

Subinterface	Supported Since			
ATM	Cisco IOS Software Release 12.0(1)T			
Frame Relay	Cisco IOS Software Release 11.1			
LANE <sup>1</sup>	Cisco IOS Software Release 11.1			
• FE <sup>2</sup> • GE <sup>3</sup>	<ul> <li>Cisco IOS Software Release 12.0(21)         S—(IEEE 802.1Q encapsulation)</li> <li>Cisco IOS Software Release 12.1(3)         T—Cisco bug ID <u>CSCdk25367</u>         (registered customers only) (Cisco Inter-Switch Link Protocol [ISL]         encapsulation support)</li> <li>Cisco IOS Software Release 12.1(7)         E—Cisco bug ID <u>CSCds76462</u>         (registered customers only) (Cisco ISL encapsulation support)</li> </ul>			

• Cisco IOS Software Release 12.2
(6.8)—Cisco bug ID <u>CSCds00250</u>
( registered customers only) (IEEE 802.1Q
encapsulation)

<sup>&</sup>lt;sup>1</sup> LAN Emulation

#### Q. How can I reload a router with use of SNMP?

#### **A.** Follow this procedure:

On the Cisco router, you must set these commands to support the **reload** command:

```
snmp-server community private RW
snmp-server system-shutdown
```

This example reloads the router with IP address 10.16.99.55:

### **NetPro Discussion Forums - Featured Conversations**

Networking Professionals Connection is a forum for networking professionals to share questions, suggestions, and information about networking solutions, products, and technologies. The featured links are some of the most recent conversations available in this technology.

```
NetPro Discussion Forums - Featured Conversations for Network Management
Network Infrastructure: Network Management
```

<sup>&</sup>lt;sup>2</sup> Fast Ethernet

<sup>&</sup>lt;sup>3</sup> Gigabit Ethernet

RME and Change audit - Dec 10, 2004

SNMP OID for interface in status err-disabled - Dec 10, 2004

DFM Email Notify - Dec 10, 2004

CiscoWorks ANI Server ERROR - Dec 10, 2004

Optimal SNMP Traps and Syslogging - Dec 10, 2004

Virtual Private Networks: Network and Policy Management

IDS MC Config Deployment take a long time - Dec 8, 2004

VPN routing with PIXes vs routers - Dec 7, 2004

How to monitor edonkey, bt download in PIX - Dec 6, 2004

VPN Client 3.6x work and 4.x does not work - Dec 6, 2004

How to check the PIX Syslog messages - Dec 6, 2004

## **Related Information**

- Simple Network Management Protocol Technical Tips
- Technical Support Cisco Systems

Home	How to Buy	Login	Profile	Feedback	Site Map	Help

All contents are Copyright © 1992-2004 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

Updated: Dec 10, 2004 Document ID: 26010