

Release Notes for Cisco WBPN Wireless-N Bridge for Phone Adapters Firmware Version 1.0.2

September 2013

Contents

This document includes the following topics:

- [Resolved Issues in Release 1.0.2](#)
- [Known Issues in Release 1.0.2](#)
- [Related Information](#)

Resolved Issues in Release 1.0.2

Ref Number	Description
CSCuc06641	<p>Issue—When WBPN boots up with LAN setting DHCP, the vendor class identifier, option 60 for DHCP packet is incorrect.</p> <p>Resolution—Vendor class ID changed to Cisco WBPN.</p>

Release Notes

Ref Number	Description
CSCuc17489	<p>Issue—In a WPBN wireless setup by WPS with WRP400, there is failure in connection between WPBN and WRP400.</p> <p>Resolution—There is no WPS interoperability issue between WPBN and WRP400.</p>
CSCuc17509	<p>Issue—After factory reset of WPBN, when the WLAN LED is on, web login fails intermittently after changing username and password.</p> <p>Resolution—The problem does not occur anymore.</p>

Known Issues in Release 1.0.2

There are no known issues in this release.

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Small Business Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco WBPN	www.cisco.com/go/spabridge
Cisco SPA50X Phones	www.cisco.com/go/spa500phones
Cisco SPA30X Phones	www.cisco.com/go/300phones
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Release Notes

© 2013 Cisco Systems, Inc. All rights reserved.
78-21411-01