

End-of-Sale and End-of-Life Announcement for the Cisco Digital Media Manager versions 3.4 and 3.5

EOL5572

With the Cisco Digital Media Manager version 4.0 now available and orderable, Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco Digital Media Manager versions 3.4 and 3.5. The last day to order the Cisco Digital Media Manager versions 3.4 and 3.5 is June 25, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco Digital Media Manager versions 3.4 and 3.5. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to order the upgrade to version 4.0 of the Cisco Digital Media System application for the latest set of features, enhancements, and functionality. There is no cost to perform the upgrade from versions 3.4 and 3.5 to version 4.0.

Table 1. End-of-Life Milestones and Dates for the Cisco Digital Media Manager versions 3.4 and 3.5

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 26, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 25, 2007
Last Ship Date: App. SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 23, 2007
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 24, 2008
End of New Service Attachment Date: App. SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 24, 2008
End of Service Contract Renewal Date: App. SW		
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
DMS-DMM3.4-7835-H1	Digital Media Mgr Base V3.4 Perptl SW License with MCS-7835-H1	DMM4.0-7835-H1-K9	Digital Media Mgr Base V4.0 Perptl SW License for MCS-7835-H1
DMS-DMM3.4-VPE	Digital Media Mgr V3.4 Video Portal Enabler Perptl. SW License	DMM4.0-VPM4.0-K9	DMM V4.0 Video Portal Module 4.0 Perptl. SW License
DMS-DMM3.5-7835-H1	Digital Media Mgr. Base V3.5 Perptl. SW License for MCS-7835-H1	DMM4.0-7835-H1-K9	Digital Media Mgr Base V4.0 Perptl SW License for MCS-7835-H1
DMS-DMM3.5-VPE	Digital Media Mgr. V3.5 Video Portal Enabler Perptl. SW License	DMM4.0-VPM4.0-K9	DMM V4.0 Video Portal Module 4.0 Perptl. SW License
DMS-VP3.4-7825-H2	Cisco Video Portal V3.4 Perptl. SW License with MCS-7825-H2	VP4.0-7825-H2-K9	Cisco Video Portal V4.0 Perptl. SW License for MCS-7825-H2
DMS-VP3.4-7835-H1	Cisco Video Portal V3.4 Perptl. SW License with MCS-7835-H1	VP4.0-7835-H1-K9	Cisco Video Portal V4.0 Perptl. SW License for MCS-7835-H1
DMS-VP3.5-7825-H2	Cisco Video Portal V3.5 Perptl. SW License for MCS-7825-H2	VP4.0-7825-H2-K9	Cisco Video Portal V4.0 Perptl. SW License for MCS-7825-H2
DMS-VP3.5-7835-H1	Cisco Video Portal V3.5 Perptl. SW License for MCS-7835-H1	VP4.0-7835-H1-K9	Cisco Video Portal V4.0 Perptl. SW License for MCS-7835-H1
DMS-VPR3.4	Cisco Video Portal Reports V3.4 Perptl. SW License	VPR4.0-K9	Cisco Video Portal Reports V4.0 Perptl. SW License
DMS-VPR3.5	Cisco Video Portal Reports V3.5 Perptl. SW License	VPR4.0-K9	Cisco Video Portal Reports V4.0 Perptl. SW License

Product Migration Options

Customers are encouraged to migrate to Cisco Digital Media Manager 4.0. Information about this product can be found at: http://www.cisco.com/en/US/products/ps6681/index.html. There is no cost to perform the upgrade from versions 3.4 and 3.5 to version 4.0.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: http://www.cisco.com/go/tradein/. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

 $\underline{\text{http://www.cisco.com/web/ordering/ciscocapital/refurbished/index.html.}}$

For More Information

For more information about the Digital Media Manager 4.0, visit http://www.cisco.com/en/US/products/ps6681/index.html, contact your local account representative, or send an e-mail to DMS_EOS@cisco.com.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod end of life.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice.



Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 527-0883 Asia Pacific Headquarters Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7779 Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.: Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.: and Access Registrat, Aironet, BPX, Catalyst, CODA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco lOS, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherChannel, EtherFast, EtherChannel, EtherFast, EtherChannel, EtherFast, Ether Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, IQ Expertise, the iQ logo, IQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0701R)

Printed in USA C51-397118-00 03/07