Product End-of-Life Notice



Cisco public

# End-of-Sale and End-of-Life Announcement for the Cisco uBR10012 Universal Broadband Router Software License PIDs

# Contents

Overview	3
End-of-life milestones	3
Product part numbers	3
Product migration options	4
For more information	4

#### Overview

#### EOL12899 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco uBR10012 Universal Broadband Router Software License PIDs. The last day to order the affected product(s) is July 31, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

#### End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco uBR10012 Universal Broadband Router Software License PIDs

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	January 30, 2019
End-of-Sale Date License	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 31, 2019
Last Ship Date License	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 29, 2019

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description
L-3G60-RSTR-SWLIC=	3G6o PAK Container, Cable Access BU Approval Reqd to Order
L-MC20X20V-10DS	+10DS Upgrade License for UBR-MC20X20V
L-MC20X20V-15DS	+15DS Upgrade License for UBR-MC20X20V
L-MC20X20V-20DS	+20DS Upgrade License for UBR-MC20X20V
L-MC20X20V-5DS	+5DS Upgrade License for UBR-MC20X20V
L-MC20X20V-SWLIC=	Container for 20x20:+5,+15,+20 DS are options under this
L-MC <sub>3</sub> GX6 <sub>0</sub> V-DS	1 Count DS License For 3G6o
L-MC <sub>3</sub> GX6 <sub>0</sub> V-SWLIC=	PAK Container For 3G6o
L-MC <sub>3</sub> GX6 <sub>0</sub> V-US	1 Count US License For 3G6o

End-of-Sale Product Part Number	Product Description
L-PRE <sub>5</sub> -10G	1 count 10G license for PRE5
L-PRE <sub>5</sub> -SWLIC=	PAK Container For PRE <sub>5</sub>
L-RCON-LIC-3G6oDS=	1 Count Downstream Reconciliation License for 3G6o
L-RCON-LIC-3G6oUS=	1 Count Upstream Reconciliation License for 3G6o
L-SPA-RSTRC-SWLIC=	3G SPA PAK Container, Cable Access BU Approval Reqd to Order
L-SPA-UBR10-DS	1 Count DS License For SPA
L-SPA-UBR10-SWLIC=	PAK Container For 3G SPA
SWLIC-MC <sub>3</sub> GX6 <sub>0</sub> V-DS	1 DS license: Must configure with UBR-MC <sub>3</sub> GX6oV only
SWLIC-MC <sub>3</sub> GX6 <sub>0</sub> V-US	1 US license: Must configure with UBR-MC <sub>3</sub> GX6oV only
SWLIC-PRE <sub>5</sub> -10G	1 10G license, must configure with PRE5 only
SWLIC-SPA-UBR10-DS	1 DS license: Must configure with SPA-UBR10-DS-HD only

### Product migration options

There is no replacement available for the Cisco uBR10012 Universal Broadband Router Software License PIDs at this time.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html.

#### For more information

For more information about the Cisco End-of-Life Policy, go to: <a href="https://www.cisco.com/en/US/products/products\_end-of-life\_policy.html">https://www.cisco.com/en/US/products/products\_end-of-life\_policy.html</a>.

For more information about the Cisco Product Warranties, go to:

https://www.cisco.com/en/US/products/prod\_warranties\_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

https://www.cisco.com/cisco/support/notifications.html.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore **Europe Headquarters**Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at https://www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-741914-01 07/19